

NO VISIBLE ACM

FIELD DATA SHEET 1


Site Information:

Occupant:	Interviewee:
Address: <u>[REDACTED] MARRERO</u>	
Phone No.:	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>[REDACTED]</u>	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): <u>locked gate</u> ; <u>gate</u> ; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____

Comments: *No visible ACM; only concrete.*

Date/Time of Interview: 11/22/15

Access Granted (circle): yes; no N/A

Team Members: TC / LT

07-0875-510

991086

007000



TRACKING# 875

NO ACM

007001

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE:

9/15/98

SITE #:

875

ADDRESS:

[REDACTED]

1141120

ACM LOCATED BENEATH:

HOUSE
SHED

APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

CHUNKS
POWDER
SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

no ACM	

TEAM MEMBERS:

143/13

07-0875-540

007002

Tracking Number 876

No visible ACM

FIELD DATA SHEET 1


Site Information:

Occupant: <u>[REDACTED]</u>	Interviewee:
Address: <u>[REDACTED] Marrero 70072</u>	
Phone No.: <u>[REDACTED]</u>	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>same</u>	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): <u>Locked gate</u> ; gate; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



(b) (6)

Estimated Volume of ACM: _____

Comments: No visible ACM; owner had ACM but he poured concrete over it and built a new garageDate/Time of Interview: 11/22 1630Access Granted (circle): yes; no N/ATeam Members: TC/LT

07-0876-510

007003

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/15/98

ADDRESS: [REDACTED]

SITE #: 076

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	_____

TEAM MEMBERS:

KJ/TS

07-0876-540

007004

Tracking Number 877
No visible ACM

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee: <u>Donald Chapin</u>
Address: <u>[REDACTED] Manor</u>	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>same</u>	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): <u>locked gate</u> ; gate; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____

Comments: So [REDACTED] called in. Said ACM was in yard and sidewalk. TC/LT determined sidewalk is concrete however no one answered door so we couldn't check back yard. No visible ACM.

Date/Time of Interview: 11/22 16:35 12/2/96 Access Granted (circle): yes; no (N/A)

Team Members: TC/LT SN/ML **07-0877-510**

12/2/96
ACM is
bound in
concrete
(mlysn)
Told him will
not remove.
Gave PR #s
to call

007005

TRACKING# ^{CMA}~~723~~ (877) ^{CMA} 12/9/96

NO ACM

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE:

9-24-98

ADDRESS:

[REDACTED]

SITE #:

0877

MARRERO

ACM LOCATED BENEATH:

<input checked="" type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED

APPR. CRAWL SPACE HEIGHT:

12"


DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

0%

SKETCH OR COMMENTS:

CRAWL SPACE CLOSED

TEAM MEMBERS:

J.Y. & A.T.

07-0877-540

007007

Tracking Number 878*NO VISIBLE ACM*

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee:
Address: [REDACTED]	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: <i>SAME</i>	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; <u>gate</u> ; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____

Comments: *NO VISIBLE ACM; Owner has nice yard with flowers and a garden.*Date/Time of Interview: *11/22 1700*Access Granted (circle): yes; no *N/A*Team Members: *R/L*

07-0878-510

007008

TRACKING# 878

NO ACM

007009

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/24/98
SITE #: 878

ADDRESS: [REDACTED]
Manero

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	<u>slab</u>

TEAM MEMBERS:

RL/SS

07-0878-540

007010

FIELD DATA SHEET 1

11-23 sketch
 12/3/96 1 m in mailing address
 12/6/96

Site Information: 12/17/96 revisited place to reconfirm back portion of ACM per owner request/positive


Occupant: [REDACTED]	Interviewee: [REDACTED]
Address: 4 [REDACTED] St., Gretna	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED] [REDACTED] 11221 [REDACTED] [REDACTED] [REDACTED] 10040	

Site Description: Rore Ehret Jr 830 St. Philip St. Apt. C N.O. 70116

- 1) Description of property (circle): single home; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
- 2) Problems accessing yards (circle): locked gate; gate; dogs; other _____ resolution: _____
- 3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____
 Note location on site sketch.
- 4) Is any underground ACM present? (circle): yes; no; don't know
 If yes, note on site sketch. How deep? _____

Site Sketch:

Q = ACM



(b) (6)(b) (6)

Estimated Volume of ACM: 110 ft²

Comments: ACM observed along the north edge of the shed.
 12/16 Owner called, he wants to recheck back portion of house AR before he signs access AR
 Backfill: CONCRETE 12/17/96 - [REDACTED] identified ACM in back yard
 called [REDACTED] to confirm

Date/Time of Interview: 10 AR 12/16 1105 Access Granted (circle): yes; no
 Team Members: AR - phone 05-0879-510

12/18/96
 will mail
 to Dallas
 A.R.

007011

#879

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]
Property's Address: [REDACTED]
State/Zip: 70053 Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
★ Replace with concrete
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.


This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

12-17-76
DATE


[REDACTED]
SIGNATURE

05-0879-520

007012



NOTES:



RESTORATION: A: Soil / sod

B: lime stone

C: concrete (8' x 20')

ARRIVAL:

DEPARTURE:

RESTORATION APPROVED BY:

05-0879-530

TEAM: IT / Q31C

007013

13, 19, 97

To IT 07/21/97

DATE: 7, 16, 97

WESTBANK ACM REMOVAL PROJECT SAMPLE ANALYSIS CONFIRMATION USEPA START TEAM

FYI:

SITE# 879

ADDRESS: [REDACTED]
Gretna



THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON No analytical as of 08.05-97

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ✓ ✓

B. FURTHER ACTION NECESSARY:



AUTHORIZED EPA/START REPRESENTATIVE 007014 Alma Rullera

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
Indianapolis, Indiana 46250
Phone (317) 570-5892 Fax (317) 570-5894

EMSL

Attn.: Alma Rillera
Ecology & Environmental
11550 New Castle Avenue
Baton Rouge, LA 70816

Thursday, August 07, 1997

Ref Number: IN97727

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: 020801 RAGI WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
WBS879G01		Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			40% Quartz 60% Other
WBS879G02		Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			40% Quartz 60% Other
WBS345G01		Brown Non-Fibrous Homogeneous	Crushed	2% Chrysotile < 1% Crocidolite			40% Quartz 58% Other
WBS345G02		Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			40% Quartz 60% Other
WBS345G03		Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			40% Quartz 60% Other
WBS616G01		Brown Non-Fibrous Homogeneous	Crushed	None Detected			80% Quartz 20% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "% of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

Note: Sample WBS1216G01 could not be homogenized due to the nature of the sample submitted

Jane Wasilewski
Analyst


Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. This report may only be reproduced in full with written approval by EMSL. The above test report relates only to the sample analyzed. EMSL is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200188-0).

05-0879-570

007015

By PM Date 8-6-97 Subject RESTORATION SITE # 879 Sheet No. _____ of _____
Chkd. By _____ Date _____ Proj. No. _____



05-0879-590

007016

WESTBANK ASBESTOS ABATEMENT NEW ORLEANS, LOUISIANA

RESTORATION FORM

SITE # 879

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)					(b) (4) (b) (4)		
Sod Installation (sq.yds.)					(b) (4) (b) (4)		
3" Concrete Installation (sq. yds.)					(b) (4)		
1" Concrete Installation (sq. yds.)							
Sand Installation (sq.yds.)					(b) (4) (b) (4)		
Lower Lift Sand							
Rock, Brown (cu.yds.)							(b) (4) (b) (4)
Rock, Gray (cu.yds.)					(b) (4) (b) (4) (b) (4)		
Sand (cu.yds.)					(b) (4) (b) (4)		
Concrete (cu.yds.)					(b) (4) (b) (4)		
Plastic Edging (ft.)					(b) (4) (b) (4)		
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

05-0879-590

IT REPRESENTATIVE SIGNATURE _____

SUB 1 SIGNATURE _____

SUB 2 SIGNATURE _____

007017

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE:

8/27/98

ADDRESS

[REDACTED]
[REDACTED]
[REDACTED]

SITE #:

879

ACM LOCATED BENEATH:

☒ HOUSE
☐ SHED

APPR. CRAWL SPACE HEIGHT:

12"-18"


DESCRIPTION OF ACM:

☒ CHUNKS
☐ POWDER
☐ SLAB

PERCENT OF AREA (ACM)

1-2%

SKETCH OR COMMENTS:

	<u>Couldn't see most of under house</u>
	<u>too much debris in way.</u>

(b) (6)

(b) (6)

05-0879-540

TEAM MEMBERS:

007018

~~████████████████████~~
New Orleans, La. 70116



John Martin
US EPA Region 6 (6SF-2)
1442 Ross Ave.
Dallas, Texas 75202

75202/2712



007019

FIELD DATA SHEET 1

Site Information:


Occupant: <u>[REDACTED]</u> IS	Interviewee: <u>[REDACTED]</u>
Address: <u>[REDACTED]</u>	
Phone No.: <u>[REDACTED]</u>	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>same as above</u>	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other <u>NONE</u> resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; <u>no</u> ; don't know If yes, note on site sketch. How deep? _____

Site Sketch:

① = ACM



Estimated Volume of ACM: _____

Comments: owner will remove shed prior to removal activities so ACM can be excavated from shed floor.Backfill: discuss w/ [REDACTED] prior to replacement. He may want concrete and limestoneDate/Time of Interview: 11/22 / 0845Access Granted (circle): yes; noTeam Members: JM/AR

05-0880-510

880

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]
Property's Address: [REDACTED]
State/Zip: LA Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

11/23/97
DATE


[REDACTED]
SIGNATURE

05-0880-520

007021

TRACKING # 880

SITE SKETCH

ADDRESS: [REDACTED]UPDATED: 1 1

NOTES:



#	COVER	THICKNESS
1	+6" soil/grass	—

RESTORATION: A: CONCRETE (11'x70' - DRIVEWAY
B: 11'x24' - SHED FOUNDATION)
C:

05-0880-530

ARRIVAL: 1455

DEPARTURE: 1530

RESTORATION APPROVED BY: [REDACTED]

Via Phone @ 1028

DATE: 7/24/97

TEAM: * WJW/50/177M DATE: 7/24/97
7/9 007022

To IT 7/24/97 JRD

WESTBANK ACM REMOVAL PROJECT SAMPLE ANALYSIS CONFIRMATION USEPA START TEAM

FYI:

SITE# 880

ADDRESS: [REDACTED]
Gretna, LA



THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON _____

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ☒ ☒

B. FURTHER ACTION NECESSARY: ☐ ☐



007023

05-0880-560

AUTHORIZED EPA/START REPRESENTATIVE

[Signature]

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
 Indianapolis, Indiana 46250
 Phone (317) 570-5892 Fax (317) 570-5894



Attn.: Jody Shires
 Ecology & Environmental
 11550 New Castle Avenue
 Baton Rouge, LA 70816

Wednesday, August 27, 1997

Ref Number: IN97908

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: 020801 RAGI WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
WBS880G01	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
WBS880G02	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "% of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 108-1 Method

Jane Wasilewski
 Analyst

Approved
 Signatory

05-0880-570

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative results are not guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the PLM analysis. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim compliance with any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one laboratory responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk 5200165-0).

07024




INTERNATIONAL
TECHNOLOGY
CORPORATION



By PM Date 8-25-97 Subject RESTORATION SITE # 280 Sheet No. _____ of _____

Chkd. By _____ Date _____ Proj. No. _____



05-0880-590

007025

WESTBANK ASBESTOS ABATEMENT NEW ORLEANS, LOUISIANA

RESTORATION FORM

SITE # 880

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)							
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)					(b) (4)		
Plastic Edging (ft.)					(b) (4)		
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

05-0880-590

IT REPRESENTATIVE SIGNATURE _____

SUB 1 SIGNATURE _____

SUB 2 SIGNATURE _____

007026




By PM Date 8-25-97 Subject RESTORATION SITE # 880 Sheet No. of

Chkd. By Date Proj. No.

REVISED 9-16-97

AS PER USACE



05-0880-590

007027

WESTBANK ASBESTOS ABATEMENT NEW ORLEANS, LOUISIANA

RESTORATION FORM

SITE # 880

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)							
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)					(b) (4)		
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

05-0880-590

IT REPRESENTATIVE SIGNATURE

SUB 1 SIGNATURE

SUB 2 SIGNATURE

007028

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/1/98
SITE #: 580

ADDRESS: [REDACTED]

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	_____

05-0880-540

TEAM MEMBERS: DA/ML

007029

FIELD DATA SHEET 1

Site Information:


Occupant: <u>[REDACTED]</u>	Interviewer: <u>[REDACTED]</u>
Address: <u>[REDACTED]</u>	
Phone No.: <u>[REDACTED]</u>	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>same as above</u>	

Site Description:

1) Description of property (circle): single home; <u>duplex</u> ; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other <u>storm drain</u> Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:

① = visible ACM

Estimated ^{area} Volume of ACM: 450 ft²Comments: Backfill: limestone w/ edgingDate/Time of Interview: 11-22 / 0915Access Granted (circle): yes noTeam Members: JM / AR

05-0881-510

881

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]
Property's Address: [REDACTED]
State/Zip: LA Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

11-22-96
DATE

[REDACTED]
SIGNATURE

05-0881-520


007031

TRACKING # 881

SITE SKETCH

ADDRESS: [REDACTED]

UPDATED: 1/1



NOTES:

N (NTS)

RESTORATION: A: ~~SOIL~~ Limestone

B:

C:

ARRIVAL: 1330

DEPARTURE: 1440

RESTORATION APPROVED BY: F [REDACTED]

TEAM:

*mw/js/dm jw
7/2

DATE:

7/8/97

© 2041

DATE: 7/8/97

TO IT 7/9/97

COVER THICKNESS

1 +3" soil/grass ALM

2 +6" soil/grass

05-0881-530

WESTBANK ACM REMOVAL PROJECT
SAMPLE ANALYSIS CONFIRMATION
USEPA START TEAM

FYI:

SITE# 881

ADDRESS: 821 M. [REDACTED]
Gretna, LA


THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON No analytical as of 08.06.97

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ☒

B. FURTHER ACTION NECESSARY: ☐



007033

AUTHORIZED EPA/START REPRESENTATIVE Alma Riller

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
Indianapolis, Indiana 46250
Phone (317) 570-5892 Fax (317) 570-5894

EMSL

Attn.: Alma Rillera
Ecology & Environmental
11550 New Castle Avenue
Baton Rouge, LA 70816

Monday, August 11, 1997

Ref Number: IN97752

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: 020601 RAG1 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	<u>ASBESTOS</u>		<u>NONASBESTOS</u>	
				%	TYPE	% FIBROUS	% NONFIBROUS
WBS367/368G01	5013/5015 OAK	Brown Non-Fibrous Homogeneous	Crushed		None Detected		20% Quartz 80% Other
WBS367/368G02	5013/5015 OAK	Brown Non-Fibrous Homogeneous	Crushed		< 1% Chrysotile		20% Quartz 80% Other
WBS367/368G03	5013/5015 OAK	Brown Non-Fibrous Homogeneous	Crushed		None Detected		20% Quartz 80% Other
WBS1005/1412 G01	WE	Brown Non-Fibrous Homogeneous	Crushed		None Detected		80% Quartz 20% Other
WBS881G01	CR	Brown Non-Fibrous Homogeneous	Crushed		< 1% Chrysotile < 1% Crocidolite		70% Quartz 30% Other
WBS138G01	WE	Brown Non-Fibrous Homogeneous	Crushed		< 1% Chrysotile < 1% Crocidolite		70% Quartz 30% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

Jane Wasilewski
Analyst

Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus neg be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim pro NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered sam. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200186-0)

05-0881-570


007034



INTERNATIONAL
TECHNOLOGY
CORPORATION



By PM Date 8-7-97 Subject RESTORATION SITE # 88 Sheet No. of
Chkd. By Date Proj. No.



05-0881-590

007035

SITE # 881

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)					(b) (4)		
Sod Installation (sq.yds.)							
6" Concrete Installation (sq. yds.)							
4" Concrete Installation (sq. yds.)							
Sand Installation (sq.yds.)							
Lower Lift Sand							
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)							
Sand (cu.yds.)							
Concrete (cu.yds.)							
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoll (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

05-0881-590

IT REPRESENTATIVE SIGNATURE

007036

SUB 1 SIGNATURE

SUB 2 SIGNATURE

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 8/31/98
SITE #: 881

ADDRESS: [REDACTED]

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED

APPR. CRAWL SPACE HEIGHT:

18'

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

<p>NO ACM Doreen Allison</p>	_____

TEAM MEMBERS:

DA/ML

05-0881-540

007037

FIELD DATA SHEET 1


Site Information:

Occupant: <u>[REDACTED]</u>	Interviewee: _____
Address: <u>[REDACTED]</u>	
Phone No.: <u>[REDACTED]</u>	
Owner Name, Address, and Phone No. if Different Than Occupant: _____	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____

Comments:

No visible ACM
11-22 No one home, JM/AR

Date/Time of Interview:

Access Granted (circle): yes; no

Team Members:

05-0882-510

007038

TRACKING# ^{CMS}~~795~~ 882

NO ACM

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 8/27/98
SITE #: 888

ADDRESS: [REDACTED]
Groynes

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED

APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

<div>No ACM</div>	_____

TEAM MEMBERS: MTL/pLL

05-0882-540

007040

FIELD DATA SHEET 1


Site Information:

Occupant: <u>[REDACTED]</u>	Interviewee: <u>Rita</u>
Address: <u>[REDACTED]</u>	
Phone No.: <u>[REDACTED]</u>	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>as above</u>	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; <u>dogs</u> ; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): <u>yes</u> ; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated ^{area} Volume of ACM: 21 ft² visible

Comments:

Backfill: crushed limestone

Date/Time of Interview: 11/22 - 14:12

Access Granted (circle): yes; no

Team Members: JM/AR

08-0883-510

007041

884 ml
883

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: _____
Property's Address: _____
State/Zip: LA Phone Number(s): 313 883-520

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

11-22-96
DATE

[Signature]
SIGNATURE

08-0883-520


007042

TRACKING # 883


SITE SKETCH

ADDRESS: 22711 11th Pl Terry

UPDATED: 11



NOTES:



RESTORATION: A: Limestone (10' WIDE CENTERED
B: SOD/SOD 3" SOIL REMAINDER
C:

ARRIVAL: 1000
DEPARTURE: 1030

TEAM: RL/TT

RESTORATION APPROVED BY: tw 7/29/97 Via Phone @ 1050 DATE: 7/30/97

DATE: 7/22/97 * TO IT 7/30/97 gww
007043

COVER	THICKNESS
1. Soil/SOD 6"	
2. Soil/SOD 3"	3" ACM
3. Gravel 6"	
4.	4" SACM

08-0883-530

WESTBANK ACM REMOVAL PROJECT SAMPLE ANALYSIS CONFIRMATION USEPA START TEAM

FYI:

SITE# 883

ADDRESS: [REDACTED]
Terrytown, La.


THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON No analytical as of 10-6-97.

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ✓ ✓ ✓ — — — — —

B. FURTHER ACTION NECESSARY: — — — — — — — —



08-0883-560

AUTHORIZED EPA/START REPRESENTATIVE [Signature]

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
Indianapolis, Indiana 46250
Phone (317) 570-5892 Fax (317) 570-5894

EMSL

Attn: Maggie Lin
Ecology & Environment
11550 New Castle Avenue
Baton Rouge, LA 70816

Thursday, October 09, 1997

Ref Number: IN971316

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: 020601 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
WBS1440G01	██████████ MARRERO	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			80% Quartz 20% Other
WBS1440G02	██████████ MARRERO	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			80% Quartz 20% Other
WBS1187G01	██████████ AVE X, MA	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			80% Quartz 20% Other
WBS1437G01	██████████ AVE, MA	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile			80% Quartz 20% Other
WBS1437G02	██████████ AVE, MA	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			80% Quartz 20% Other
WBS883G01	██████████ TERRYTOWN	Brown Non-Fibrous Homogeneous	Crushed	1% Chrysotile 1% Crocidolite			78% Quartz 20% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "8 of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

Margaret S. Phillips

Margaret Phillips
Analyst

Entered
10/9/97
HRS

Robert L. Harding

Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus neg be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim pre NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least on Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered sam. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200188-0)

08-0883-570

007045

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
Indianapolis, Indiana 46250
Phone (317) 570-5892 Fax (317) 570-5894

EMSL

Attn.: Maggie Lin
Ecology & Environment
11550 New Castle Avenue
Baton Rouge, LA 70816

Thursday, October 09, 1997

Ref Number: IN971316

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 800/R-93/116 Method*

Project: 020601 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	<u>ASBESTOS</u>		<u>NONASBESTOS</u>	
				%	TYPE	%	FIBROUS % NONFIBROUS
WBS883G02	[REDACTED] TERRYTOWN	Brown Non-Fibrous Homogeneous	Crushed	None Detected			80% Quartz 20% Other
WBS883G03	[REDACTED] TERRYTOWN	Brown Non-Fibrous Homogeneous	Crushed	1%	Chrysotile		78% Quartz
				1%	Crocidolite		20% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

Margaret J. Phillips

Margaret Phillips
Analyst


Entered
10/9/97
gls

Approved
Signatory

08-0883-570

Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negat be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the its may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim prod NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200188-0).

007046



007047

WESTBANK ASBESTOS ABATEMENT

NEW ORLEANS, LOUISIANA

RESTORATION FORM

SITE # 883

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)					(b) (4)		
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)					(b) (4)		
Plastic Edging (ft.)					(b) (4)		
Walkway Rock Inst. (sq.yds.)					(b) (4)		
Topsoil (cu.yds.)					(b) (4)		
EXTRA							

Site Sketch on Back of Page

COMMENTS:

08-0883-590

IT REPRESENTATIVE SIGNATURE

SUB 1 SIGNATURE

SUB 2 SIGNATURE

007048

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/22/98
SITE #: 0883

ADDRESS: [REDACTED]
Terrytown

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

 <p>no ACM present</p>	_____

TEAM MEMBERS:

JSB

08-0883-540

007049


FIELD DATA SHEET 1

Site Information:

Occupant: [REDACTED]	Interviewee: Cynthia
Address: [REDACTED] SM Jerrytown	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: same as above	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other
2) Problems accessing yards (circle): locked gate; gate; <u>dogs</u> ; other <u>contact owner prior</u> resolution: <u>to removal as dogs can be put up.</u>
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; <u>septic tank</u> ; other <u>possible gas line in back yard.</u> Note location on site sketch.
4) Is any underground ACM present? (circle): yes; <u>no</u> ; don't know If yes, note on site sketch. How deep?



(b) (6)

Estimated Volume of ACM: _____	
Comments: Back fill: soil/sod in backyard for certain. limestone (tentatively) in front yard. discuss with owner first.	
Date/Time of Interview: 11-22/ 15:58	Access Granted (circle): <u>yes</u> ; no
Team Members: SM/AR	

use gate on south side of house. ask owner for location of septic tank in back yard.

884

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]

Property's Address: [REDACTED]

State/Zip: LA

Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

11-22-96

DATE

[REDACTED SIGNATURE]

SIGNATURE

08-0884-520


007051

884

SITE SKETCH

050-111-1 T

UPDATED: 1/1



(b) (6)

NOTES:

N (NTS)



RESTORATION:

A: CONCRETE
B: SODA SOIL
C:

ARRIVAL: 1430

DEPARTURE: 1507

RESTORATION APPROVED BY:

DATE: 7/29/97

TEAM:

RESTO
BB/DM/JD

DATE: 7-16-97

007052

⊗ T₀ IT 7/30/97

922

#	COVER	THICKNESS
1	Soil/Grass	No ACM
2	1"-2" Soil/Grass	covered ACM
3	2"-3" Soil/Grass	covered ACM

Chris Semore

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
 Indianapolis, Indiana 46250
 Phone (317) 570-5892 Fax (317) 570-5894



Attn.: Chris Sansone
 Ecology & Environment
 11550 New Castle Avenue
 Baton Rouge, LA 70816

Friday, October 10, 1997

Ref Number: IN971328

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: 020801 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
WBS884G01	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	1% Chrysotile 1% Crocidolite			78% Quartz 20% Other
WBS884G02	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	1% Chrysotile 1% Crocidolite			78% Quartz 20% Other
WBS884G03	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	1% Chrysotile 1% Crocidolite			78% Quartz 20% Other
WBS1358G01	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	1% Chrysotile 1% Crocidolite			78% Quartz 20% Other
WBS945G01	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			80% Quartz 20% Other
WBS945G02	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	1% Chrysotile 1% Crocidolite			78% Quartz 20% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

Margaret S. Phillips
 Margaret Phillips
 Analyst

Entered
 10/10/97
 BRD

[Signature]
 Approved
 Signatory


08-0884-570

Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negs be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the i may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim pro NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200186-0)

007054



By PM Date 10-8-97 Subject RESTORATION SITE # 884 Sheet No. _____ of _____
Chkd. By _____ Date _____ Proj. No. _____



08-0884-590

007055

WESTBANK ASBESTOS ABATEMENT NEW ORLEANS, LOUISIANA

RESTORATION FORM

SITE # 884

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)							
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)					(b) (4)		
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

08-0884-590

IT REPRESENTATIVE SIGNATURE

SUB 1 SIGNATURE

SUB 2 SIGNATURE

007056

WESTBANK ASBESTOS ABATEMENT NEW ORLEANS, LOUISIANA

RESTORATION FORM

SITE # 884

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)							
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)					(b) (4)		
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

08-0884-590

IT REPRESENTATIVE SIGNATURE _____

SUB 1 SIGNATURE _____

007058

SUB 2 SIGNATURE _____

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/22/98

SITE #: 0884

ADDRESS: [REDACTED]
Perrytown

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

 <p>no ACM present</p>	_____

TEAM MEMBERS:

JS & EW

08-0884-540

607059

Tracking Number 885
No visible ACM

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee: <u>Phillip</u>
Address: [REDACTED]	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>same as above</u>	

Site Description:

1) Description of property (circle): single home; duplex; business; school; daycare; church; vacant house; vacant lot; other <u>NA</u>
2) Problems accessing yards (circle): locked gate; gate; dogs; other <u>NA</u> resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other <u>NA</u> Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____

Comments: No visible ACM. Owner suspected ACM could be mixed in with driveway concrete. Our field assessment did not indicate typical ACM material. The concrete paving was "soft", but in good condition. (over)

Date/Time of Interview: _____

Access Granted (circle): yes; no

Team Members: _____

05-0885-510

007060

TRACKING# ^{CMA}~~857~~ 885

NO ACM

~~007003~~
007063

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 8/28/98
SITE #: 885

ADDRESS: [REDACTED]
Cretina

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	_____

TEAM MEMBERS:

MTL / PLL

05-0885-540

007064

FIELD DATA SHEET 1

Site Information:

Occupant: [REDACTED]	Interviewee: [REDACTED]
Address: [REDACTED] WESTWEGO, LA 70094	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED]	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other <u>NONE</u> resolution: _____
3) Underground utilities installed by owner? (circle): no; <u>water</u> ; gas; electric; cable TV; septic tank; other _____ Note location on site sketch. <u>owner says it is "deep" but doesn't know depth and it runs "somewhere" from house to shed.</u>
4) Is any underground ACM present? (circle): <u>yes</u> ; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:

(b) (6)

Estimated Volume of ACM: <u>160 ft³</u>	
Comments: <u>backfill: grass</u>	
Date/Time of Interview: <u>11/23/96 0800</u>	Access Granted (circle): <u>yes</u> ; no
Team Members: <u>LT/TC</u>	09-0886-510

886

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]
Property's Address: [REDACTED]
State/Zip: 78094 Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

June 28-1997
DATE

[REDACTED]
SIGNATURE

09-0886-520


007066

TRACKING # 886

SITE SKETCH

ADDRESS: [REDACTED]

UPDATED: 1/1



NOTES:

N (NTS)



RESTORATION:

A: ^{tw} sand/gravel

B:

C:

ARRIVAL: 1330

DEPARTURE: 1425

TEAM:

BB DM JD

RESTORATION APPROVED BY: [REDACTED]

DATE:

7/15/97

(phone)

DATE: 8/7/97

2017 7/7/97

mm

09-0886-530

(b) (6)

#	COVER	THICKNESS
1	2-3" soil/grass	ACM
2	3-4" " "	ACM
3	6" soil/grass	

WESTBANK ACM REMOVAL PROJECT
SAMPLE ANALYSIS CONFIRMATION
USEPA START TEAM

FYI:

SITE# 886

ADDRESS: Westwego, LA


THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON _____

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ☒

B. FURTHER ACTION NECESSARY: ☐



AUTHORIZED EPA/START REPRESENTATIVE

007068

09-0886-560

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
Indianapolis, Indiana 46250
Phone (317) 570-5892 Fax (317) 570-5894

Attn.: Alma Rillera
Ecology & Environmental
11550 New Castle Avenue
Baton Rouge, LA 70816

Tuesday, September 09, 1997

Ref Number: IN971031

**POLARIZED LIGHT MICROSCOPY (PLM)**

Performed by EPA 600/R-93/116 Method*

Project: 020601 RAGI WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
WBS886G01		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
WBS1129G02		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile < 1% Crocidolite		80% Quartz 20% Other
WBS991G01	ST. GR	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		40% Quartz 60% Other
WBS991G02	ST. GR	Brown Non-Fibrous Homogeneous	Crushed	2%	Chrysotile < 1% Crocidolite		40% Quartz 58% Other
WBS1467G01		Brown Non-Fibrous Homogeneous	Crushed		None Detected		85% Quartz 15% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

Jane Wasilewski
Analyst

Approved
Signatory

Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative results are not guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the fiber analysis. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product liability or any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200188-0).

09-0886-570

007069




INTERNATIONAL
TECHNOLOGY
CORPORATION



By DM Date 9-8-97 Subject RESTORATION SITE # 886 Sheet No. _____ of _____

Chkd. By _____ Date _____ Proj. No. _____

NOTE:
INSTALL & COMPACT SAND
IN "SAND ONLY" AREA TO
4" BELOW FINAL GRADE.
OWNER WILL POUR HIS
OWN CONCRETE.



09-0886-590

007070

SITE # 886

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)							
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)							
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

09-0886-590

IT REPRESENTATIVE SIGNATURE _____

SUB 1 SIGNATURE _____

SUB 2 SIGNATURE _____

007071

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/23/98

ADDRESS: [REDACTED]
09-0886-540

SITE #: 0886

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	_____

TEAM MEMBERS:

RL/TS

09-0886-540

007072

Tracking Number 887

No visible ACM

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee: [REDACTED]
Address: [REDACTED]	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: Rev. Jerry Henry, Sr.	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; <u>gate</u> ; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



(b) (6)

Estimated Volume of ACM: _____

Comments:

No VISIBLE ACM

Date/Time of Interview: 12/2/96 1545

Access Granted (circle): yes; no (P/A)

Team Members: SN/ML

07-0887-510

007073

TRACKING# ^{CMS}~~859~~ 887

NO ACM

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE:

9/25/98

ADDRESS:

[REDACTED]

SITE #:

887

Marrero

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	_____

TEAM MEMBERS:

GD/JS

07-0887-540

07075

Tracking Number 888
No VISIBLE ACM

FIELD DATA SHEET 1


Site Information:

Occupant: <u>[REDACTED]</u>	Interviewee: <u>[REDACTED]</u>
Address: <u>[REDACTED] Murrell 70072</u>	
Phone No.: <u>[REDACTED]</u>	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>[REDACTED]</u>	

Site Description:

1) Description of property (circle): <u>single home;</u> duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; <u>gate;</u> dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): <u>no;</u> water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; <u>no;</u> don't know If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____

Comments:

No VISIBLE ACM

Date/Time of Interview: 11/23/96 0915

Access Granted (circle): yes; no (N/A)

Team Members: LT/TC

07-0888-510

07076

TRACKING# 888

NO ACM

WAS IN PROBLEM FILE

NO ACM
AT THIS
SITE

- So by [REDACTED] and
see if there is ACM on
property

- windshield survey
10/12 0840 - None visible from curbside.
Possibly on sides of house or back yard.
(Doubtful) Cockhill/Johnson
[REDACTED]

W

(b) (6)

Phone #

Tracking # or
property address
unknown
10/2/96
[Signature]

007078

07-0888-600

September 24, 1996

To Whom It May Concern:

The August 30, 1996, "Westbank Asbestos Site Update" states that "excavated areas" will be restored with "similar materials". Please state the replacement materials and restoration means to restore shrubbery, lawns, etc.

The same publication states that each cleanup site be "monitored to assure protection of public health." Please state if this means that quantitative air sampling and analyses will be performed while the remediation work is in progress. If air sampling and analyzes is to be performed, please state the quantities of samples to be obtained per work day or other work period, the analyses method to be employed, and any Action Levels (based on airborne fiber concentrations) used to control the work. Will these air monitoring results be furnished to me?

[REDACTED]

Please contact [REDACTED]
[REDACTED]
Marrero, La. 70072

RE: Asbestos CONTAINING MATERIAL IN the Westbank
AREA New Orleans: EPA Superfund RESPONSE

2

07-0888-600

No Accrual Record Yet
10/01/96

007079

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/9/98

ADDRESS: [REDACTED]

SITE #: 888

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED

APPR. CRAWL SPACE HEIGHT:


NA

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

TEAM MEMBERS:

DA/KJ

07-0888-540

007080

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee: [REDACTED]
Address: [REDACTED]	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>same</u>	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; <u>gate</u> ; <u>dogs</u> ; other <u>dogs pinned up</u> resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; <u>don't know</u> If yes, note on site sketch. How deep? _____

Site Sketch:

NE
NTSEstimated Volume of ACM: 10' x 10' = 100 ft²Comments: crushed limestone per Dianne 12/3/96 m&m

Date/Time of Interview: <u>12/02/96</u> <u>1515h</u>	Access Granted (circle): <u>yes</u> ; no <u>12/2/96</u>
Team Members: <u>Tm</u>	07-0889-510

889

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]

Property's Address: [REDACTED]

State/Zip: 70072

Phone Number(s): [REDACTED]

Beeper

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

12-2-96

DATE

[REDACTED]

SIGNATURE


07-0889-520

007082

4/7/97 16 30
16 45

TEAM - CC, MH, ML

surrounded by concrete 12x10
then grass balance



~~ZZ~~

Restoration:

① Concrete

① SACM cement like - 4"

② grass/sod no ACM

Dianne Dalney

4/19/97

07-0889-530

To IT 4/21/97

007083

**WESTBANK ASBESTOS ABATEMENT
NEW ORLEANS, LOUISIANA**

RESTORATION FORM

SITE # 889

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)							
Sod Installation (sq.yds.)							
6" Concrete Installation (sq. yds.)							
4" Concrete Installation (sq. yds.)							
Sand Installation (sq.yds.)							
Lower Lift Sand							
Rock, Brown (cu.yds.)							
Rock, Gray (cu.yds.)							
Sand (cu.yds.)							
Concrete (cu.yds.)							
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: NO RESTORATION NEEDED ON THIS SITE
AS PER USAGE @ 0730 MEETING ON 5-19-97
NO SAMPLES COLLECTED - AREA AFTER EXCAVATION WAS ALL
CONCRETE - RPD 7/25/97 **07-0889-590**

IT REPRESENTATIVE SIGNATURE _____

SUB 1 SIGNATURE _____

SUB 2 SIGNATURE 007084

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/23/98

SITE #: 889

ADDRESS: [REDACTED]
marrero

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	<u>soil</u>

TEAM MEMBERS: RL/JS

07-0889-540

007085

Tracking Number 890NO VISIBLE
ACM

FIELD DATA SHEET 1


Site Information:

Occupant:	Interviewee:
Address: [REDACTED]	70072
Phone No. [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>Charles Dwyer</u>	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; <u>gate</u> ; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; <u>no</u> ; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____

Comments:

NO VISIBLE ACM

Date/Time of Interview: 11/23/96 0945Access Granted (circle): yes; no (N/A)Team Members: LT/TL (Nobody home)

07-0890-510

7086

TRACKING# 890

NO ACM

007087

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/10/98
SITE #: 890

ADDRESS [REDACTED]

ACM LOCATED BENEATH:

☐ HOUSE
☐ SHED

APPR. CRAWL SPACE HEIGHT:


12"

DESCRIPTION OF ACM:

☐ CHUNKS
☐ POWDER
☐ SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

TEAM MEMBERS:

DA/KJ

07-0890-540

007088

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee: <u>Thelma</u>
Address: [REDACTED], <u>Manero, CA 70072</u>	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>Same</u>	

Site Description:

1) Description of property (circle): <u>single home; duplex</u> ; business; school; daycare; church; vacant house; vacant lot; other <u>former duplex - appears to be one structure</u>
2) Problems accessing yards (circle): locked gate; <u>gate</u> ; <u>dogs</u> ; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____

Comments: Sketch on 11/23/96 - TMN. Need site visit for area & access
Doc/50dDate/Time of Interview: 11/29/96 3:15pAccess Granted (circle): yes noTeam Members: TMN/IT Tel Personna

07-0891-510

007089

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: _____
Property's Address: _____
State/Zip: LA Phone Number(s): _____

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

11-27-96
DATE

[Signature]
SIGNATURE

07-0891-520

007090

Site 891

Site sketch

4445

4445

4/7/97


1650

1710

TEAM: CC, MH, ML

note need field data
sheet for 448

No. 5505
Engineer's Computation Pad



Restoration:

Area ① - soil/sod - appraised by T [redacted] at 1352 hrs
on 4/10/97 - Tm

07-0891-530

ML

007091

WESTBANK ACM REMOVAL PROJECT
SAMPLE ANALYSIS CONFIRMATION
USEPA START TEAM

FYI:

SITE# 891

ADDRESS: [REDACTED]
Marrero


THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON _____.

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ☒ 
B. FURTHER ACTION NECESSARY: ☐

• visible ACM highlighted below: (1) and (2)
• drilled 05-07-97



AUTHORIZED EPA/START REPRESENTATIVE

07-0891-560
March Kooms

Westwood, NJ 800-804-4900	Flack-Krawitz, NJ 908-981-0600	Carle Place, NY 516-987-7251	Madison, NY 212-280-2852	Seattle, WA 206-226-9007	Ann Arbor, MI 313-966-0610	San Mateo, CA 415-870-6401	Baytown, GA 404-333-0000	Greensboro, NC 910-297-1487	Houston, TX 713-696-3635
------------------------------	-----------------------------------	---------------------------------	-----------------------------	-----------------------------	-------------------------------	-------------------------------	-----------------------------	--------------------------------	-----------------------------

EMSL

Ecology & Environment, Inc.
11550 Newcastle Ave. #250
Baton Rouge, LA 70816

Friday, May 09, 1997

Ref Number: TX971661

POLARIZED LIGHT MICROSCOPY (PLM)

Project: 020601RAG1 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
TSW1	HEBERT, MA	Grey Fibrous Homogeneous	Teased	60%	Chrysotile		38% Other
				2%	Crocidolite		
WBS891G01	EISEMAN, MA	Tan Non-Fibrous Homogeneous	Teased	2%	Chrysotile		98% Other
				< 1%	Crocidolite		
WBS334G02	SADDLER, MA	Tan Non-Fibrous Homogeneous	Teased	2%	Chrysotile		98% Other
				< 1%	Crocidolite		
WBS418G01		Tan Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other
WBS418G02		Tan Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other
WBS418G03		Tan Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

Carlos D. Salinas
Analyst

Approved
Signatory


Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. This report is not guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the item only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature. EMSL is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

07-0891-570

007093



By PM Date 5-7-97 Subject RESTORATION SITE # 891 Sheet No. of
Chkd. By Date Proj. No.



07-0891-590

007094

**WESTBANK ASBESTOS ABATEMENT
NEW ORLEANS, LOUISIANA**

RESTORATION FORM

SITE # 891

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)							
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)							
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

07-0891-590

IT REPRESENTATIVE SIGNATURE _____

SUB 1 SIGNATURE _____






007095

SUB 2 SIGNATURE _____

007096

FIELD DATA SHEET 1

Site Information:

Occupant: 	Interviewee: George Mack
Address:  <i>Morrero</i>	
Phone No.: 	
Owner Name, Address, and Phone No. if Different Than Occupant:   <i>Morrero, LA 70072</i>	

Site Description:


1) Description of property (circle): single home; duplex; business; school; daycare; church;
vacant house; vacant lot; other _____

2) Problems accessing yards (circle): locked gate; gate; dogs; other Fence
resolution: Rottweiler + pit bull

3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV;
septic tank; other _____
Note location on site sketch.

4) Is any underground ACM present? (circle): yes; no; don't know
If yes, note on site sketch. How deep? suspect larger area than is visible

Site Sketch:



Estimated Volume of ACM: unknown

Comments: Owner owns both projects at 499 and 455
11/26/96 - need to call about replacement material

Date/Time of Interview: 11/25/96

Access Granted (circle): yes; no

Team Members: *G. Day*

07-0892-510

007097

Trackings# 092

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]

Property's Address: [REDACTED] 55 Eisenman too

State/Zip: 70075

Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

11-26-96

DATE

[REDACTED]
SIGNATURE

07-0892-520

007098

Site 892

Site sketch

SITE 892

4/8/97

1010/1050

Team CC/MTT/ML

~~76~~


Merreio, LA

parking pad
for boat 11x17

No. 5505
Engineer's Computation Pad



Date:



(b) (6)

Notes gas & water lines near
boat pad

cover

ACM

① SACM 2" thick ACM

② .25' cement 5" thick ACM

07-0892-530

Restoration

(A) ~~in drive way~~ Concrete pad 11x17

(B) ~~concrete pad~~ Soil/sod

to see note 007099

To 77 on 4/21/97

FIELD DATA SHEET 1


Site Information:

Occupant: <u>[REDACTED]</u>	Interviewee: <u>[REDACTED]</u>
Address: <u>[REDACTED] Herrera</u>	
Phone No.: <u>[REDACTED]</u>	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>[REDACTED]</u> <u>Marrero, LA 70072</u>	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; <u>dogs</u> ; other <u>Fence</u> resolution: <u>Rottweiler + pit bull</u>
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? <u>Suspect larger area than is visible</u>

Site Sketch:

Estimated Volume of ACM: unknownComments: Owner owns both properties at 499 and 455
11/26/96 - need to call about replacement materialDate/Time of Interview: 11/25/96Access Granted (circle): yes; noTeam Members: G. Day

007100

4/12/97 - OSC Windheim; ~~the~~

NO new rock! Will replace driveway area with concrete ^{area} comparable to ~~the~~ pad in the back. If area is smaller, will make arrangements, if area is bigger, will form area for Mr. Mack to pour own concrete. Please call before coming so he can schedule diggs, etc.

5/6/97 - talked w/ Pat @ IT - understands what owner wants and will dig areas in back per grass restoration and front areas as per concrete placement by resident.

07-0892-600

007101

WESTBANK ACM REMOVAL PROJECT
SAMPLE ANALYSIS CONFIRMATION
USEPA START TEAM

FYI:

SITE# 892

ADDRESS: [REDACTED]

Marrero, LA

THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON 05.08.97 ^{No analytical results received as of 05.08.97}


BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ☒ ☒

B. FURTHER ACTION NECESSARY: ☐ ☐

- Visible ACM after excavation highlighted below by (1) and (2)
- Geokined 05.07.97



AUTHORIZED EPA/START REPRESENTATIVE

Alma Rillera

Westmont, NJ 908-368-0900 Pleasantway, NJ 908-861-0550 Clark Place, NY 810-997-7251 Manhattan, NY 212-590-0062 Seattle, WA 206-223-6007 Ann Arbor, MI 313-963-4010 San Mateo, CA 415-476-4401 Smyrna, GA 404-323-0900 Greensboro, NC 919-297-1437 Houston, TX 713-866-3625



Ecology & Environment, Inc.
11550 Newcastle Ave. #250
Baton Rouge, LA 70816

Friday, May 09, 1997

Ref Number: TX971670

POLARIZED LIGHT MICROSCOPY (PLM)

Project: WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS % NONFIBROUS
WBS177G16	HEBERT, MA	Brown Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other
WBS177G17	HEBERT, MA	Brown Non-Fibrous Homogeneous	Teased		None Detected		100% Other
WBS892G01	TEISEMAN, MA	Brown Non-Fibrous Homogeneous	Teased		None Detected		100% Other
WBS892G02	TEISEMAN, MA	Brown Non-Fibrous Homogeneous	Teased		None Detected		100% Other
WBS433G01	MA	Brown Non-Fibrous Homogeneous	Teased		None Detected		100% Other
WBS433G02	MA	Brown Non-Fibrous Homogeneous	Teased		None Detected		100% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "% of Layers" refers to number of separable subsamples.


Arthur Hernandez, Jr.
Analyst

Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. This report is not guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product or nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

07-0892-570

007103




INTERNATIONAL
TECHNOLOGY
CORPORATION



By PM Date 5-9-97 Subject RESTORATION SITE # 892 Sheet No. of

Chkd. By Date Proj. No. jam



07-0892-590

007104

WESTBANK ASBESTOS ABATEMENT NEW ORLEANS, LOUISIANA

RESTORATION FORM

SITE # 892

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)							
Sod Installation (sq.yds.)					(b) (4) (b) (4)		
6" Concrete Installation (sq. yds.)					(b) (4) (b) (4)		
4" Concrete Installation (sq. yds.)							
Sand Installation (sq.yds.)					(b) (4) (b) (4)		
Lower Lift Sand							
Rock, Brown (cu.yds.)							
Rock, Gray (cu.yds.)							
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)					(b) (4)		
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

07-0892-590

IT REPRESENTATIVE SIGNATURE

SUB 1 SIGNATURE

SUB 2 SIGNATURE

_____ 007105 _____

WESTBANK ACM REMOVAL PROJECT
SAMPLE ANALYSIS CONFIRMATION
USEPA START TEAM

FYI:

SITE# 892

ADDRESS: [REDACTED]
Marrero, LA

THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON 05.08.97 ^{No analytical results received as of 05.08.97}


BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ☒ ☒

B. FURTHER ACTION NECESSARY: ☐ ☐

- Visible ACM after excavation highlighted below by (1) and (2)
- Geolined 05.07.97



AUTHORIZED EPA/START REPRESENTATIVE

Alma Rillera

Westmont, NJ 800-650-6000
 Pleasanton, NJ 800-861-6550
 Carlo Place, NY 810-997-7351
 Manhattan, NY 212-690-0062
 Seattle, WA 206-333-9007
 Ann Arbor, MI 313-969-4810
 San Mateo, CA 415-878-6401
 Dayton, OH 904-333-9906
 Greensboro, NC 910-287-1437
 Houston, TX 713-669-3635

EMSL

Ecology & Environment, Inc.
 11550 Newcastle Ave. #250
 Baton Rouge, LA 70816

Friday, May 09, 1997

Ref Number: TX971670

POLARIZED LIGHT MICROSCOPY (PLM)**Project: WESTBANK ASBESTOS**

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
WBS177G16	HEBERT, MA	Brown Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other
WBS177G17	HEBERT, MA	Brown Non-Fibrous Homogeneous	Teased		None Detected		100% Other
WBS892G01	EISEMAN, MA	Brown Non-Fibrous Homogeneous	Teased		None Detected		100% Other
WBS892G02	EISEMAN, MA	Brown Non-Fibrous Homogeneous	Teased		None Detected		100% Other
WBS433G01	MA	Brown Non-Fibrous Homogeneous	Teased		None Detected		100% Other
WBS433G02	MA	Brown Non-Fibrous Homogeneous	Teased		None Detected		100% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately.
 Also, "% of Layers" refers to number of separable subsamples.

Arthur Hernandez, Jr.
 Analyst

Approved
 Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative results are not guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product or nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

07-0892-570

007103




INTERNATIONAL
TECHNOLOGY
CORPORATION



By PM Date 5-9-97 Subject RESTORATION SITE # 892 Sheet No. of

Chkd. By Date Proj. No. Jem



07-0892-590

007104

WESTBANK ASBESTOS ABATEMENT NEW ORLEANS, LOUISIANA

RESTORATION FORM

SITE # 892

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)					(b) (4)		
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)					(b) (4)		
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

07-0892-590

IT REPRESENTATIVE SIGNATURE _____

SUB 1 SIGNATURE _____

SUB 2 SIGNATURE _____

607105

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/23/98
SITE #: 892

ADDRESS: [REDACTED]
Marrero

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED

APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

<div>NO ACM</div>	<div>[REDACTED] siding</div>
	<div>[REDACTED] soil</div>
	<div>[REDACTED] slab</div>

TEAM MEMBERS:

RL/JS

07-0892-540

007106

Tracking Number 893
No visible ACM

11-23 sketch, 1554, JM/AR FIELD DATA SHEET 1

Site Information:

Occupant: [REDACTED]	Interviewee: [REDACTED]
Address: [REDACTED], Gretna	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED]	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other <u>NA</u> resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other <u>NA</u> Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? <u>NA</u>

Site Sketch:

(b) (6)

Estimated Volume of ACM: _____	
Comments: <u>NO visible ACM. Tenant stated that city removed some driveway concrete 1.5 years ago during water line replacement.</u>	
Date/Time of Interview: <u>11/23/96 1554</u>	Access Granted (circle): yes; no <u>NA</u>
Team Members: <u>JM/AR</u>	05-0893-510

007107

TRACKING# 893 / 894

NO ACM

007108

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 8-7-98

ADDRESS: [REDACTED]

SITE #: 0893

GRETNH

ACM LOCATED BENEATH:

☐ HOUSE
☐ SHED

APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

☐ CHUNKS
☐ POWDER
☐ SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

<p>NO VIS ACM HOUSE ON CONC SLAB</p>	_____

TEAM MEMBERS: PM

05-0893-540

007109

Tracking Number 894

NO visible ACM

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewer: [REDACTED]
Address: [REDACTED]	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: <i>same as above</i>	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other <u>NA</u> resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other <u>NA</u> Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know <u>NA</u> If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____	
Comments: <i>No visible ACM, 11-23, 16:22, JM/AR</i>	
Date/Time of Interview: <i>11/23/96 1622</i>	Access Granted (circle): yes; no <u>(NA)</u>
Team Members: <i>JM/AR</i>	05-0894-510

007110

TRACKING# 894^{ml} 894

NO ACM

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/1/98
SITE #: 894

ADDRESS: [REDACTED]

ACM LOCATED BENEATH:

☐ HOUSE
☐ SHED

APPR. CRAWL SPACE HEIGHT:

NA

DESCRIPTION OF ACM:

☐ CHUNKS
☐ POWDER
☐ SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

<p><i>NO ACM</i> <i>Removal Cellar</i></p>	

TEAM MEMBERS:

DA/ML

05-0894-540

007112

Tracking Number 617-895

FIELD DATA SHEET 1

Site Information:

Occupant: [REDACTED]	Interviewee: [REDACTED]
Address: [REDACTED]	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED] Gretna, LA	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:

Site Sketch:

shed

carport

Barn

← N

⊙ = ACM

(b) (6)

Estimated ^{area} Volume of ACM: <u>24 ft²</u>	
Comments: <u>Backfill: soil/sod</u>	
Date/Time of Interview: <u>11-23 / 10:01</u>	Access Granted (circle): <u>yes</u> ; no
Team Members: <u>JM/AR</u>	05-0895-510

007113

617 sw
895

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: _____
Property's Address: _____
State/Zip: LA Phone Number(s): _____

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

11-23-96
DATE


(b) (6)

TRACKING # 895

SITE SKETCH

ADDRESS: [REDACTED]

UPDATED: 1/1



NOTES:

N (NTS)
←

RESTORATION: A: sod/soil
B:
C:

ARRIVAL: 9:30
DEPARTURE: 9:15

TEAM: TT/SJ

RESTORATION APPROVED BY: [REDACTED]

JM 7/9

DATE: 6/27/97

Via Phone 1750 DATE: 7/21/97

TO IT 07/22/97 gpd

#	COVER	THICKNESS
1	6" + soil/shell	—
2	3" soil/shell	3" ACM
3	—	5" SACM

05-0895-530

WESTBANK ACM REMOVAL PROJECT
SAMPLE ANALYSIS CONFIRMATION
USEPA START TEAM

FYI:

SITE# 895

ADDRESS: ~~1521 GLENVIEW~~
Glenview



THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON No analytical as of 08-07-97

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ☒

B. FURTHER ACTION NECESSARY: ☐



007116

05-0895-560

AUTHORIZED EPA/START REPRESENTATIVE

Alma Rulliere

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
Indianapolis, Indiana 46250
Phone (317) 570-5892 Fax (317) 570-5894



Attn.: Alma Rillera
Ecology & Environmental
11550 New Castle Avenue
Baton Rouge, LA 70816

Monday, August 11, 1997

Ref Number: IN97753

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: 020601 RAGI WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
WBS895G01	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
WBS352G01	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed		None Detected		80% Quartz 20% Other
WBS352G02	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed		None Detected		20% Quartz 80% Other
WBS128G01	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile < 1% Crocidolite		80% Quartz 20% Other
WBS128G02	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed		None Detected		80% Quartz 20% Other
WBS367G01	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "N of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 196-1 Method

Jane Wasilewski
Analyst

Approved
Signatory

Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negat be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the its may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim prod. NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200586-0)

05-0895-570

007117



INTERNATIONAL
TECHNOLOGY
CORPORATION



By PM Date 8-8-97 Subject RESTORATION site # 895 Sheet No. _____ of _____

Chkd. By _____ Date _____ Proj. No. _____

1517

1531

Rock

SIDEWALK

(b) (6)

05-0895-590

007118

**WESTBANK ASBESTOS ABATEMENT
NEW ORLEANS, LOUISIANA**

RESTORATION FORM

SITE # 895

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)					(b) (4) (b) (4)		
Sod Installation (sq.yds.)							
6" Concrete Installation (sq. yds.)							
4" Concrete Installation (sq. yds.)							
Sand Installation (sq.yds.)							
Lower Lift Sand							
Rock, Brown (cu.yds.)							
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)							
Concrete (cu.yds.)							
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

05-0895-590

IT REPRESENTATIVE SIGNATURE

SUB 1 SIGNATURE

SUB 2 SIGNATURE

007119

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 8/27/98
SITE #: 0895

ADDRESS: [REDACTED]

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	<u>Vacant lot</u>

TEAM MEMBERS:

MTL / PLL

05-0895-540

07120

Tracking Number 896
No visible ACM

FIELD DATA SHEET 1

11-22 No one Home, sketch made, did not enter back yard, 2 dogs; JM/AR, 1529
11-

Site Information:

Occupant: [REDACTED]	Interviewee: [REDACTED]
Address: [REDACTED] Merrittown	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: as above	

Site Description:

1) Description of property (circle): single home; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; <u>dogs</u> ; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch. <u>N/A</u>
4) Is any underground ACM present? (circle): yes; no; don't know <u>N/A</u> If yes, note on site sketch. How deep? _____

Site Sketch:

Site Sketch: [Hand-drawn sketch of a property with a concrete drive, a large blacked-out area, and a north arrow pointing right. The bottom of the sketch is labeled (b) (6).]

Estimated Volume of ACM: _____

Comments: No visible ACM, 11-23, 09:31, JM/AR

Date/Time of Interview: _____	Access Granted (circle): yes; no <u>(N/A)</u>
Team Members: _____	08-0896-510

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/22/98
SITE #: 0896

ADDRESS [REDACTED]
Terrytown

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

 <p>No ACM present</p>	_____

08-0896-540

TEAM MEMBERS:

JS&EW

007122

Tracking Number 897
No visible ACM

FIELD DATA SHEET 1

11-22, No one home, made sketch, 4M/AR, 1500
11-23, No one home, checked yard, 0915, 1M/AR


Site Information:

Occupant:	Interviewee:
Address: <u>[REDACTED]</u> , <u>Seagraven</u>	
Phone No.:	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>[REDACTED]</u> <u>576-578</u> <u>[REDACTED]</u>	

Site Description:

1) Description of property (circle): single home; <u>duplex</u> ; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other <u>NA</u> resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other <u>NA</u> Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____

Comments: No visible ACM

Date/Time of Interview:

Access Granted (circle): yes; no (NA)

Team Members:

08-0897-510

007123

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/22/98

SITE #: 0897

ADDRESS: [REDACTED]
Terrytown

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

 <p>no ACM present</p>	_____

TEAM MEMBERS: JS & EW

08-0897-540

007124

NO visible ACM

11-22, No one home, could not access backyard; JM/AR, 1331

Occupant: [REDACTED]	Interviewee: [REDACTED]
Address: [REDACTED]	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED] as above	

Interviewee: [REDACTED] Cadro

as above ~~SECRET~~

1) Description of property (circle):	single home;	duplex;	business;	school;	daycare;	church;	vacant house;	vacant lot;	other _____	
2) Problems accessing yards (circle):	locked gate;	gate;	dogs;	other _____	resolution: _____					
3) Underground utilities installed by owner? (circle):	no;	water;	gas;	electric;	cable TV;	septic tank;	other _____	Note location on site sketch.		
4) Is any underground ACM present? (circle):	yes;	no;	don't know	If yes, note on site sketch. How deep? _____						

Site Sketch:

green-house

garage

concrete drive

N →

green-house

[illegible]

$N \rightarrow$

(b) (6)(b) (6)

Comments: *No visible ACM, 11-23, 08:52, JM*

Access Granted (circle): yes; no

01-0898-510

007125

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE:

9/22/98

ADDRESS:

~~XXXXXXXXXX~~
~~XXXXXXXXXX~~
Algiers

SITE #:

0898

ACM LOCATED BENEATH:

<input type="checkbox"/>
<input type="checkbox"/>

HOUSE
SHED

APPR. CRAWL SPACE HEIGHT:


DESCRIPTION OF ACM:

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

CHUNKS
POWDER
SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

 <p>no ACM present</p>	_____

TEAM MEMBERS:

JS & EW

01-0898-540

007126

Tracking Number 899
reference # 326

FIELD DATA SHEET 1

Site Information:

Occupant: [REDACTED]	Interviewee: <u>Woodhew</u>
Address: <u>[REDACTED] marrero Laporte Barataria</u>	
Phone No.: <u>[REDACTED]</u>	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>[REDACTED]</u>	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; <u>gate</u> ; dogs; other <u>open</u> resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): <u>yes</u> ; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:

(b) (6) (b) (6)

Estimated Volume of ACM: <u>1126 #2</u>	
Comments: <u>limestone w/ edging</u> <u>Call before we come out</u>	
Date/Time of Interview: <u>12/10 16:45</u>	Access Granted (circle): <u>yes</u> no
Team Members: <u>R/ML</u>	<u>07-0899-510</u> <u>#326 12/3/10</u>

007127

326
899

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Two - Property Owner's Name: [REDACTED]
Property's Address: [REDACTED]
State/Zip: 70072 Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

Nov. 14 - 1996
DATE

[REDACTED]
SIGNATURE

Two Separate Properties

1- [REDACTED] a # [REDACTED] Bath Driveway
2- [REDACTED] → [REDACTED]
(side of house driveway) very little
007128


07-0899-520

TRACKING # 899


SITE SKETCH

ADDRESS: [REDACTED] Fla.

UPDATED: 1



NOTES:



RESTORATION: A: Limestone
B:
C:

ARRIVAL: 8:00
DEPARTURE: 9:00

TEAM: TT/CJ/mw
RESTORATION APPROVED BY: [REDACTED]
DATE: 6/23/97

#	COVER	THICKNESS
1	6" + sed/soil	
2	1" sed/soil	3" ACM
3		4" S&C

07-0899-530

DATE: 6/23/97

WESTBANK ACM REMOVAL PROJECT

SAMPLE ANALYSIS CONFIRMATION

USEPA START TEAM

FYI:

SITE# 899

ADDRESS: [REDACTED]
[REDACTED]


THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON No analytical as of 07-30-97

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

- A. PROCEED WITH RESTORATION: ✓ ✓ ✓ ✓
- B. FURTHER ACTION NECESSARY:

• Visible ACM after excavation highlighted below by: (1) and (2)
 • Gridded 7-29-97



07-0899-560

AUTHORIZED EPA/START REPRESENTATIVE

Alma Rillera
 007130

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
Indianapolis, Indiana 46250
Phone (317) 570-5892 Fax (317) 570-5894

Attn.: Gregory R. Day
Ecology & Environmental
11550 New Castle Avenue
Baton Rouge, LA 70816

Thursday, July 31, 1997

Ref Number: IN97642

EMSL**POLARIZED LIGHT MICROSCOPY (PLM)**

Performed by EPA 600/R-93/116 Method*

Project: 020601 RAG1 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS
WBS596G02	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	None Detected			80% Quartz 20% Other
WBS899G01	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	1%	Chrysotile		80% Quartz 18% Other
				1%	Crocidolite		
WBS899G02	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
				< 1%	Crocidolite		
WBS899G03	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
				< 1%	Crocidolite		
WBS964G01	[REDACTED] ST.	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
WBS964G02	[REDACTED] ST.	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

Margaret S. Phillips
Margaret Phillips
Analyst

[Signature]
Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negat be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the its may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim prod. NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200188-0).

07-0899-570

007131

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
Indianapolis, Indiana 46250
Phone (317) 570-5892 Fax (317) 570-5894

EMSL

Attn.: Deena DePalma
Ecology & Environmental
11550 New Castle Avenue
Baton Rouge, LA 70816

Friday, August 01, 1997

Ref Number: IN97668

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: 020601 RAGI WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS % NONFIBROUS
WBS899G04	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			40% Quartz 60% Other
WBS596G03	[REDACTED] GRENA	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			40% Quartz 60% Other
WBS976G01	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			40% Quartz 60% Other
WBS976G02	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile			40% Quartz 60% Other
WBS965G01	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile			40% Quartz 60% Other
WBS965G02	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			40% Quartz 60% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

Jane Wasilewski
Analyst

Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product (NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one sign Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200188-0).

07-0899-570

007132




INTERNATIONAL
TECHNOLOGY
CORPORATION



By PM Date 7-30-97 Subject RESTORATION SITE # 899 Sheet No. of

Chkd. By Date Proj. No.



007133

07-0899-590

WESTBANK ASBESTOS ABATEMENT
NEW ORLEANS, LOUISIANA

RESTORATION FORM

 SITE # 899

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)					(b) (4)		
Sod Installation (sq.yds.)							
6" Concrete Installation (sq. yds.)							
4" Concrete Installation (sq. yds.)							
Sand Installation (sq.yds.)							
Lower Lift Sand							
Rock, Brown (cu.yds.)							
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)							
Concrete (cu.yds.)							
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoll (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

IT REPRESENTATIVE SIGNATURE _____

07-0899-590

SUB 1 SIGNATURE _____

SUB 2 SIGNATURE _____

007134
~~007134~~

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9-23-98

ADDRESS: [REDACTED]

SITE #: 0899

MARRERO

ACM LOCATED BENEATH:

<input checked="" type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED

APPR. CRAWL SPACE HEIGHT:

0

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

0%

SKETCH OR COMMENTS:

<p>NO ACM</p>	

07-0899-540

TEAM MEMBERS: J.Y. + A.T.

007135

Tracking Number 900

No visible ACM

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee: <u>Kenya (daughter)</u>
Address: <u>2 [REDACTED] [REDACTED]</u>	
Phone No.: <u>[REDACTED]</u>	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>Janice Smith</u>	

Site Description:

1) Description of property (circle): <u>single home</u> duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): <u>locked gate</u> ; <u>gate</u> ; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know _____ If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____

Comments: NO visible ACMDate/Time of Interview: 12/11 09:40Access Granted (circle): yes; no N/ATeam Members: TC/ML

01-0900-510

007136

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/21/98
SITE #: 0900

ADDRESS: [REDACTED]
Algiers

ACM LOCATED BENEATH:

☐ HOUSE
☐ SHED

APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

☐ CHUNKS
☐ POWDER
☐ SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

<div>no ACM Present</div>	

TEAM MEMBERS:

JS & EW

01-0900-540

~~07137~~ 07137

1/8/97 OWNER CALLED -- TALKED TO KOBIE

Frontyard-driveaway
early at work

Tracking Number 901

No ACM

FIELD DATA SHEET 1

Site Information:

Occupant: [REDACTED]	Interviewee: Ms. [REDACTED]
Address: [REDACTED] Harvey 70058	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED]	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; <u>dogs</u> ; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; <u>no</u> ; don't know If yes, note on site sketch. How deep? _____

Site Sketch:

Sketch of property layout:

- DITCH (top)
- shed (top right)
- Porch (middle left)
- Drive way concrete (bottom left)
- [REDACTED] (center)
- (b) (6) (bottom center)
- N (North arrow, right)

Estimated Volume of ACM: _____

Comments: NO VISIBLE ACM

Date/Time of Interview: 1/8/97 11:28

Access Granted (circle): yes; no N/A

Team Members: RW/LT

06-0901-510

007138

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/21/98
SITE #: 901

ADDRESS: [REDACTED]
Harvey

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	_____

TEAM MEMBERS:

RL, TS

06-0901-540

007139

FIELD DATA SHEET 1

Site Information:

Occupant: <u>[REDACTED]</u>	Interviewee: <u>NONE</u>
Address: <u>[REDACTED]</u> <u>HARVEY</u>	
Phone No.:	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>[REDACTED]</u> <u>[REDACTED]</u>	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; <u>gate</u> ; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; <u>don't know</u> If yes, note on site sketch. How deep? _____

Site Sketch:

Site Sketch:

(b) (6)

Estimated Volume of ACM: NONEComments: NO ACM

Date/Time of Interview: <u>12/3/96</u>	Access Granted (circle): yes; no <u>NA</u>
Team Members: <u>CMA/SN</u>	<u>06-0902-510</u>

TRACKING# 902

NO ACM

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/14/98

ADDRESS: [REDACTED]

SITE #: 902

ACM LOCATED BENEATH:

☐ HOUSE
☐ SHED

APPR. CRAWL SPACE HEIGHT:


NA

DESCRIPTION OF ACM:

☐ CHUNKS
☐ POWDER
☐ SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	<div>concrete slab</div>
---	------------------------------

TEAM MEMBERS: DA/ML

06-0902-540

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee: <u>None</u>
Address: [REDACTED] <u>HARVEY</u>	
Phone No.:	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED] [REDACTED]	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; <u>gate</u> ; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; <u>no</u> ; don't know If yes, note on site sketch. How deep? _____

Site Sketch:

Estimated Volume of ACM: NONE

Comments:

NO ACMDate/Time of Interview: 12/3/96 1255Access Granted (circle): yes; no (N/A)Team Members: CMA / SN

06-0903-510

007143

TRACKING# 903

NO ACM

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/4/98
SITE #: 903

ADDRESS: 903 [REDACTED] St.
HHA

ACM LOCATED BENEATH:

☐ HOUSE
☐ SHED

APPR. CRAWL SPACE HEIGHT:

NA

DESCRIPTION OF ACM:

☐ CHUNKS
☐ POWDER
☐ SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

concrete slab

TEAM MEMBERS:

DA/ML

06-0903-540

007145

FIELD DATA SHEET 1


Site Information:

Occupant: <u>[REDACTED]</u>	Interviewee: <u>NONE</u>
Address: <u>769 Gresham St. Gretna</u>	
Phone No.:	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>[REDACTED]</u> <u>[REDACTED]</u>	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; <u>gate</u> ; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; <u>no</u> ; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



(b) (6)

Estimated Volume of ACM: <u>NONE</u>	
Comments: <u>NO ACM</u> LEFT NOTICE OF NO ACM MAPN,6	
Date/Time of Interview: <u>12/3/96 1445</u>	Access Granted (circle): yes; no <u>(N/A)</u>
Team Members: <u>CMA/SN</u>	05-0904-510

TRACKING# 904

NO ACM

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE:

8/28/98

ADDRESS:

[REDACTED]
Gretna

SITE #:

704

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	_____

TEAM MEMBERS:

MTL / PLL

05-0904-540

007118

FIELD DATA SHEET 1

Site Information:

Occupant: [REDACTED]	Interviewee: <u>NONE</u>
Address: [REDACTED]	
Phone No: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED] [REDACTED]	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other <u>NONE</u> resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; <u>no</u> ; don't know If yes, note on site sketch. How deep? _____

Site Sketch:

Site Sketch:

(b) (6)(b) (6)

Estimated Volume of ACM: NONEComments: NEWER NEIGHBORHOODNO ACM12/3 NO ONE IN - LEFT NOTICE OF NO ACM

MAP N, 6

Date/Time of Interview: 12/3/96 1430Access Granted (circle): yes; no N/ATeam Members: CWA / SN

05-0905-510

TRACKING# 905

NO ACM

007151

FIELD DATA SHEET 1

Site Information:

Occupant: [REDACTED]	Interviewee: JOY
Address: [REDACTED]	HARVEY
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED] [REDACTED]	

Site Description:

1) Description of property (circle): <u>single home</u> duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; <u>gate</u> ; dogs; other <u>NONE</u> resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; <u>don't know</u> If yes, note on site sketch. How deep? _____

Site Sketch:

(b) (6)

Estimated Volume of ACM: 200 ft²Comments: FENCE EMBEDDED IN ACM - BOTH SIDES.
DOESN'T WANT GOD/SOIL OR LIMESTONE - CONCRETE PREFERRED.

Date/Time of Interview: 12/3/16 1150	Access Granted (circle): <u>yes</u> no
Team Members: CMA/SN	06-0906-510

007152

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]
Property's Address: [REDACTED] HARVEY
State/Zip: LA 70058 Phone Number(s): 3 [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.


I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.


12/3/96
DATE

[REDACTED]
SIGNATURE

06-0906-520



NOTES: Chain Wall - 8" high + 6" deep



#	COVER	THICKNESS
①	+6" grass + soil	—

RESTORATION: A: concrete

B:

C:

ARRIVAL: 1550

DEPARTURE: 1639

06-0906-530

RESTORATION APPROVED BY:

DATE: 6/5/97

TEAM: AL/DM/DA JM
6/6/97

DATE: 06/05/97
007154

Forward to IT 6/11/97 CHC

WESTBANK ACM REMOVAL PROJECT
SAMPLE ANALYSIS CONFIRMATION
USEPA START TEAM

FYI:

SITE# 906

ADDRESS: [REDACTED]
Harvey, LA


THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON no analysis of 6-24-97

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION:	✓						
B. FURTHER ACTION NECESSARY:							

- Visible ACM after excavation highlighted below by: (none applicable) N.T.S.
- Geolined 06-24-97



AUTHORIZED EPA/START REPRESENTATIVE

007155

Lawrence Roca

WESTBANK ACM REMOVAL PROJECT
SAMPLE ANALYSIS CONFIRMATION
USEPA START TEAM

FYI:

SITE# #906-PHII

ADDRESS: [REDACTED]
[REDACTED]



THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON no analytical as of 8-11-97

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION:

B. FURTHER ACTION NECESSARY:



AUTHORIZED EPA/START REPRESENTATIVE 007156 Deena DePalma

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
Indianapolis, Indiana 46250
Phone (317) 570-5892 Fax (317) 570-5894

EMSL

Attn.: Deena DePalma
Ecology & Environmental
11550 New Castle Avenue
Baton Rouge, LA 70816

Thursday, August 14, 1997

Ref Number: IN97795

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: 020601 RAGI WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS % NONFIBROUS
WBS906Q01		Brown Non-Fibrous Homogeneous	Crushed		None Detected		20% Quartz 80% Other
WBS357Q05		Brown Non-Fibrous Homogeneous	Crushed		None Detected		20% Quartz 80% Other
WBS357Q08		Brown Non-Fibrous Homogeneous	Crushed		None Detected		20% Quartz 80% Other
WBS1057G01	WW	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		20% Quartz 80% Other
WBS1057G02	WW	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		60% Quartz 40% Other
WBS451G03	WARRERO	Brown Non-Fibrous Homogeneous	Crushed	< 1% < 1%	Chrysotile Crocidolite		60% Quartz 40% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method


Jane Wasilewski
Analyst


Approved
Signatory

Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus, no guarantee. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim or NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least a Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200185-01)

06-0906-570

007157

Westmont, NJ Placetown, NJ Cape Place, NY Manhattan, NY Seattle, WA Ann Arbor, MI San Mateo, CA Smyrna, GA Greensboro, NC Houston, TX
 808-888-4800 908-981-0850 518-987-7251 212-290-0062 203-283-8007 313-688-8810 415-870-8401 404-333-8088 910-297-1487 713-888-3635

Attn.: Barbara Storey
 Ecology & Environment, Inc.
 11550 Newcastle Ave. #250
 Baton Rouge, LA 70816

Friday, June 27, 1997

Ref Number: TX972564

EMSL

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 800/R-93/116 Method*

Project: WESTBANK ASBESTOS / 020601RAG1

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS
WB8906G01	[REDACTED] AVE, HA	Brown Non-Fibrous Homogeneous	Tested		None Detected		100% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "% of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method



Carlos D. Salinas
 Analyst

Approved
 Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negat
 be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the as
 may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim prod
 NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one
 Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.
 Analysis performed by EMSL of Houston (NVLAP Air and Bulk #102106).

06-0906-570

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
 Indianapolis, Indiana 46250
 Phone (317) 570-5892 Fax (317) 570-5894

EMSL

Attn.: Alma Rillera
 Ecology & Environmental
 11550 New Castle Avenue
 Baton Rouge, LA 70816

Wednesday, August 13, 1997

Ref Number: IN97790

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: 020801 RAGI WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS % NONFIBROUS
WB8736G01	11550 NEW CASTLE AVE BATON ROUGE, LA	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			30% Quartz 70% Other
WB8736G02	11550 NEW CASTLE AVE AUGUST, MA	Brown Non-Fibrous Homogeneous	Crushed	2% Chrysotile < 1% Crocidolite			60% Quartz 38% Other
WB8736G03	11550 NEW CASTLE AVE AUGUST, MA	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			60% Quartz 40% Other
WB8736G04	11550 NEW CASTLE AVE AUGUST, MA	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			60% Quartz 40% Other
WB8184G01	11550 NEW CASTLE AVE AVE, MA	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			60% Quartz 40% Other
WB8908G01	11550 NEW CASTLE AVE MA PH 2	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile			60% Quartz 40% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "N of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

Jane Wasilewski
 Analyst

Approved
 Signatory


06-0906-570

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative results are not guaranteed. Floor tiles and wipe should be tested with either SEM or TEM. The above test report relates only to the item analyzed. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product compliance with any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one sig. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (NVLAP Air and Soil #200188-0).

007169



By PM Date 6-25-97 Subject Restoration site # 906 I Sheet No. of
 Chkd. By Date Proj. No.



06-0906-590

007160

WESTBANK ASBESTOS ABATEMENT

NEW ORLEANS, LOUISIANA

RESTORATION FORM

SITE # 906

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)							
Sod Installation (sq.yds.)							
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)							
Sand Installation (sq.yds.)							
Lower Lift Sand							
Rock, Brown (cu.yds.)							
Rock, Gray (cu.yds.)							
Sand (cu.yds.)							
Concrete (cu.yds.)					(b) (4)		
Plastic Edging (ft.)					(b) (4)		
Walkway Rock Inst. (sq.yds.)							
Topsoll (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS:

06-0906-590

IT REPRESENTATIVE SIGNATURE

SUB 1 SIGNATURE

SUB 2 SIGNATURE

007161




INTERNATIONAL
TECHNOLOGY
CORPORATION



By PM Date 8-12-97 Subject RESTORATION SITE # 906 II Sheet No. _____ of _____

Chkd. By _____ Date _____ Proj. No. _____

INSTALL CONC. CHAINWALL 21'9" x 0.18'
TOP OF CONC. GRADE WILL BE 1"
ABOVE BOTTOM OF CHAIN LINK.
BOTTOM OF CHAIN LINK WILL
BE ENCASED IN CONC.



06-0906-590

007162

WESTBANK

ASBESTOS ABATEMENT

NEW ORLEANS, LOUISIANA

RESTORATION FORM

SITE # 906 II

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)							
Sod Installation (sq.yds.)							
6" Concrete Installation (sq. yds.)							
4" Concrete Installation (sq. yds.)							
Sand Installation (sq.yds.)							
Lower Lift Sand							
Rock, Brown (cu.yds.)							
Rock, Gray (cu.yds.)							
Sand (cu.yds.)							
Concrete (cu.yds.)							
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS:

06-0906-590

IT REPRESENTATIVE SIGNATURE

SUB 1 SIGNATURE

SUB 2 SIGNATURE

007163

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE:

9/4/98

ADDRESS:

[REDACTED]

SITE #:

906

ACM LOCATED BENEATH:

☐ HOUSE
☐ SHED

APPR. CRAWL SPACE HEIGHT:

NA (23")

DESCRIPTION OF ACM:

☐ CHUNKS
☐ POWDER
☐ SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

<p>NO ACM</p> <p><i>[Signature]</i></p>	

TEAM MEMBERS:

DA/ML

06-0906-540

007164

12/2/96 no one home

FIELD DATA SHEET 1

Site Information:

Occupants: [redacted]	Interviewee: <u>NONE</u>
Address: [redacted] <u>Marven</u>	
Phone No.: [redacted]	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>Driveway/yard called in 12/2/96 1463</u>	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; <u>gate</u> ; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; <u>don't know</u> If yes, note on site sketch. How deep? _____

Site Sketch:

(b) (6)

NORTH

Estimated Volume of ACM: <u>NONE</u>	
Comments: <u>FOUND ONLY SOIL IN FRONT OF SHED 1.</u> <u>NO VISIBLE ACM</u>	
Date/Time of Interview: <u>12/3/96 1515</u>	Access Granted (circle): yes; no <u>NTA</u>
Team Members: <u>CMA/5N</u>	

TRACKING# 907

NO ACM

007166

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 8/20/98
SITE #: 907

ADDRESS:

Marverro

ACM LOCATED BENEATH:

☐ HOUSE
☐ SHED

APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

☐ CHUNKS
☐ POWDER
☐ SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

<i>No ACM</i>	_____

TEAM MEMBERS:

MTL/ASB
007167

07-0907-540

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED] OWNER	Interviewee: SAME
Address: [REDACTED] MARRERO	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant:	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; <u>gate</u> ; <u>dogs</u> ; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; <u>no</u> ; don't know If yes, note on site sketch. How deep? _____

Site Sketch:

Estimated Volume of ACM: NONEComments: NO ACMDate/Time of Interview: 12/3/96 1500Access Granted (circle): yes; no NATeam Members: CMA / SN00716807-0908-510

TRACKING# 908

NO ACM

07169

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/2/98
SITE #: 908

ADDRESS: [REDACTED]

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED

APPR. CRAWL SPACE HEIGHT:

12"

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

<p><i>NO ACM</i> <i>D. Miller</i></p>	_____

TEAM MEMBERS:

DA/ML

07-0908-540

007170

3 Apt access to 446
5196 will bring access

Tracking Number 909

FIELD DATA SHEET 1

update
phone #'s
KJ

Site Information:


Occupant: <u>Same</u>	Interviewee:
Address: <u>[REDACTED] HARVEY</u>	
Phone No.:	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>[REDACTED]</u> <u>[REDACTED]</u> (w/ <u>[REDACTED]</u>) <u>[REDACTED]</u>	

Site Description:

(w/ [REDACTED])

- 1) Description of property (circle): single home; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
- 2) Problems accessing yards (circle): locked gate; gate; dogs; other _____
resolution: 2-BACK
- 3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____
Note location on site sketch.
- 4) Is any underground ACM present? (circle): yes; no; Don't know
If yes, note on site sketch. How deep? _____

Site Sketch:



(b) (6)(b) (6)

Estimated Volume of ACM: _____

Comments: SMALL CONCRETE PAD POURED OVER ACM IN REAR
backfill: grass (within the fence)
limestone (behind the fence) BR

Date/Time of Interview: 12/3/96 1100

Access Granted (circle): yes; no

Team Members: CWA / SN

007171

06-0909-510

TELEPHONE INQUIRY LOG

DATE: 7-28 TIME: 11:00 a

NAME OF RESIDENT OR OWNER:

(Circle one)

[REDACTED]

SITE#: 909

HOME/WORK PHONE NUMBER:

[REDACTED]

ADDRESS:

[REDACTED]

CITY: Harvey

ZIP CODE: 70058

TYPE: (Circle one)

HOME

BUSINESS

SCHOOL

PARK

VACANT LOT

OTHER Duplex

COMMENTS OR COMPLAINTS:

was told cleanup would start in about 3wks - ok with that but
would like to report that the property behind this ^{identified} site needs to
be checked also.

RESOLUTION:

06-0909-600

007172

#909

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]
Property's Address: [REDACTED] HARVEY
State/Zip: LA 70058 Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

12/5/96
DATE

[REDACTED]
SIGNATURE

06-0909-520

007173


TRACKING #

909


SITE SKETCH

ADDRESS: [REDACTED]

UPDATED: 1/1



NOTES:



RESTORATION: A: [REDACTED]

B:

C:

ARRIVAL: 1030

DEPARTURE: 1130

RESTORATION APPROVED BY: [REDACTED]

(phone)

DATE: 8/12/97

TEAM: TT/DIA/DM

DATE: 7/21/97

007174

2027 8/12 K/

06-0909-530

WESTBANK ACM REMOVAL PROJECT
SAMPLE ANALYSIS CONFIRMATION
USEPA START TEAM

FYI:

SITE# 909

ADDRESS: [REDACTED]
MARRERO, LA

THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON no analytical as of 9-18-97


- received 09-22-97

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ☒

B. FURTHER ACTION NECESSARY: ☐



(b) (6)

06-0909-560

AUTHORIZED EPA/START REPRESENTATIVE

A. Rollins 007175

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
Indianapolis, Indiana 46250
Phone (317) 570-5892 Fax (317) 570-5894

Attn.: Deena DePalma
Ecology & Environmental
11550 New Castle Avenue
Baton Rouge, LA 70816

Monday, September 22, 1997

Ref Number: IN971142

EMSL

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: 020601 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS % NONFIBROUS
WBS1329G02	MARRERO	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
WBS1180G01	AVE, MA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
WBS1180G02	AVE, MA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile < 1% Crocidolite		80% Quartz 20% Other
WBS909G01	FAIRMONT, HA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile < 1% Crocidolite		80% Quartz 20% Other
WBS961G03	ST, HA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
WBS961G04	ST, HA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile < 1% Crocidolite		80% Quartz 20% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "N of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

Jane Wasilewski
Analyst

Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative results are not guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items analyzed. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product compliance with any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (BAA AP Air and Bulk #200188-0)

06-0909-570


607176



INTERNATIONAL
TECHNOLOGY
CORPORATION



By PM Date 9-19-97 Subject RESTORATION site # 909 Sheet No. of
Chkd. By Date Proj. No.



(b) (6)

06-0909-590

007177

SITE # 909

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)							
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)							
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoll (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

IT REPRESENTATIVE SIGNATURE

SUB 1 SIGNATURE

SUB 2 SIGNATURE

007178

06-0909-590

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/3/98
SITE #: 909

ADDRESS: [REDACTED]

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED

APPR. CRAWL SPACE HEIGHT:


18" - skirting

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

TEAM MEMBERS:

DA/JW

06-0909-540

007179

12/4/96 called owner / left message

Tracking Number 910

FIELD DATA SHEET 1

Site Information:

Occupant: [REDACTED]	Interviewee:
Address: [REDACTED] HARVEY	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED] [REDACTED]	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other <u>NONE</u> resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; <u>don't know</u> If yes, note on site sketch. How deep? _____

Site Sketch:

(b) (6)

Estimated Volume of ACM: _____

Comments: 12/3 LEFT ACCESS INFO
backfill: GRASS 12/6/96 0745 mLin

Date/Time of Interview: 12/3/96 1020

Access Granted (circle): yes; no 12/17

Team Members: CWA/SN

06-0910-510

mailed

mailed to
Dallas
12/6/96

007180

9/10

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]
Property's Address: [REDACTED] HARVEY
State/Zip: LA 70058 Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

11/4/96
DATE

[REDACTED]
SIGNATURE


06-0910-520

TRACKING # 910


SITE SKETCH

ADDRESS: 636 Pallet

UPDATED: 1 1



NOTES:



owner signed restoration in field prior to OSC approval
OWNER WANTS CONCRETE EXTENDING STRAIGHT BACK FROM EXISTING DRIVEWAY

RESTORATION: A: gran
B: CONCRETE
C:

ARRIVAL: 1800
DEPARTURE: 1400

RESTORATION APPROVED BY: [Signature]

TEAM: TT / DA / BM

DATE: 7 12 1 97 @ FORWARD TO IT 8/1/97
DATE: 7 21 1 97

007182

#	COVER	THICKNESS
1.	Soil/sod 6"	
2.	Soil/shell 6"	
3.	Soil/sod 3"	3' R/W
4.		4' S/CW

06-0910-530

WESTBANK ACM REMOVAL PROJECT SAMPLE ANALYSIS CONFIRMATION USEPA START TEAM

FYI:

SITE# 910

ADDRESS: [REDACTED]
Harvey, La.


THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON No analytical as of 9.12.97

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ✓ ✓ ✓ — — — — —

B. FURTHER ACTION NECESSARY: — — — — — — — —



AUTHORIZED EPA/START REPRESENTATIVE

[Signature]

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
Indianapolis, Indiana 46250
Phone (317) 570-5892 Fax (317) 570-5894

EMSL

Attn.: Christopher Sansone
Ecology & Environmental
11550 New Castle Avenue
Baton Rouge, LA 70816

Tuesday, September 16, 1997

Ref Number: IN971087

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
WBS910G01	HARVEY	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		30% Quartz 70% Other
WBS910G02	HARVEY	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
WBS910G03	HARVEY	Brown Non-Fibrous Homogeneous	Crushed	< 1% < 1%	Chrysotile Crocidolite		80% Quartz 20% Other
WBS910G04	HARVEY	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
WBS1273G01	WE	Brown Non-Fibrous Homogeneous	Crushed	3% 1%	Chrysotile Crocidolite		75% Quartz 21% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

Jane Wasilewski
Analyst

Approved
Signatory

Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus report is guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the test as performed. It may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product liability nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200188-0).

06-0910-570


007184



INTERNATIONAL
TECHNOLOGY
CORPORATION



By PM Date 9-15-97 Subject RESTORATION SITE # 910 Sheet No. _____ of _____
Chkd. By _____ Date _____ Proj. No. _____



06-0910-590

007185

**WESTBANK ASBESTOS ABATEMENT
NEW ORLEANS, LOUISIANA**

RESTORATION FORM

SITE # 910

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)							
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)					(b) (4)		
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

IT REPRESENTATIVE SIGNATURE

SUB 1 SIGNATURE

SUB 2 SIGNATURE

_____ **06-0910-590**
_____ **007186**

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 8-13-98

ADDRESS: [REDACTED]

SITE #: 0910

Harvey

ACM LOCATED BENEATH:

☐ HOUSE
☐ SHED

APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

☐ CHUNKS
☐ POWDER
☐ SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

The sketch area contains a large rectangle. A diagonal line runs from the bottom-left corner to the top-right corner. The word "No" is handwritten near the bottom-left corner, and "ACM" is handwritten near the top-right corner. To the right of the rectangle is a large area with horizontal lines for text.

06-0910-540

TEAM MEMBERS: KJ/JS

007187

12/3/96 called owner/left message
12/6/96 mailed access to owner

Tracking Number

911

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee: WISA
Address: [REDACTED] HARVEY	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED] [REDACTED] [REDACTED]	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other <u>NONE</u> resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; <u>don't know</u> If yes, note on site sketch. How deep? _____

Site Sketch:



(b) (6)

Estimated Volume of ACM: _____

Comments: ~~original time~~ 12/6/96 0830 min
CONCRETE 12/12 IN DRIVE -

Date/Time of Interview: 12/3/96 1035

Access Granted (circle): yes; no

Team Members: CMA SN

06-0911-510

mailed 12/17

007188

#911

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: _____
Property's Address: _____
State/Zip: Wego, La. Phone Number(s): _____
70094

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

12-10-96
DATE

[Signature]
SIGNATURE

_____ 4

TRACKING #


9/11

SITE SKETCH

ADDRESS: [REDACTED]

Harvey

UPDATED: 9/8/97



(b) (6)

NOTES:

N (NTS)

* approximately 260sqft. of concrete for pad - do either 10x26' (if it will fit) or 9x29' from front of house back.

RESTORATION:

A: concrete
B: L. masonry
C:

ARRIVAL: 1430

DEPARTURE: 1430

fw 7/25/97

RESTORATION APPROVED BY: [REDACTED]

Via Phone

DATE: 8/1/97

TEAM: TT/DA/BM

DATE: 7/21/97

007190

⊗ FORWARD TO IT 8/4/97
Jaw

#	COVER	THICKNESS
1	Soil/SOD 6"	
2	Soil/shell 6"	
3	Soil/SOD 3"	3" ACM
4	Soil/shell 3"	3" ACM
5		4" 9ACM

06-0911-530

TRACKING #

911

SITE SKETCH


ADDRESS:

718 N. [REDACTED]

Harvey

UPDATED:

1/1



NOTES:

N (NTB)



*approximately 260sqft. of concrete for pad - do either 10'x26' (if it will fit) or 9'x29' from front of house back.

RESTORATION: A: concrete
B: 6" mesh
C:

ARRIVAL: 1400

DEPARTURE: 1430

TW 7/12/97

RESTORATION APPROVED BY:

[REDACTED]

Via Phone 8/11/97

DATE: 8/1/97

TEAM: TT / DA / BM

DATE:

7/21/97

⊗ FORWARD TO IT 8/1/97
9lw

007191

#	COVER	THICKNESS
1.	Soil/SOD 6"	
2.	Soil/SOD 6"	
3.	Soil/SOD 3"	3" ACW
4.	Soil/SOD 3"	2" ACW
5.		4" GACW

06-0911-530

WESTBANK ACM REMOVAL PROJECT

SAMPLE ANALYSIS CONFIRMATION

USEPA START TEAM

FYI:

SITE# 911


ADDRESS: [REDACTED]
Harvey LA

THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON None needed

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #:	1	2	3	4	5	6	7	8
A. PROCEED WITH RESTORATION:	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
B. FURTHER ACTION NECESSARY:	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Geolined: 9/8/97



06-0911-560

AUTHORIZED EPA/START REPRESENTATIVE

007192

[Signature]

WESTBANK ACM REMOVAL PROJECT SAMPLE ANALYSIS CONFIRMATION USEPA START TEAM

FYI:

SITE# 911

ADDRESS: [REDACTED]
Harvey, Ca


THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON _____

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ✓ ✓ ✓ ✓ _____

B. FURTHER ACTION NECESSARY: _____



AUTHORIZED EPA/START REPRESENTATIVE

007193

06-0911-560

Westmont, NJ 908-858-4800 Pascataway, NJ 908-981-0660 Carle Place, NY 516-987-7261 Manhattan, NY 212-290-0062 Seattle, WA 203-233-9007 Ann Arbor, MI 313-688-6610 San Mateo, CA 415-570-5401 Smyrna, GA 404-333-6088 Greensboro, NC 810-287-1487 Houston, TX 713-686-3635

EMSL

Attn.: Christopher Sansone
Ecology & Environment, Inc.
11550 Newcastle Ave. #250
Baton Rouge, LA 70816

Wednesday, September 10, 1997

Ref Number: TX973781

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: WESTBANK ASBESTOS REMOVAL PROJECT/ KJ6102020601RAXX

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		%	NONASBESTOS	
				%	TYPE		FIBROUS	% NONFIBROUS
WBS-1251-G01	[REDACTED]	Brown Fibrous Homogeneous	Teased	< 1%	Chrysotile			100% Other
				< 1%	Crocidolite			
WBS-911-G01	[REDACTED]	Brown Fibrous Homogeneous	Teased	< 1%	Chrysotile			100% Other
WBS-911-C-02	[REDACTED]	Brown Fibrous Homogeneous	Teased	< 1%	Chrysotile			100% Other
WBS-911-G-03	[REDACTED]	Brown Fibrous Homogeneous	Teased	2%	Chrysotile			98% Other
WBS753-G01	[REDACTED]	Brown Fibrous Homogeneous	Teased		None Detected			100% Other
WBS753-G02	[REDACTED]	Brown Fibrous Homogeneous	Teased	< 1%	Chrysotile			100% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

Arthur Hernandez, Jr.
Analyst

Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus, negr be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the 1 may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim pro NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered sam. Analysis performed by EMSL of Houston (NVLAP Air and Bulk #102106).

06-0911-570

007194

Westmont, NJ 800-886-4800 Piscataway, NJ 800-881-0800 Carlo Place, NY 810-887-7351 Manhattan, NY 212-380-0082 Seattle, WA 206-233-9007 Ann Arbor, MI 313-886-8810 San Mateo, CA 415-870-8401 Atlanta, GA 404-883-8086 Greensboro, NC 910-297-1467 Houston, TX 713-886-3836

EMSL

Attn.: Christopher Sansone
Ecology & Environment, Inc.
11550 Newcastle Ave. #250
Baton Rouge, LA 70816

Wednesday, September 10, 1997

Ref Number: TX973788

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM)
Performed by EPA 40 CFR Part 763 Final Rule. (AHERA)

Project: WESTBANK ASBESTOS / 020401

SAMPLE ID	VOLUME (liters)	ASBESTOS TYPE(S)	# STRUCTURES			AREA ANALYZED (mm ²)	CONCENTRATION OF ASBESTOS STRUCTURES		ANALYTICAL SENSITIVITY (AS/cc)
			< 5	≥ 5	NONASB		AS/mm ²	AS/cc	
WBA98-HF3		Chrysotile	9	2	0	0.0808	216.8354	0.0243	0.0022
WBA197-HF5		Chrysotile	1	0	0	0.0808	19.8850	0.0032	0.0032
WBA911-HF10		None Detected			0	0.0788	413.1234	<0.0042	0.0042

Comments: For "None Detected" samples, the number under AS/cc is equal to the analytical sensitivity.

Carlos D. Salinas
Analyst

Approved
Signatory

06-0911-573

Disclaimer: The laboratory is only responsible for fibers counted in fibers/mm² and not in fibers/cc, which is dependent on non-laboratory personnel.

Accredited for PLM by NVLAP #102108

007195

Westmont, NJ 609-858-4800 Pleasanton, NJ 908-991-0560 Carlo Place, NY 616-987-7261 Manhattan, NY 212-290-0082 Seattle, WA 203-233-9007 Ann Arbor, MI 313-888-8810 San Mateo, CA 415-870-8401 Smyrna, GA 404-338-8080 Greensboro, NC 910-297-1487 Houston, TX 713-686-3635



Attn.: Christopher Sansone
Ecology & Environment, Inc.
11550 Newcastle Ave. #250
Baton Rouge, LA 70816

Wednesday, September 10, 1997

Ref Number: TX973781

POLARIZED LIGHT MICROSCOPY (PLM)


Performed by EPA 600/R-93/116 Method*

Project: WESTBANK ASBESTOS REMOVAL PROJECT/ KJ6102020601RAXX

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
WBS1251G01	[REDACTED]	Brown Fibrous Homogeneous	Tessed	< 1%	Chrysotile Crocidolite		100% Other
WBS911G01	[REDACTED]	Brown Fibrous Homogeneous	Tessed	< 1%	Chrysotile		100% Other
WBS911G02	[REDACTED]	Brown Fibrous Homogeneous	Tessed	< 1%	Chrysotile		100% Other
WBS911G03	[REDACTED]	Brown Fibrous Homogeneous	Tessed	2%	Chrysotile		98% Other
WBS753G01	[REDACTED] WE	Brown Fibrous Homogeneous	Tessed		None Detected		100% Other
WBS753G02	[REDACTED] WE	Brown Fibrous Homogeneous	Tessed	< 1%	Chrysotile		100% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "W of Layers" refers to number of separable subsamples.

* NY samples also analyzed by EPA 198-1 Method



Arthur Hernandez, Jr.
Analyst

Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus it is recommended that floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to PLM. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim (NVLAP) nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature. EMSL is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Houston (NVLAP Ar and Bulk #102100)

06-0911-570

007196

Westmont, NJ 909-856-4800 Pascabury, NJ 908-981-0850 Corte Madera, CA 916-997-7251 Manhattan, NY 212-280-0082 Seattle, WA 206-233-9007 Ann Arbor, MI 313-666-6810 San Mateo, CA 415-670-5401 Smyrna, GA 404-333-8088 Greensboro, NC 910-297-1487 Houston, TX 713-686-3635

EMSL

Attn.: Christopher Sansone
Ecology & Environment, Inc.
11550 Newcastle Ave. #250
Baton Rouge, LA 70816

Wednesday, September 10, 1997

Ref Number: TX973781

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: WESTBANK ASBESTOS REMOVAL PROJECT/ KJ6102020601RAXX

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
WBS763G03	[REDACTED]	Brown Fibrous Homogeneous	Teased		None Detected		100% Other
WBS998G03	[REDACTED] 4TH ST, HA	Brown/White Fibrous Homogeneous	Teased	40%	Chrysotile		60% Other
WBS911G04	[REDACTED] AVE., HA	Brown Fibrous Homogeneous	Teased	3%	Chrysotile < 1% Crocidolite		97% Other
WBS998G04	[REDACTED] ST, HA	Brown Fibrous Homogeneous	Teased	2%	Chrysotile < 1% Crocidolite		98% Other
WBS998G05	[REDACTED] ST, HA	Brown Fibrous Homogeneous	Teased	4%	Chrysotile < 1% Crocidolite		96% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 100-1 Method

Arthur Hernandez, Jr.
Analyst

Approved
Signatory


Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus reports be guaranteed. Floor mats and wipes should be tested with either SEM or TEM. The above test report relates only to the PLM. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim that NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Houston (NVLAP Air and Bulk #102108)

06-0911-570

007197



By PM Date 9-9-97 Subject RESTORATION SITE # 911 Sheet No. _____ of _____
Chkd. By _____ Date _____ Proj. No. _____



06-0911-590



RESTORATION FORM

SITE # 911

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)					(b) (4)		
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)					(b) (4)		
Plastic Edging (ft.)					(b) (4)		
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

IT REPRESENTATIVE SIGNATURE

SUB 1 SIGNATURE

SUB 2 SIGNATURE

007199

06-0911-590

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/4/98
SITE #: 911

ADDRESS: [REDACTED]

ACM LOCATED BENEATH:

☐ HOUSE
☐ SHED

APPR. CRAWL SPACE HEIGHT:


6"

DESCRIPTION OF ACM:

☐ CHUNKS
☐ POWDER
☐ SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	_____

TEAM MEMBERS: DA/ML

06-0911-540

007200

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee: <u>LORENA K. [REDACTED]</u>
Address: [REDACTED] <u>MARERO</u>	
Phone No.: _____	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED] <u>21 AUGUST [REDACTED]</u>	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; <u>gate</u> ; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> yes water; gas; electric; cable TV; <u>septic tank</u> ; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; <u>don't know</u> If yes, note on site sketch. How deep? _____

Site Sketch:

**(b) (6)(b) (6)**Estimated Volume of ACM: 435 cu ftComments: BACKFILL - SOIL + SOD

Date/Time of Interview: <u>12/4/96 1115</u>	Access Granted (circle): <u>(yes)</u> no
Team Members: <u>CMA / ML</u>	<u>07-0912-510</u>

007211

912

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]
Property's Address: [REDACTED] MARREAO
State/Zip: LA Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

12-4-96
DATE

[REDACTED]
SIGNATURE

07-0912-520

007202

TRACKING #


9/2

SITE SKETCH

ADDRESS: [REDACTED]

MARRIO

UPDATED: 1/1



NOTES:

N (N15)



⊕ OWNER WANTS ALL GRASS.

RESTORATION: A: soil/sod

B:

C:

ARRIVAL: 900
DEPARTURE: 930

RESTORATION APPROVED BY: [REDACTED]

Via Phone 61040

DATE: 8/1/77

TEAM: TT / CD / BEE JM 7/9

DATE: 6/10/77

⊕ To IT 8/1/97
9CW

007213

(b) (6)

#	COVER	THICKNESS
1	soil/sod	6"
2	soil/sod	3" ACm
3		3" SACM
4	Gravel	6"

07-0912-530

WESTBANK ACM REMOVAL PROJECT SAMPLE ANALYSIS CONFIRMATION USEPA START TEAM

FYI:

SITE# 912

ADDRESS: [REDACTED]
Marrero, La

THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON no analytical as of 9-17-97
received 09-22-97


BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ✓ ✓

B. FURTHER ACTION NECESSARY:

Geotined 9-17-97



07-0912-560

AUTHORIZED EPA/START REPRESENTATIVE

A. Pullera
007204

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
Indianapolis, Indiana 46250
Phone (317) 570-5892 Fax (317) 570-5894

EMSL

Attn.: Alma Rillera
Ecology & Environmental
11550 New Castle Avenue
Baton Rouge, LA 70816

Monday, September 22, 1997

Ref Number: IN971143

POLARIZED LIGHT MICROSCOPY (PLM)


Performed by EPA 800/R-93/116 Method*

Project: 020601 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	NONFIBROUS
WBS1228G01	[REDACTED] MARRERO	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			80% Quartz 20% Other
WBS912G01	[REDACTED] MA	Brown Non-Fibrous Homogeneous	Crushed	None Detected			80% Quartz 20% Other
WBS912G02	[REDACTED] MA	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			80% Quartz 20% Other
WBS1153G01	[REDACTED] MARRERO	Brown Non-Fibrous Homogeneous	Crushed	15% Chrysotile			75% Quartz 10% Other
WBS1361G01	[REDACTED] AVENUE, MA	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			80% Quartz 20% Other
WBS1393G01	[REDACTED] GRETNA	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile			80% Quartz 40% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method


Jane Wasilewski
Analyst


Approved
Signatory


07-0912-570

Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus, negative results are not guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the PLM analysis. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product compliance with any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature of a qualified analyst. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (IND) ASR and BSL-8200188-0.

0072115



By PM Date 9-22-97 Subject RESTORATION SITE # 912 Sheet No. _____ of _____
Chkd. By _____ Date _____ Proj. No. _____



07-0912-590

007206

WESTBANK ASBESTOS ABATEMENT NEW ORLEANS, LOUISIANA

RESTORATION FORM

SITE # 912

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)					(b) (4)		
Sod Installation (sq.yds.)					(b) (4)		
3" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)							
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoll (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

IT REPRESENTATIVE SIGNATURE _____ 07-0912-590
 SUB 1 SIGNATURE _____
 SUB 2 SIGNATURE _____ 007207

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9-24-98

SITE #: 0912

ADDRESS: [REDACTED]
[REDACTED]
MARRERO

ACM LOCATED BENEATH:



APPR. CRAWL SPACE HEIGHT: 0

DESCRIPTION OF ACM:



PERCENT OF AREA (ACM) 0%

SKETCH OR COMMENTS:

A large rectangular area for sketching or comments. On the left side, a diagonal line is drawn from the bottom-left corner towards the top-right corner. The words "NO ACM" are written in a large, handwritten font across this line. On the right side, the words "HOUSE ON SLAB" are written in a large, handwritten font. The rest of the area is filled with horizontal lines for additional notes.

TEAM MEMBERS: T.Y. & A.T.

07-0912-540

007208

RECEIVED

DEC 12 1996

BY: RPTracking Number 913

FIELD DATA SHEET 1

Site Information:

Occupant: [REDACTED]	Interviewee: [REDACTED]
Address: [REDACTED]	
Phone No.: [REDACTED] 55(W)	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED]	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): <u>locked gate</u> ; <u>gate</u> ; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): <u>yes</u> ; no; don't know If yes, note on site sketch. How deep? <u>east side of house</u>

Site Sketch:

Shed

pool 20' diam. ACM under

concrete

Business

7-ACM 4'x4'

Call & coordinate

(b)(6)
(b)(6)
(b)(6)

Estimated Volume of ACM: _____

Comments: 12/4 LEFT ACCESS w/ OWNER
ACM under pool. Owner will move pool
SDD/Soil in back yard; Limestone in front by light pole

Date/Time of Interview: 12/4/96 1510

Access Granted (circle): yes no

Team Members: ML/mtt

007209

07-0913-510

#913

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]

Property's Address: [REDACTED]

State/Zip: Manu La Phone Number(s): [REDACTED]

7072

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.


12/12/96

DATE

[REDACTED]
SIGNATURE

07-0913-520

007210



(b) (6)

NOTES: *Contact about parking problem.

9 + 6" grass soil

10 + 6" debris/concrete

11 + 6" grass/soil

This is a business (Tamales stand)

RESTORATION: A: 1m (13x6.5 + 10x50)

B: Sand Only (22x23)

4/17 C: 4/18

ARRIVAL: 1000 0830

DEPARTURE: 1710 0940

#	COVER	THICKNESS
①	2" gravel	ACM - 1"
②	6" soil/grass	ACM - 1"
③	6" gravel + soil	-
④	2" grass/soil	ACM - 1"
⑤	2" grass/soil	ACM - 2"
⑥	2" grass/soil	ACM - 1"
⑦	3" grass/soil	ACM - 1"
⑧	+ 6" grass/soil	-

07-0913-530

WESTBANK ACM REMOVAL PROJECT

SAMPLE ANALYSIS CONFIRMATION

USEPA START TEAM

FYI:

SITE# 913

ADDRESS: [REDACTED]

Marrero, LA


THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON 5-26-97

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ☒ ☒ ☒ ☒ ☒ ☒ ☐ ☐

B. FURTHER ACTION NECESSARY: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐




- Visible ACM after excavation highlighted below by: (1) and (2)
- Geolined 05.20.97

N.T.S.

↑ N
05.24.97
(AR)

GRID	Sample ID	Depth	Backfill/Anno.
①	WBS913G01	6"	limestone/sewerhouse
②	WBS913G02	6"	limestone/driveway
③	WBS913G03	6"	limestone/driveway
④	WBS913G04	6"	limestone/driveway
⑤	WBS913G05	6"	sod-soil/yard
⑥	WBS913G06	8"	sod-soil/yard



07-0913-560

AUTHORIZED EPA/START REPRESENTATIVE

[Signature]
07-212

USEPA START TEAM

Resolved 05/26/97. Bennett.
Will let restoration put in liner
ADDRESS: ~~_____~~
sand under
phase II since a pool will be in grid 4.
already talked with Pat of IT.

ULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND

SITE#

913

ADDRESS:


THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON NO ANALYSIS 5-21-97.

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION:

B. FURTHER ACTION NECESSARY:

- Visible ACM highlighted below (2A) And (1)
- Coloured 5-20-93



Wilmington, NJ 610-688-0000	Philadelphia, NJ 610-681-0000	Carle Place, NY 516-467-7201	Manhasset, NY 516-438-0000	Seattle, WA 206-498-0007	Ann Arbor, MI 313-489-0010	San Diego, CA 619-576-6401	Dayton, OH 919-489-0000	Greensboro, NC 919-487-1007	Baltimore, MD 714-488-0000
--------------------------------	----------------------------------	---------------------------------	-------------------------------	-----------------------------	-------------------------------	-------------------------------	----------------------------	--------------------------------	-------------------------------

EMSL

Ecology & Environment, Inc.
11550 Newcastle Ave. #250
Baton Rouge, LA 70816

Thursday, May 29, 1997

Ref Number: TX972002

POLARIZED LIGHT MICROSCOPY (PLM)**Project: WESTBANK ASBESTOS**

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	NONFIBROUS
WB9913G08	MA	Brown Fibrous Homogeneous	Tessed	2%	Chrysotile		98% Other
WB8488G01	HA	Brown Fibrous Homogeneous	Tessed	2%	Chrysotile		98% Other
WB8488G02	HA	Brown Fibrous Homogeneous	Tessed	2%	Chrysotile		98% Other
WB8488G03	HA	Brown Fibrous Homogeneous	Tessed	2%	Chrysotile		98% Other
WB8488G01	HA	Brown Non-Fibrous Homogeneous	Tessed		None Detected		100% Other
WB8488G04	HA	Brown Non-Fibrous Homogeneous	Tessed	< 1%	Chrysotile		100% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "N of Layers" refers to number of separable subsamples.

Arthur Hernandez, Jr.
Analyst

Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus not guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the test only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one sign is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

07-0913-570

007214

Westmont, NJ 908-653-4500	Plainsboro, NJ 908-981-8550	Carle Place, NY 516-977-7251	Manhasset, NY 212-230-8832	Seattle, WA 206-233-9007	Ann Arbor, MI 313-963-8310	San Mateo, CA 415-570-5401	Brynna, MA 617-330-6000	Greenboro, NC 919-287-1487	Albany, NY 518-488-9030
------------------------------	--------------------------------	---------------------------------	-------------------------------	-----------------------------	-------------------------------	-------------------------------	----------------------------	-------------------------------	----------------------------



Ecology & Environment, Inc.
11550 Newcastle Ave. #250
Baton Rouge, LA 70816

Friday, May 23, 1997

Ref Number: TX971924

POLARIZED LIGHT MICROSCOPY (PLM)

Project: 020601RAG1 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS
WBS913G05	MA	Brown Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "N of Layers" refers to number of separable subsamples.

Arthur Hernandez, Jr.
Analyst

Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negat guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product or nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

07-0913-570

007215



Ecology & Environment, Inc.
11550 Newcastle Ave. #250
Baton Rouge, LA 70816

Friday, May 23, 1997

Ref Number: TX971924

POLARIZED LIGHT MICROSCOPY (PLM)

Project: 020601RAG1 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS NONFIBROUS
WBS315G03	██████████ ROBINSON, MA	Brown Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other
WBS434G01	██████████ MA	Brown Fibrous Homogeneous	Teased	2% < 1%	Chrysotile Crocidolite		98% Other
WBS434G02	██████████ MA	Brown Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other
WBS451G01	██████████ MA	Brown Fibrous Homogeneous	Teased	3%	Chrysotile		97% Other
WBS451G02	██████████ MA	Brown/White Fibrous Homogeneous	Teased	4%	Chrysotile		96% Other
WBS913G04	██████████ MA	Brown Fibrous Homogeneous	Teased	2%	Chrysotile		98% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "N of Layers" refers to number of separable subsamples.

Arthur Hernandez, Jr.
Analyst

Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus we guarantee Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the fiber only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signal is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

07-0913-570

Westport, NJ 908-968-8890	Florahway, NJ 908-961-8888	Carle Place, NY 516-977-7251	Manhasset, NY 212-230-8882	Seattle, WA 206-223-8007	Ann Arbor, MI 313-465-4610	San Mateo, CA 415-878-4481	Smyrna, GA 404-232-8888	Grossbeck, NC 919-227-1487	Houston, TX 713-688-3835
------------------------------	-------------------------------	---------------------------------	-------------------------------	-----------------------------	-------------------------------	-------------------------------	----------------------------	-------------------------------	-----------------------------

EMSL

Ecology & Environment, Inc.
11550 Newcastle Ave. #250
Baton Rouge, LA 70816

Thursday, May 22, 1997


Ref Number: TX971907

POLARIZED LIGHT MICROSCOPY (PLM)

Project: 020601RAG1 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS			
				%	TYPE	%	FIBROUS	%	NONFIBROUS
WBS913G03	MA	Brown Non-Fibrous Homogeneous	Teased	2%	Chrysotile < 1% Crocidolite			98%	Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "N of Layers" refers to number of separable subsamples.



Carlos D. Salinas
Analyst

Approved
Signatory

07-0913-570

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative results are not guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items it only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product and nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature. EMSL is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

007217

Westwood, NJ	Manassas, NJ	Carle Place, NY	Manhattan, NY	Seattle, WA	Ann Arbor, MI	San Mateo, CA	San Jose, CA	Providence, RI	Boston, MA
609-652-4888	800-461-0888	516-897-7251	212-288-8832	206-222-0087	313-966-0210	415-870-5481	408-322-0888	910-397-1437	713-686-3645

EMSL

Ecology & Environment, Inc.
11550 Newcastle Ave. #250
Baton Rouge, LA 70816

Thursday, May 22, 1997


Ref Number: TX971907

POLARIZED LIGHT MICROSCOPY (PLM)

Project: 020601RAG1 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
WBB913PILE	MA PILE IN FR. YD.	Brown Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other
WBS752G01	MA	Brown Non-Fibrous Homogeneous	Teased	2%	Chrysotile < 1% Crocidolite		98% Other
WBS752G02	MA	Brown Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other
WBS752G03	MA	Brown Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other
WBS913G01	MA	Brown Non-Fibrous Heterogeneous	Teased	2%	Chrysotile < 1% Crocidolite		98% Other
WBS913G02	MA	Brown Non-Fibrous Homogeneous	Teased	2%	Chrysotile		98% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.



Carlos D. Salinas
Analyst

Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items as only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product end nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature. I is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

07-0913-570

007218




INTERNATIONAL
TECHNOLOGY
CORPORATION



By PM Date 5-20-97 Subject RESTORATION SITE 913 I Sheet No. _____ of _____

Chkd. By _____ Date _____ Proj. No. _____



07-0913-590

007219

WESTBANK ASBESTOS ABATEMENT NEW ORLEANS, LOUISIANA

RESTORATION FORM

SITE # 913 I

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)					(b) (4)		
Sod Installation (sq.yds.)							
6" Concrete Installation (sq. yds.)							
4" Concrete Installation (sq. yds.)							
Sand Installation (sq.yds.)							
Lower Lift Sand							
Rock, Brown (cu.yds.)							
Rock, Gray (cu.yds.)					(b) (4) (b) (4)		
Sand (cu.yds.)							
Concrete (cu.yds.)							
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

IT REPRESENTATIVE SIGNATURE

07-0913-590

SUB 1 SIGNATURE


SUB 2 SIGNATURE

007220



By PM Date 5-21-97 Subject RESTORATION SITE #913 I Sheet No. 1 of 3

Chkd. By _____ Date _____ Proj. No. _____



07-0913-590

WESTBANK ASBESTOS ABATEMENT NEW ORLEANS, LOUISIANA

RESTORATION FORM

SITE # 913 I

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)					(b) (4)		
Sod Installation (sq.yds.)							
6" Concrete Installation (sq. yds.)							
4" Concrete Installation (sq. yds.)							
Sand Installation (sq.yds.)							
Lower Lift Sand							
Rock, Brown (cu.yds.)							
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)							
Concrete (cu.yds.)							
Plastic Edging (fl.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS:

IT REPRESENTATIVE SIGNATURE

SUB 1 SIGNATURE

SUB 2 SIGNATURE

07-0913-590

007222




INTERNATIONAL
TECHNOLOGY
CORPORATION



By DM Date 5-22-97 Subject Restoration site # 913 II Sheet No. 2 of 3

Chkd. By _____ Date _____ Proj. No. _____



07-0913-590

007223

**WESTBANK ASBESTOS ABATEMENT
NEW ORLEANS, LOUISIANA**

RESTORATION FORM

SITE # 913 II

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)					(b) (4)		
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)							
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

IT REPRESENTATIVE SIGNATURE _____

SUB 1 SIGNATURE _____

SUB 2 SIGNATURE _____

07-0913-590


67224



INTERNATIONAL
TECHNOLOGY
CORPORATION



By PM Date 5-22-97 Subject RESTORATION SITE # 913 III Sheet No. 3 of 3
Chkd. By _____ Date _____ Proj. No. _____



07-0913-590

007225

WESTBANK ASBESTOS ABATEMENT NEW ORLEANS, LOUISIANA

RESTORATION FORM

SITE # 913 III

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)							
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)							
Sand Installation (sq.yds.)							
Lower Lift Sand							
Rock, Brown (cu.yds.)							
Rock, Gray (cu.yds.)							
Sand (cu.yds.)							
Concrete (cu.yds.)							
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS:

07-0913-590

IT REPRESENTATIVE SIGNATURE

SUB 1 SIGNATURE

SUB 2 SIGNATURE

007226

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/23/98
SITE #: 913

ADDRESS: [REDACTED]
Manero

ACM LOCATED BENEATH:

☐ HOUSE
☐ SHED

APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

☐ CHUNKS
☐ POWDER
☐ SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

<div data-bbox="289 1123 735 1575"><p>no ACM</p></div>	<div data-bbox="892 1081 1090 1165"><p>siding</p></div>

TEAM MEMBERS:

RL/JS

07-0913-540

007227

12/12 TCMC No one home - Reinvestigate
12/12 called for Rezanne could not
find ACM

Revisited/Investigated on 3/24 by
6 Day / K. Starling / S. Johnson.
No ACM found

Tracking Number 0914
No visible ACM

FIELD DATA SHEET 1


Site Information:

Occupant:	Interviewee:
Address: <u>[REDACTED]</u>	
Phone No.:	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>[REDACTED]</u> <u>[REDACTED]</u>	

Site Description:

1) Description of property (circle): single home; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____

Comments: TCMC 12/12 sketched part of property; couldn't see rest of yard.
No visible ACM MC 12/12/96

called 3/15/97 10/9 hours would like to re-investigate - TMM

Date/Time of Interview:

Access Granted (circle): yes; no NA

Team Members:

07-0914-510

007228

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE:

9/10/98

ADDRESS:

[REDACTED ADDRESS]

SITE #:

914

ACM LOCATED BENEATH:

☐ HOUSE
☐ SHED

APPR. CRAWL SPACE HEIGHT:


NA

DESCRIPTION OF ACM:

☐ CHUNKS
☐ POWDER
☐ SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:



concrete slab

TEAM MEMBERS:

DA/JW

07-0914-540

007229

FIELD DATA SHEET 1


Site Information:

Occupant: <u>[REDACTED]</u>	Interviewee: <u>SAME</u>
Address: <u>[REDACTED] WEST WEGO</u>	
Phone No. <u>[REDACTED]</u>	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>SAME</u>	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; <u>gate</u> ; <u>dogs</u> ; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): <u>yes</u> ; no; don't know If yes, note on site sketch. How deep? <u>6-10 INCHES</u>

Site Sketch:



(b) (6)

Estimated Volume of ACM: 450 ft³Comments: crushed limestone "whatever's cheap" ML 12/4/96

Date/Time of Interview: <u>12/4/96 1605</u>	Access Granted (circle): <u>yes</u> ; no
Team Members: <u>CMA / ML</u>	09-0915-510

007230

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]
Property's Address: [REDACTED]
State/Zip: 70094 Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

12/4/96
DATE

[REDACTED]
SIGNATURE

09-0915-520

TRACKING #

915


SITE SKETCH

ADDRESS:

[REDACTED] G. Westway

UPDATED:

1/1



NOTES:

N (NTS)

lots of yard junk

#	COVER	THICKNESS
①	Soil/Grass	No ACM
②	5"-6" Shell/Gravel/Soil covered ACM	

RESTORATION:

A: LIMESTONE

B:

C:

* OUT OF TOWN WEEK OF 7/21 - 7/28

09-0915-530

ARRIVAL: 1605

DEPARTURE: 1622

TW 7/16/97

RESTORATION APPROVED BY:

[REDACTED]

Via Phone @ 1315 DATE: 7/28/97

TEAM:

JB DM JD

DATE: 07/15/97

* TO IT 7/30/97 g.w

007232

WESTBANK ACM REMOVAL PROJECT
SAMPLE ANALYSIS CONFIRMATION
USEPA START TEAM

FYI:

SITE# 915

ADDRESS: [REDACTED]

Westwego, LA

THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON 8-19-97


BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

A. PROCEED WITH RESTORATION:

B. FURTHER ACTION NECESSARY:

GRID #:

1 2 3 4 5 6 7 8




Gridlined 8-18-97

8/18/97

DM (NTS)

Concrete
Edge ACM
Surface ACM

Grid Sample ID Depth Backfill
① WBS915 Cell 6" Limestone



09-0915-560

(b) (6)

AUTHORIZED EPA/START REPRESENTATIVE

Deena DePalma

007233

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
 Indianapolis, Indiana 46250
 Phone (317) 570-5892 Fax (317) 570-5894

EMSL

Attn: Maggie Lin
 Ecology & Environmental
 11500 New Castle Avenue
 Baton Rouge, LA 70816

Friday, August 22, 1997

Ref Number: IN97886

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: 020601 RAGI WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS % NONFIBROUS
WBS915G01		Brown Non-Fibrous Homogeneous	Crushed	2%	Chrysotile		80% Quartz 18% Other
				< 1%	Crocidolite		
WBS362G01		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
				< 1%	Crocidolite		
WBS362G02		Brown Non-Fibrous Homogeneous	Crushed		None Detected		80% Quartz 20% Other
WBS362G03		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
				< 1%	Crocidolite		

Comments: For obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "% of Layers" refers to number of separable subsamples.

* NY samples analyzed by ELAP 198-1 Method

Margaret Phillips
 Margaret Phillips
 Analyst

[Signature]
 Approved
 Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus, negative results are not guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the test performed. It may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product compliance with any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one statement that the laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200188-0).

09-0915-570

007234




INTERNATIONAL
TECHNOLOGY
CORPORATION



By PM Date 8-19-97 Subject RESTORATION SITE # 915 Sheet No. _____ of _____

Chkd. By _____ Date _____ Proj. No. _____



09-0915-590

007235

WESTBANK ASBESTOS ABATEMENT

NEW ORLEANS, LOUISIANA

RESTORATION FORM

SITE # 915

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)					(b) (4)		
Sod Installation (sq.yds.)							
6" Concrete Installation (sq. yds.)							
4" Concrete Installation (sq. yds.)							
Sand Installation (sq.yds.)							
Lower Lift Sand							
Rock, Brown (cu.yds.)							
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)							
Concrete (cu.yds.)							
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS:

IT REPRESENTATIVE SIGNATURE

07-0915-590

SUB 1 SIGNATURE

007236

SUB 2 SIGNATURE

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE:

9/16/99

SITE #:

915

ADDRESS:

Whitcomb

ACM LOCATED BENEATH:

☐ HOUSE
☐ SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

☐ CHUNKS
☐ POWDER
☐ SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	Debris

TEAM MEMBERS:

KS/B

09-0915-540

007237

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee:
Address: [REDACTED], MAYERO	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED]	

Site Description:

1) Description of property (circle): <u>single home</u> duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; <u>gate</u> dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; <u>don't know</u> If yes, note on site sketch. How deep? _____

Site Sketch:



(b) (6)

Estimated Volume of ACM: _____

Comments: backfill: dirt load

Date/Time of Interview: 12/6/96

Access Granted (circle): yes no see # 918

Team Members: CMA ML

07-0916-510

marked and revised 12/12/96
KJ/TN

Tracking Number 916

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee:
Address: [REDACTED] Marrero	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED]	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; <u>gate</u> ; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; <u>don't know</u> If yes, note on site sketch. How deep? _____

Site Sketch:



(b) (6) (b) (6) (b) (6)

Estimated Volume of ACM: 190 ft²

Comments: Backfill: soil & grass *pre-holiday removal approved

Date/Time of Interview: 12/9/96 Access Granted (circle): yes; no

Team Members: MH / ML

07-0916-510

007239

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee:
Address: [REDACTED]	MARRERO
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED]	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; <u>gate</u> ; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; <u>don't know</u> If yes, note on site sketch. How deep? _____

Site Sketch:



(b) (6)(b) (6)

Estimated Volume of ACM: 45 ft²Comments: Backfill: Soil/Salok for removal before ChristmasDate/Time of Interview: 12/4/96Access Granted (circle): yes noTeam Members: WNA / ML

07-0916-510

007240

9/8
9/16

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]
Property's Address: [REDACTED] EISEMAN
State/Zip: MASSACHUSETTS 02072 Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

Dec 5, 1996

DATE

[REDACTED]
SIGNATURE

RES. GLADES + DOROTHY

07-0916-520

[REDACTED] dirt + sod

[REDACTED] Sewage - limestone
[REDACTED] Walkway - concrete
[REDACTED] road - dirt / sod

#07241

**WESTBANK ACM REMOVAL PROJECT
SAMPLE ANALYSIS CONFIRMATION
USEPA START TEAM**

FYI:

SITE# 916

ADDRESS: [REDACTED]

Marrero, La. 70072


THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON 12-19-96.

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ☒

B. FURTHER ACTION NECESSARY: geo-liner needed
(see below)



AUTHORIZED EPA/START REPRESENTATIVE

007242

Barbara A. Storey

Westport, NJ 201-552-4500
 Pleasanton, NJ 908-961-3650
 Clark Place, NY 516-997-7251
 Manhattan, NY 212-286-0852
 Seattle, WA 206-225-9007
 Ann Arbor, MI 313-963-6616
 San Mateo, CA 415-576-4461
 Baytown, GA 404-333-6886
 Greensboro, NC 910-337-1487
 Houston, TX 713-686-3625







Ecology & Environment, Inc.
 11550 Newcastle Ave. #250
 Baton Rouge, LA 70816

Thursday, December 19, 1996


Ref Number: TX963288

POLARIZED LIGHT MICROSCOPY (PLM)

Project: 020601 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS % NONFIBROUS
WBS317GO3		Tan Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile Crocidolite		100% Other
WBS916GO1		Tan Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other
WBS330GO1		Tan Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other
WBS330GO2		Tan Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile Crocidolite		100% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately.
 Also, "N of Layers" refers to number of separable subsamples.


 Carlos D. Salinas
 Analyst

Approved
 Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. This negative guarantee. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items (a) only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endc nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature. It is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

07-0916-570

007243

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/2/98

ADDRESS: [REDACTED]

SITE #: 916

ACM LOCATED BENEATH:

☒ HOUSE
☐ SHED

APPR. CRAWL SPACE HEIGHT:

12"


DESCRIPTION OF ACM:

☐ CHUNKS
☐ POWDER
☒ SLAB

PERCENT OF AREA (ACM)

5%

SKETCH OR COMMENTS:



(b) (6)(b) (6)

appears to be a slab

TEAM MEMBERS:

DA/ML

07-0916-540

007244

Note: Please visit in AM

Tracking Number 917
(Ref. #666 + #667)
No Visible ACM

FIELD DATA SHEET 1

1-7-97 Owner home, but cannot
come out during wet weather.
Wait for sunny day.

Site Information:


Occupant: <u>Vacant</u>	Interviewee: <u>[Redacted] 24196</u>
Address: <u>[Redacted] Bridge City 70094</u>	
Phone No.: _____	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>[Redacted] - lives @ [Redacted]</u>	

Site Description:

1) Description of property (circle): single home; duplex; business; school; daycare; church; <u>vacant house</u> ; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; <u>don't know</u> If yes, note on site sketch. How deep? _____

Site Sketch:

(x x x - fence posts, no mesh)



Estimated Volume of ACM: _____

Comments: No Visible ACM

Date/Time of Interview: <u>1/15/97 1400</u>	Access Granted (circle): <u>yes</u> ; no
Team Members: <u>LT/RW</u>	<u>04-0917-510</u>

007245

Owner's presence
required. (305 West)

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 8/11/98
SITE #: 0917

ADDRESS: [REDACTED]
Bridge City, LA

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	_____

TEAM MEMBERS:

GD/JS

04-0917-540

007246

FIELD DATA SHEET 1


Site Information:

Occupant: [redacted] (renter)	Interviewee: [redacted] (owner)
Address: [redacted] Marrero, LA 70072	
Phone No.: [redacted]	
Owner Name, Address, and Phone No. if Different Than Occupant: [redacted] [redacted] at corner of [redacted] (lives in back)	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other <u>None</u> resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): <u>yes</u> ; no; don't know If yes, note on site sketch. How deep? <u>In servitude</u>

Site Sketch:



Estimated Volume of ACM: _____

Comments: Owner wants concrete walkway without circle if material is ACM (need to collect sample)
- rock in servitude

Date/Time of Interview: 12/5/96 12/6/96

Access Granted (circle): yes; no

Team Members: TMV ML/MM

07-0918-510

007247

Tracking Number 918

REVISED 12/6/96

FIELD DATA SHEET 1

Site Information:

Occupant: [REDACTED]	Interviewee: [REDACTED]
Address: [REDACTED]	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED] [REDACTED]	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other <u>NONE</u> resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): <u>yes</u> ; no; don't know If yes, note on site sketch. How deep? <u>SERVITUDE</u>

Site Sketch:

(b) (6)(b) (6)

Estimated Volume of ACM: _____

Comments: ACM IN SERVITUDE CHASED FROM [REDACTED]
LIMESTONE IN SERVITUDE WALK-CONCRETE YARD-DIRT & SOD

Date/Time of Interview: 12/6/94 Access Granted (circle): yes noTeam Members: mr/mt 07-0918-510

007248

9/8
9/16

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]
Property's Address: [REDACTED]
State/Zip: WATER 70072 Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

Dec 5, 1996

DATE

[REDACTED]
SIGNATURE

07-0918-520

RES. GLADYS + DOROTHY

[REDACTED] dirt + sod

[REDACTED] servaytwell - limestone

[REDACTED] Walkway - concrete

[REDACTED] yard - dirt/sod

0707249

Site 918

Site Sketch

608 Eiseman - Marrero

4/8/97

1100 1/30


Team CC/MT/ML

~~ZZ~~Alton LeBont - owner
Mike Rankins - resident

No. 5505

Engineer's Computation Pad

ADVN

Owner Approves Restoration: *Alton LeBont*

Note: low power lines over drive
water meter in removal area
storm sewer in removal area

Restoration

- (A) Crush stone
- (B) ~~set back~~ Crushed Stone
- (C) concrete walkway - w/b circle

- ① surface ACm walk 4" thick
- ② 2" grass cover 2" ACm
- ③ grass no ACm
- ④ [1" crushed stone 2" soil] 3" ACm

07-0918-530

007250 DM 4/11/97

WESTBANK ACM REMOVAL PROJECT
SAMPLE ANALYSIS CONFIRMATION
USEPA START TEAM

FYI:

SITE# 918

ADDRESS: [REDACTED]
Marrero


THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON _____.

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ☒ ☒

B. FURTHER ACTION NECESSARY: ☐ ☐




• visible ACM highlighted below: (1) and (2)
• outlined 05-02-97

NTS

← N all
05-02-97

Grid	Sample ID	Depth	Backfill / Area
①	WBS918G01	12"	limestone / semitide
②	WBS918G02	6"	concrete / walkway



0072

(b) (6) (b) (6)

07-0918-560

AUTHORIZED EPA/START REPRESENTATIVE

Amante Loane

Westland, MI	Plattsburgh, NY	Carle Place, NY	Westchester, NY	Seattle, WA	Ann Arbor, MI	San Mateo, CA	Baytown, TX	Cumtong, NC	Houston, TX
909-858-6509	508-881-8550	516-897-7251	212-270-0952	206-233-8007	313-969-0810	415-879-6481	281-333-0900	919-897-1457	713-686-3635

EMSL

Ecology & Environment, Inc.
11550 Newcastle Ave. #250
Baton Rouge, LA 70816

Tuesday, May 06, 1997

Ref Number: TX971567

POLARIZED LIGHT MICROSCOPY (PLM)

Project: 020601RAG1 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
WBS918G01	AR-51? EISEMAN, MA	Tan Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other
WBS918G02	AR-51? EISEMAN, MA	Tan Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other
WBS833G05	BLVD, MA	Tan Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other
WBS833G06	BLVD, MA	Tan Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other
WBS833G07	BLVD, MA	Tan Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other
WBS833G08	BLVD, MA	Tan Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.



Carlos D. Salinas
Analyst

Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negat guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product or nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

07-0918-570

007252

Westwood, NJ 020-422-0700
 Florham Park, NJ 096-261-0200
 Great Plains, NY 010-497-7701
 Manhattan, NY 212-530-0000
 Seattle, WA 206-430-0007
 San Arter, ME 215-000-0000
 San Diego, CA 619-490-4001
 Sayreville, NJ 908-325-0000
 Greenville, NC 919-497-1077
 Houston, TX 713-686-0000

EMSL

Ecology & Environment, Inc.
 11550 Newcastle Ave. #250
 Baton Rouge, LA 70816

Wednesday, April 16, 1997

Ref Number: TX971263

POLARIZED LIGHT MICROSCOPY (PLM)

Project: 020601RAGI WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
WB5547005	WE, MA	Grey Non-Fibrous Homogeneous	Teased	4%	Chrysotile		96% Other
WB5554G01	MA	Tan Non-Fibrous Homogeneous	Teased		None Detected		100% Other
WB5554G02	MA	Grey Non-Fibrous Homogeneous	Teased		None Detected		100% Other
WB5554G03	MA	Grey Non-Fibrous Homogeneous	Teased		None Detected		100% Other
WB5550G01	ROCKDALE, MA	Tan Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other
WB5551G01 WB5551G01	ROCKMAN, MA	Grey Fibrous Homogeneous	Teased	35%	Chrysotile		65% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately.
 Also, "# of Layers" refers to number of separable subsamples.



Carlos D. Salinas
 Analyst

Approved
 Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus, negative results are not guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items listed and only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product or nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

07-0918-570


007253



INTERNATIONAL
TECHNOLOGY
CORPORATION



By PM Date 5-5-97 Subject Restoration site # 918 Sheet No. of
Chkd. By Date Proj. No.



07-0918-590

007254

**WESTBANK ASBESTOS ABATEMENT
NEW ORLEANS, LOUISIANA**

RESTORATION FORM

SITE # 918

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)					(b) (4)		
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)					(b) (4)		
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

IT REPRESENTATIVE SIGNATURE

07-0918-590

SUB 1 SIGNATURE

SUB 2 SIGNATURE

007255

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/2/98

ADDRESS: [REDACTED], MA

SITE #: 918

ACM LOCATED BENEATH:

☐ HOUSE
☐ SHED

APPR. CRAWL SPACE HEIGHT:

12"

DESCRIPTION OF ACM:

☐ CHUNKS
☐ POWDER
☐ SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

<p><i>NO ACM</i></p> <p><i>Demolition</i></p>	

TEAM MEMBERS: DA/ML

07-0918-540

007256

School teacher
Be home
late afternoon
4:30 or 05:00 PM

Tracking Number 919

★ DID NOT FIND ANY ACM 6/2/97
FIELD DATA SHEET 1
NO VISIBLE ACM


Site Information:

Occupant: [REDACTED]	Interviewee: [REDACTED]
Address: [REDACTED] <u>Marroco, LA</u>	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>Same</u>	

Site Description:

- 1) Description of property (circle): single home; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
- 2) Problems accessing yards (circle): locked gate; gate; dogs; other _____
resolution: _____
- 3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____
Note location on site sketch.
- 4) Is any underground ACM present? (circle): yes; no; don't know
If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____

Comments: Wants property investigated for ACM.

No Visible ACM

Date/Time of Interview: 5/16/97 1420 hrs

Access Granted (circle): yes; no

Team Members: TV via phone

07-0919-510

5/20/97 1767 Not home M/LAR

007257

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 8/17/98
SITE #: 919

ADDRESS: [REDACTED]
Harvero

ACM LOCATED BENEATH:

	HOUSE
	SHED

APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

	CHUNKS
	POWDER
	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

<i>No ACM</i>	

TEAM MEMBERS: MTL/ASB

07-0919-540

007258

FIELD DATA SHEET 1


Site Information:

Occupant: <u>[REDACTED]</u>	Interviewee: _____
Address: <u>[REDACTED] Marrero</u>	
Phone No.: _____	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>son of [REDACTED] Mr. [REDACTED]</u>	

Site Description:

1) Description of property (circle): single home; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



(b) (6)

Estimated Volume of ACM: _____

Comments: *No visible ACM*

Date/Time of Interview: *11/12 10:20*

Access Granted (circle): yes; no *NA*

Team Members: *TC/ml*

07-0920-510

007259

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE:

8/10/98

ADDRESS:

[REDACTED]
Marrero

SITE #:

920

ACM LOCATED BENEATH:

HOUSE
SHED

APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

CHUNKS
POWDER
SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

No ACM	

TEAM MEMBERS:

MTL/ASB

07-0920-540

007260

Tracking Number 921

FIELD DATA SHEET 1

NVA

Site Information:

Occupant: <u>VACANT LOT</u>	Interviewee:
Address: <u>[REDACTED]</u> <u>WESTWEGO</u> (<u>BETWEEN</u>) <u>[REDACTED]</u>	
Phone No.: <u>[REDACTED]</u> <u>[REDACTED]</u> <u>PAGER</u>	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>[REDACTED]</u> , <u>AVONDALE</u>	

Site Description:

1) Description of property (circle): single home; duplex; business; school; daycare; church; vacant house; <u>vacant lot</u> ; other _____
2) Problems accessing yards (circle): locked gate; <u>gate</u> ; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:

Site Sketch:

(b) (6) (b) (6) (b) (6) (b) (6)

Estimated Volume of ACM: _____

Comments:

Date/Time of Interview: 12/19/96 1415 Access Granted (circle): yes; noTeam Members: ML / BS **09-0921-510**

007261

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE:

9/17/98

SITE #:

921

ADDRESS:

Westwego

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED

APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

NO ACM	_____

TEAM MEMBERS:

KJ TS

09-0921-540

007262

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee: [REDACTED]
Address: [REDACTED] ST WESTWEGO 70094	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED]	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; <u>gate</u> ; <u>dogs</u> ; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; <u>don't know</u> If yes, note on site sketch. How deep? _____

Site Sketch:



(b) (6)(b) (6)

Estimated Volume of ACM: <u>300 ft²</u>	
Comments: BACKFILL - CONCRETE UNDER SHED 12/6 LEFT ACCESS	
Date/Time of Interview: <u>12/6/96 1620</u>	Access Granted (circle): yes; no
Team Members: <u>CMA/ML</u> <u>007263</u> <u>09-0922-510</u>	

922

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]

Property's Address: [REDACTED]

State/Zip: LA 70094

Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

Dec. 6, 1996
DATE

[REDACTED]
SIGNATURE

09-0922-520

007264

TRACKING #

922


SITE SKETCH

ADDRESS:

[REDACTED] Westwego

UPDATED:

1/1



owner will
remove shed
replace w/concrete
pad 10'x15' or
equivalent size
to SACM.

(b) (6)

(b) (6)
(b) (6)
(b) (6)

NOTES:

N (NTS)
↓

SACM = 2x4 + 2x10 + 3x10
ACM also makes up entire floor
of Shed - All exposed

#	COVER	THICKNESS
1	GRASS - N/A	No ACM
2	GRASS - 3"	> 1"
3	Soil/Shell	3" > 1"
4	" "	NO ACM

RESTORATION: A: Lime/stone
B: Soil/SOD
C: Concrete

ARRIVAL: 0800

DEPARTURE: 0340

RESTORATION APPROVED BY:

[REDACTED]

(phone)

DATE: 8/12/97

TEAM: GD/PL

DATE: 08265, 97

WET 8/12/97

el.

09-0922-530

WESTBANK ACM REMOVAL PROJECT SAMPLE ANALYSIS CONFIRMATION USEPA START TEAM

FYI:

SITE# 922

ADDRESS: [REDACTED]

Westwego, LA

THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON No analytical results received as of 09.05.97


BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ☒ ☒ ☒ ☐ ☐ ☐ ☐ ☐

B. FURTHER ACTION NECESSARY: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐

• Geolined 09.05.97



(b) (6)(b) (6)(b) (6)(b) (6)

09-0922-560

AUTHORIZED EPA/START REPRESENTATIVE

007264
[Signature]

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152

Indianapolis, Indiana 46250

Phone (317) 570-5892 Fax (317) 570-5894

EMSL

Attn.: Alma Rillera

Ecology & Environmental

11550 New Castle Avenue

Baton Rouge, LA 70816

Tuesday, September 09, 1997

Ref Number: IN971031

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 800/R-83/116 Method*

Project: 020601 RAGI WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		%	NONASBESTOS	
				%	TYPE		FIBROUS	% NONFIBROUS
WBS1162G01		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile			40% Quartz
				< 1%	Crocidolite			60% Other
WBS933G01		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile			80% Quartz
				< 1%	Crocidolite			20% Other
WBS933G02		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile			80% Quartz
								20% Other
WBS922G01		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile			80% Quartz
								20% Other
WBS922G02	MA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile			80% Quartz
								20% Other
WBS922G03	MA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile			80% Quartz
				< 1%	Crocidolite			20% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "N of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 168-1 Method

Jane Wasilewski
Analyst

Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. This report may only be reproduced in full with written approval by EMSL. The above test report relates only to the data reported herein and may not be reproduced in full without written approval by EMSL. The above test must not be used by the client to claim product liability or any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature of a laboratory representative for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200168-0).

09-0922-570

007267

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
 Indianapolis, Indiana 46250
 Phone (317) 570-5892 Fax (317) 570-5894

EMSL

Attn.: Alma Rillera
 Ecology & Environmental
 11550 New Castle Avenue
 Baton Rouge, LA 70816

Tuesday, September 09, 1997

Ref Number: IN971031

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 800/R-93/116 Method*

Project: 020601 RAGI WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	NONFIBROUS
WBS1182G01		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		40% Quartz 60% Other
WBS933G01		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
WBS933G02		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
WBS922G01		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
WBS922G02		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
WBS922G03		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "W of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

Jane Wasilewski
 Analyst

Approved
 Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negall be guaranteed. Floor tiles and wipaa should be tested with either SEM or TEM. The above test report relates only to the As may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim prod. NVLAP for any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered sample. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200188-0).

09-0922-570

007268

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
Indianapolis, Indiana 46250
Phone (317) 570-5892 Fax (317) 570-5894

EMSL

Attn.: Alma Rillera
Ecology & Environmental
11550 New Castle Avenue
Baton Rouge, LA 70816

Tuesday, September 09, 1997

Ref Number: IN971031

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 800/R-93/116 Method*

Project: 020601 RAQI WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		%	NONASBESTOS	
				%	TYPE		FIBROUS	% NONFIBROUS
WBS1182G01		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile			40% Quartz 60% Other
WBS933G01		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile			80% Quartz 20% Other
WBS933G02		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile			80% Quartz 20% Other
WBS922G01		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile			80% Quartz 20% Other
WBS922G02	MA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile			80% Quartz 20% Other
WBS922G03	MA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile			80% Quartz 20% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 188-1 Method

Jane Wasilewski
Analyst

Approved
Signatory

09-0922-570

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative results are not guaranteed. Floor tiles and wipe samples should be tested with either SEM or TEM. The above test report relates only to the items analyzed and reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product compliance for any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one sign. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk 6200188-0).


007269



INTERNATIONAL
TECHNOLOGY
CORPORATION



By PM Date 9-8-97 Subject RESTORATION SITE # 922 Sheet No. of
Chkd. By Date Proj. No.



09-0922-590

007270

SITE # 922

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)					(b) (4)		
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)					(b) (4)		
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

IT REPRESENTATIVE SIGNATURE _____
SUB 1 SIGNATURE _____
SUB 2 SIGNATURE _____
007271

09-0922-590

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/22/98
SITE #: 922

ADDRESS: [REDACTED]
Westwego

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	<u>Siding</u>

TEAM MEMBERS: RL/TS

09-0922-540

007272

* Coordinate w/
owner - owner
wants to move shed

FIELD DATA SHEET 1

Site Information:

Occupant: [REDACTED]	Interviewee: CLARA
Address: [REDACTED], Westwego	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: SAME	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; <u>gate</u> ; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; <u>don't know</u> If yes, note on site sketch. How deep? _____

Site Sketch:

Estimated Volume of ACM: _____

Comments: BACKFILL: CONCRETE / Coordinate w/ owner about shed removal
12/6 LEFT ACCESS-

Date/Time of Interview: 12/6/96 1:30

Access Granted (circle): yes no

Team Members: CWA/ML

09-0923-510

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]
Property's Address: [REDACTED] *Wadswego*
State/Zip: *La 90094* Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

12/19/96
DATE

[REDACTED]
SIGNATURE


09-0923-520

TRACKING # 923

SITE SKETCH

ADDRESS: [REDACTED]

UPDATED: 1/1



NOTES:

N (NTS)



All 11' is covered in asphalt. 11' is 11' for asphalt. 11' is 11' for asphalt.

RESTORATION: A: grass
B:
C:

ARRIVAL:
DEPARTURE:

TEAM: TT / DA

RESTORATION APPROVED BY: [REDACTED]

DATE: 1/17/97

007275

#	COVER	THICKNESS
1.	Soil/SOD 6"	
2	Gravel	
3	Soil/SOD 3"	3" New
4		4" SOD


09-0923-530

Via Phone @ 1145

DATE: 7/29/97

@ To IT 7/30/97

910



EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
Indianapolis, Indiana 46250
Phone (317) 570-5892 Fax (317) 570-5894

EMSL

Attn.: Alma Rillera
Ecology & Environmental
11550 New Castle Avenue
Baton Rouge, LA 70816

Monday, September 08, 1997

Ref Number: IN971018

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 800/R-93/116 Method*

Project: WESTBANK ASBESTOS 020601RAG1

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	NONFIBROUS
WBS923G01	[REDACTED] AVE, WE	Brown Non-Fibrous Homogeneous	Crushed		None Detected		80% Quartz 20% Other
WBS683G01	[REDACTED] WE	Brown Non-Fibrous Homogeneous	Crushed		< 1% Chrysotile		80% Quartz 20% Other
WBS732G01	[REDACTED] WATERMATE, HA	Brown Non-Fibrous Homogeneous	Crushed		< 1% Chrysotile < 1% Crocidolite		40% Quartz 60% Other
WBS732G02	[REDACTED] WATERMATE, HA	Brown Non-Fibrous Homogeneous	Crushed		< 1% Chrysotile		40% Quartz 60% Other
WBS732G03	[REDACTED] WATERMATE, HA	Brown Non-Fibrous Homogeneous	Crushed		< 1% Chrysotile < 1% Crocidolite		40% Quartz 60% Other
WBS1008G01	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed		< 1% Chrysotile < 1% Crocidolite		40% Quartz 60% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "% of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

Jane Wasilewski
Analyst

Approved
Signatory

Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus report may not be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the data may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim production of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200188-0).

09-0923-570

007277




INTERNATIONAL
TECHNOLOGY
CORPORATION



By PM Date 9-5-97 Subject RESTORATION SITE # 923 Sheet No. _____ of _____

Chkd. By _____ Date _____ Proj. No. _____



09-0923-590

052500

007278

WESTBANK ASBESTOS ABATEMENT
NEW ORLEANS, LOUISIANA

RESTORATION FORM

 SITE # 923

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)							
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)							
4" Concrete Installation (sq. yds.)							
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand							
Rock, Brown (cu.yds.)							
Rock, Gray (cu.yds.)							
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)							
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

IT REPRESENTATIVE SIGNATURE

09-0923-590

SUB 1 SIGNATURE

007279

SUB 2 SIGNATURE

872798

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 7/30/98
SITE #: 0923

ADDRESS: [REDACTED]
Westwego, LA

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	_____

TEAM MEMBERS:

AL/DA

09-0923-540

007280

FIELD DATA SHEET 1


Site Information:

Occupant: <u>VACANT LOT</u>	Interviewee: [REDACTED]
Address: [REDACTED] <u>MARBERO</u>	
Phone No.: <u>(behind)</u> [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED] <u>marbero</u> [REDACTED]	

Site Description:

1) Description of property (circle): single home; duplex; business; school; daycare; church; vacant house; <u>vacant lot</u> ; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other <u>none</u> resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): <u>yes</u> ; no; don't know If yes, note on site sketch. How deep? <u>under grass</u>

Site Sketch:

Estimated Volume of ACM: 72 ft²Comments: backfill: dirtDate/Time of Interview: 12/6/94 1255Access Granted (circle): yes; noTeam Members: ML/MT

07-0924-510

007281

317
→ 924 this page

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]

Property's Address: [REDACTED] MARREPO

State/Zip: LD. 70072 Phone Number(s): [REDACTED]

lots [REDACTED] *behind [REDACTED] on ROBINSON*
I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

Dec 6-94
DATE

[REDACTED]
SIGNATURE

07-0924-520

007282

Site 924


SITE SKETCH

[REDACTED] - Merrero

SITE 924

4/8/97

[REDACTED]




[REDACTED]
vacant lot behind
on Robinson street
Merrero LA

No. 5505
Engineer's Computation Pad



Forwarded to IT SOURCE on 4/14/97

Vacant
house
ACM removed
and restored



Restoration: (A) soil/sod

4/10/97 1435 hrs - called left message with co-worker. - Tm

4/11/97 1025 hrs - called again - his secretary confirm soil/sod; however, she will tell him to call and confirm - Tm

Restoration Plan accepted

4/15/97 1355 CAC

07-0924-530

007283

DM
4/14/97

WESTBANK ACM REMOVAL PROJECT
SAMPLE ANALYSIS CONFIRMATION
USEPA START TEAM

FYI:

SITE# 924

ADDRESS: [REDACTED] (on Robinson)
Marrero, LA

THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON 5-19-97.

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:


GRID #: 1 2 3 5 6 7 8

A. PROCEED WITH RESTORATION: ☒ ☒ ☒ ☐ ☐ ☐ ☐ ☐

B. FURTHER ACTION NECESSARY: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐

- Visible ACM highlighted below: (E)
- Creolined 05-15-97

Grid Sample ID depth Backfill Area
① WBS924601 6"-8" sod/soil vacant lot
② WBS924602 6"-8" sod/soil vacant lot
③ WBS924603 6"-8" sod/soil vacant lot



07-0924-560

AUTHORIZED EPA/START REPRESENTATIVE

007284

Lawrence Reed

Westport, NJ
201-992-0900Parsippany, NJ
908-861-0800Cedar Park, TX
817-407-7231Houston, TX
281-260-0800Seattle, WA
206-222-0007Ann Arbor, MI
313-995-0010San Mateo, CA
415-870-6400Cupertino, CA
408-996-0000Overland Park, KS
913-607-1407Houston, TX
713-680-0800

Ecology & Environment, Inc.
11550 Newcastle Ave. #250
Baton Rouge, LA 70816

Monday, May 19, 1997

Ref Number: TX971817

EMSL

POLARIZED LIGHT MICROSCOPY (PLM)

Project: 020601RAG1 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS % NONFIBROUS
WBS428G01	MA	Brown Fibrous Homogeneous	Teased	2%	Chrysotile		98% Other
WBS1007G01	MA	Brown Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other
WBS1007G02	MA	Brown Non-Fibrous Homogeneous	Teased		None Detected		100% Other
WBS1007G03	MA	Brown Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other
WBS924G01	ROBINSON, MA	Brown Non-Fibrous Homogeneous	Teased		None Detected		100% Other
WBS924G02	ROBINSON, MA	Brown Non-Fibrous Homogeneous	Teased		None Detected		100% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

Arthur Hernandez, Jr.
Analyst

Approved
Signatory

07-0924-570

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus, negative results are not guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items only be reproduced in full with written approval by EMSL. The above test must not be used by any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

007285

Westport, NJ 202-422-4000
 Flemington, NJ 609-661-0000
 Carlo Place, NY 516-897-7351
 Manhattan, NY 212-200-0000
 Seattle, WA 206-223-0007
 Ann Arbor, MI 313-285-0010
 San Mateo, CA 415-375-0001
 Boston, MA 617-267-0000
 Greensboro, NC 336-287-3407
 Houston, TX 713-666-0000

Ecology & Environment, Inc.
 11550 Newcastle Ave. #250
 Baton Rouge, LA 70816

Monday, May 19, 1997

Ref Number: TX971817

EMSL

POLARIZED LIGHT MICROSCOPY (PLM)

Project: 020601RAG1 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		MONASBESTOS	
				%	TYPE	%	FIBROUS % NONFIBROUS
WBS924G03	ROBINSON, MA	Brown Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "N of Layers" refers to number of separable subsamples.

Arthur Hernandez, Jr.
 Analyst

Approved
 Signatory

Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative guaranteed. Floor tiles and ceiling should be tested with either SEM or TEM. This above test report relates only to the items for only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product ends nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature it is not responsible for the accuracy of results when requested to physically separate and analyze targeted samples.

07-0924-570


007286



INTERNATIONAL
TECHNOLOGY
CORPORATION



By PM Date 5-16-97 Subject Restoration site # 924 Sheet No. of
Chkd. By Date Proj. No.



07-0924-590

007282
36-100

**WESTBANK ASBESTOS ABATEMENT
NEW ORLEANS, LOUISIANA**

RESTORATION FORM

SITE # 924

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)							
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)					(b) (4)		
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

07-0924-590

IT REPRESENTATIVE SIGNATURE _____

SUB 1 SIGNATURE _____

SUB 2 SIGNATURE _____

007288

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9-21-98

ADDRESS: [REDACTED]
MARKERO 4TH ST.

SITE #: 0924

ACM LOCATED BENEATH:

<input checked="checked" type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED

APPR. CRAWL SPACE HEIGHT:


DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

0%

SKETCH OR COMMENTS:

	_____

07-0924-540

TEAM MEMBERS:

J.Y. & A.T.

007289
[Signature]

Tracking Number 925

No visible ACM

FIELD DATA SHEET 1


Site Information:

Occupant:	Interviewee:
Address: <u>[REDACTED] Bridge City</u>	
Phone No.: <u>[REDACTED]</u>	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>[REDACTED] - daughter</u>	

Site Description:

1) Description of property (circle): single home; <u>duplex</u> ; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; <u>gate</u> ; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other <u>N/A</u> Note location on site sketch.
4) Is any underground ACM present? (circle): yes; <u>no</u> ; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____

Comments:

No visible ACM

Date/Time of Interview:

12/13/96 17:10

Access Granted (circle):

yes; no

(N/A)

Team Members:

Rhodes/ Cochell

04-0925-510

007290

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 8/1/98
SITE #: 0925

ADDRESS: [REDACTED]
Bridge City

ACM LOCATED BENEATH:

☐ HOUSE
☐ SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

☐ CHUNKS
☐ POWDER
☐ SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	_____

TEAM MEMBERS:

JS/JS

04-0925-540

007291

Tracking Number 926

NO visible ACM

FIELD DATA SHEET 1

Site Information:

Occupant: <u>VACANT lot</u>	Interviewee:
Address: <u>[REDACTED] (NW corner), Gresham</u>	
Phone No.: _____	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>call [REDACTED] if no ACM</u> <u>Executrix</u>	

Site Description:

1) Description of property (circle): single home; duplex; business; school; daycare; church; vacant house; <u>vacant lot</u> ; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:

The sketch shows a rectangular lot. At the top is a rectangle labeled 'House'. On the left side is a smaller rectangle labeled 'Dixie Beer'. In the center of the lot is the text 'VACANT LOT'. On the right side, there is a north arrow pointing upwards, labeled 'N'. The lot is bounded by a line on the bottom and a line on the right.

Estimated Volume of ACM: _____

Comments: NO VISIBLE ACMDate/Time of Interview: 12/10 14:00Access Granted (circle): yes; noTeam Members: TC/ML

05-0926-510

007292

926

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: ESTATE OF [REDACTED]
Property's Address: VACANT LOT CORNER [REDACTED]
State/Zip: 70053 Phone Number(s): [REDACTED]

GRETN
LA.

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

12/7/96
DATE
*wants to know
call: if you give a letter if
you do not find
anything*
[REDACTED]
Marrero, Louisiana 70072
007293

[REDACTED]
SIGNATURE

[REDACTED]
EXECUTRIX

05-0926-520

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/22/98

ADDRESS: [REDACTED]

SITE #: 0926

Newton
Gretna

ACM LOCATED BENEATH:

	HOUSE
	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

	CHUNKS
	POWDER
	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	<u>vacant lot</u>

TEAM MEMBERS:

JS & EW

05-0926-540

007294

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee: [REDACTED]
Address: [REDACTED], Gretna	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED] lives upstairs	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; <u>business</u> ; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): <u>locked gate</u> ; gate; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): <u>yes</u> ; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:

Estimated Volume of ACM: 2250 ft³

Comments: [REDACTED] lives upstairs. Driveway runs along business

Prefers concrete for driveway but will take limestone

Date/Time of Interview: 12/11 10:15Access Granted (circle): yes noTeam Members: TC/ml

05-0927-510

927

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: _____
Property's Address: _____
State/Zip: LA, 70053 Phone Number(s): _____

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.


This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

12/15/86
DATE


[Signature]
SIGNATURE

05-0927-520

007296



NOTES:



OWNER REQUESTS CONCRETE BERM REMOVED
IN GATE AREA. SACM VISIBLE IN RIVER
RIGHT-OF-WAY AND ADJACENT PROPERTY
TO EAST. OWNER DOES NOT WANT AREA #3

RESTORATION:

- A: DISTURBED
B: CONCRETE DRIVEWAY (143 x 17)
C:

ARRIVAL: 1235

DEPARTURE: 1400

RESTORATION APPROVED BY:

TEAM: MW/SD/SB

DATE:

007297

#	COVER	THICKNESS
①	2" GRASS	ACM 3'
②	0.5" GRASS	ACM 4'
③	1-2" GRASS/WASHOUT CONCRETE	ACM/CEMENT MIX 2'

05-0927-530

DATE: 6/21/97

To #7 6/21

WESTBANK ACM REMOVAL PROJECT SAMPLE ANALYSIS CONFIRMATION USEPA START TEAM

FYI:

SITE# 927

ADDRESS: [REDACTED]
Gueta, LA

THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON No analytical results received as of 07.11.97

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:


GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ✓ ✓ ✓ ✓ — — — —

B. FURTHER ACTION NECESSARY: — — — — — — — —

- Visible ACM highlighted below: (I) and (III)
- Geolined 7/11/97

Grid	Sample ID	Depth	Area
①	W85927601	6" concrete	driveway
②	W85927602	6" concrete	driveway
③	W85927603	6" concrete	driveway
④	W85927604	6" concrete	driveway



05-0927-560

1st St.
007298

AUTHORIZED EPA/START REPRESENTATIVE

Lawrence R. [Signature]

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
 Indianapolis, Indiana 46250
 Phone (317) 570-5892 Fax (317) 570-5894

EMSL

Attn.: Larry Roedl
 Ecology & Environmental
 11550 New Castle Avenue
 Baton Rouge, LA 70816

Tuesday, July 15, 1997

Ref Number: IN97471

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: 020601 RAG1 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS % NONFIBROUS
WBS1052G03	██████████ RIVE, MA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
WBS560G01	██████████ ETER, GR	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
WBS235G01	██████████ TUCCI, MA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
WBS235G02	██████████ TUCCI, MA	Brown Non-Fibrous Homogeneous	Crushed	< 1% < 1%	Chrysotile Crocidolite		80% Quartz 20% Other
WBS235G03	██████████ TUCCI, MA	Brown Non-Fibrous Homogeneous	Crushed	< 1% < 1%	Chrysotile Crocidolite		80% Quartz 20% Other
WBS927G01	██████████	Brown Non-Fibrous Homogeneous	Crushed	2% 1%	Chrysotile Crocidolite		80% Quartz 17% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "% of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method


 Jane Wasilewski
 Analyst


 Approved
 Signatory

Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the item may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one sig Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200188-0).

05-0927-570

007299

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
 Indianapolis, Indiana 46250
 Phone (317) 570-5892 Fax (317) 570-5894

EMSL

Attn.: Larry Roedl
 Ecology & Environmental
 11550 New Castle Avenue
 Baton Rouge, LA 70816

Tuesday, July 15, 1997

Ref Number: IN97471

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: 020601 RAG1 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS % NONFIBROUS
WBS927G02		Brown Non-Fibrous Homogeneous	Crushed	2%	Chrysotile < 1% Crocidolite		80% Quartz 18% Other
WBS927G03		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile < 1% Crocidolite		80% Quartz 20% Other
WBS927G04	GR	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "% of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method


 Jane Wasilewski
 Analyst


 Approved
 Signatory

Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative results are not guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the item analyzed. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product compliance with any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature of a qualified analyst. EMSL Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200188-0).


05-0927-570

007300



INTERNATIONAL
TECHNOLOGY
CORPORATION

By PM Date 7-12-97 Subject RESTORATION site # 927 Sheet No. _____ of _____
Chkd. By _____ Date _____ Proj. No. _____



05-0927-590

0073013

WESTBANK ASBESTOS ABATEMENT NEW ORLEANS, LOUISIANA

RESTORATION FORM

SITE # 927

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)					(b) (4)		
Sod Installation (sq.yds.)							
6" Concrete Installation (sq. yds.)							
4" Concrete Installation (sq. yds.)							
Sand Installation (sq.yds.)							
Lower Lift Sand							
Rock, Brown (cu.yds.)							
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)							
Concrete (cu.yds.)							
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

05-0927-590

IT REPRESENTATIVE SIGNATURE _____

SUB 1 SIGNATURE _____

SUB 2 SIGNATURE _____

007342

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 8/28/98
SITE #: 927

ADDRESS: [REDACTED]
Gretz

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	<u>No Crawl Space</u>

TEAM MEMBERS: MJL / PHL

05-0927-540

007303

FIELD DATA SHEET 1

No visible ACM


Site Information:

Occupant:	Interviewee:
Address: [REDACTED]	MARRER O
Phone No.:	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED] 1129	

Site Description:

1) Description of property (circle): single home; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____

Comments: No visible ACM

Date/Time of Interview: 12/10 15:50

Access Granted (circle): (yes) no

Team Members: TC/ML

07-0928-510

007304

TRACKING # ~~100~~
928 409
606 12/8

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

MAILING ADDRESS

Property Owner's Name: [REDACTED]
Property's Address: [REDACTED] MARRETO
State/Zip: LA 70072 Phone Number(s): [REDACTED]


I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

9-3-96
DATE



SIGNATURE [REDACTED]

07-0928-520

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/8/98
SITE #: 928

ADDRESS: [REDACTED] MA

ACM LOCATED BENEATH:

☐ HOUSE
☐ SHED

APPR. CRAWL SPACE HEIGHT:

8"

DESCRIPTION OF ACM:

☐ CHUNKS
☐ POWDER
☐ SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

<p><i>NO ACM</i></p> <p><i>[Signature]</i></p>	

TEAM MEMBERS:

DA/KS

07-0928-540

007306

11/10/97

Mr. [REDACTED] was not home, spoke with his daughter-in-law, who said he wanted ACM removed, but wanted to talk with us before signing the access agreement. We said we would come back tomorrow morning (Sat.).

Tracking Number 929

FIELD DATA SHEET 1

Site Information:

Occupant: [REDACTED]	Interviewee: [REDACTED]
Address: [REDACTED] Terrytown, LA 70053	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: Same <u>NOTE: Owner wishes to be called before marking or further assessment.</u>	

Site Description:

1) Description of property (circle): <u>single home</u> duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other <u>None</u> resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): <u>yes</u> no; don't know If yes, note on site sketch. How deep? <u>backyard - electrical</u>

Site Sketch:

Site sketch details: A house with a chimney. A 3'x3' ACM area is marked. A utility pad is shown. A key indicates exposed ACM and utility. The ground is labeled asphalt over concrete. A north arrow points up.

Estimated Volume of ACM: 10 ft²

Comments: 11/22 left access agreement w/ daughter, 14:00 Jm/AR
11/8/97 left access agreement w/ son 14:50 LT/RW

BACKFILL: CONCRETEDate/Time of Interview: 1-11-97 0840Access Granted (circle): yes noTeam Members: LT/RW

08-0929-510

007307

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED] SR.
Property's Address: [REDACTED] TERRYTOWN, ?
State/Zip: LA Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

Jan 11, 1997
DATE

[REDACTED]
SIGNATURE

08-0929-520

WESTBANK ACM REMOVAL PROJECT
SAMPLE ANALYSIS CONFIRMATION
USEPA START TEAM

FYI:

SITE#

929

ADDRESS:

~~REDACTED~~ RJ
Terrytown, LA

THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON no analytical data as of 10-31-97

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:


GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ☒ ☒

B. FURTHER ACTION NECESSARY: ☐ ☐

Grid ① Geolined 10-30-97
Grid ② Geolined 10-31-97

Grid Sample ID Depth Backfill Area
① WBS9729601 12" sod/soil/yard
② WBS9729602 12" sod/soil/yard



AUTHORIZED EPA/START REPRESENTATIVE

007310

Amanda Rooney

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
 Indianapolis, Indiana 46250
 Phone (317) 570-5892 Fax (317) 570-5894

EMSL

Attn.: Amanda Looney
 Ecology & Environment
 11550 New Castle Avenue
 Baton Rouge, LA 70816

Monday, November 03, 1997

Ref Number: IN971533

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
WBS1496G01	[REDACTED], MA	Brown Non-Fibrous Homogeneous	Crushed	2% Chrysotile < 1% Crocidolite			78% Quartz 20% Other
WBS1496G02	[REDACTED], MA	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile			80% Quartz 20% Other
WBS1496G03	[REDACTED], MA	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile			80% Quartz 20% Other
WBS929G01	[REDACTED] MILTON RD, GR	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			80% Quartz 20% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "% of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

Margaret E. Phillips
 Margaret Phillips
 Analyst

[Signature]
 Approved
 Signatory

08-0929-570

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negs be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the PLM. It may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim compliance with NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (600 AP Air and Bulk #200188-0)

007311

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
 Indianapolis, Indiana 46250
 Phone (317) 570-5892 Fax (317) 570-5894

EMSL

Attn.: Amanda Looney
 Ecology & Environment
 11550 New Castle Avenue
 Baton Rouge, LA 70816

Wednesday, November 05, 1997

Ref Number: IN971557

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	<u>ASBESTOS</u>		<u>NONASBESTOS</u>	
				%	TYPE	%	NONFIBROUS
WBS1297G01	[REDACTED] E, HA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		40% Quartz 60% Other
WBS1297G02	[REDACTED] E, HA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile < 1% Crocidolite		40% Quartz 60% Other
WBS929G02	[REDACTED] MILTON RD, TR	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		40% Quartz 60% Other
WBS414G03	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile < 1% Crocidolite		40% Quartz 60% Other
WBS1517G01	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed		None Detected		30% Quartz 70% Other
WBS1517G02	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed		2% Chrysotile		30% Quartz 68% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

Jane Wasilewski
 Analyst

Approved
 Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative results are not guaranteed. Floor tiles and wipees should be tested with either BEM or TEM. The above test report relates only to the PLM analysis. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim compliance with any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature of the analyst. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200188-0).

08-0929-570


007312



INTERNATIONAL
TECHNOLOGY
CORPORATION

By PM Date 11-3-97 Subject RESTORATION site # 929 Sheet No. of
Chkd. By Date Proj. No.

REVISED 11-10-97



08-0929-590

007313

WESTBANK ASBESTOS ABATEMENT NEW ORLEANS, LOUISIANA

RESTORATION FORM

SITE # 929

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)					(b) (4)		
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)					(b) (4)		
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoll (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

IT REPRESENTATIVE SIGNATURE

08-0929-590

SUB 1 SIGNATURE

007314


SUB 2 SIGNATURE



INTERNATIONAL
TECHNOLOGY
CORPORATION



By PM Date 11-3-97 Subject RESTORATION site # 929 Sheet No. of
Chkd. By Date Proj. No.



08-0929-590

007315

APR 1998

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)							
Sod Installation (sq.yds.)					(b) (4)		
3" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)					(b) (4)		
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

08-0929-590

IT REPRESENTATIVE SIGNATURE _____

SUB 1 SIGNATURE _____

SUB 2 SIGNATURE _____

007316

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/22/98

ADDRESS: [REDACTED]

SITE #: 0929

Terrytown

ACM LOCATED BENEATH:

☐ HOUSE
☐ SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

☐ CHUNKS
☐ POWDER
☐ SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

 <p>no ACM present</p>	_____

TEAM MEMBERS:

JS & EW

08-0929-540

007317

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]
Property's Address: [REDACTED], Gretna
State/Zip: LA, 70053 Phone Number(s): _____

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

1/2/97
DATE


[REDACTED]
SIGNATURE

05-0930-520

930

ADDRESS:

UPDATED: 11



N (NTS)

Owner wants concrete (signed off) ★

#	COVER	THICKNESS
①	Soil/Grass	NO ACM
②	2'-3" Soil/Grass	covered ACM

A: CONCRETE (38'x8')

B: SOD / SOIL REMAINDER

C:

ARRIVAL: 1044

DEPARTURE: 1123

RESTORATION APPROVED BY:

05-0930-530

TEAM: BB DM RL

DATE: 7-7-97

④ T₀ IT 7/30/97 96W

WESTBANK ACM REMOVAL PROJECT
SAMPLE ANALYSIS CONFIRMATION
USEPA START TEAM

FYI:

SITE# 930

ADDRESS: [REDACTED]
Geetna, LA


THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON 9-29-97

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:


GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ✓ ✓

B. FURTHER ACTION NECESSARY:



. Geolined 09.25.97



(b) (6)(b) (6)

007321

05-0950-560

AUTHORIZED EPA/START REPRESENTATIVE Maguion

EMSL Analytical, Inc.

**6330 East 75th Street, Suite 152
Indianapolis, Indiana 46250
Phone (317) 570-5892 Fax (317) 570-5894**

Attn.: Alma Rillera
Ecology & Environmental
11550 New Castle Avenue
Baton Rouge, LA 70816

Monday, September 29, 1997

Ref Number: IN971208

EMSL

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
WBS410G9		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		40% Quartz 60% Other
WBS410G02		Brown Non-Fibrous Homogeneous	Crushed	2%	Chrysotile < 1% Crocidolite		40% Quartz 58% Other
WBS930G01		Brown Non-Fibrous Homogeneous	Crushed		None Detected		80% Quartz 20% Other
WBS930G02		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile < 1% Crocidolite		80% Quartz 20% Other
WBS1173G01		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile < 1% Crocidolite		80% Quartz 20% Other
WBS1173G02		Brown Non-Fibrous Homogeneous	Crushed		None Detected		80% Quartz 20% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

Margaret F. Phillips

Margaret Phillips
Analyst

[Signature]

Approved
Signatory


05-0930-570

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus neg be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim per NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least on Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.


007322



INTERNATIONAL
TECHNOLOGY
CORPORATION



By DM Date 9-26-97 Subject RESTORATION SITE # 700 Sheet No. _____ of _____
Chkd. By _____ Date _____ Proj. No. _____



05-0930-590

ASLT00

007323

WESTBANK ASBESTOS ABATEMENT

NEW ORLEANS, LOUISIANA

RESTORATION FORM

SITE # 930

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)							
Sod Installation (sq.yds.)							
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)					(b) (4)		
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS:

05-0930-590

IT REPRESENTATIVE SIGNATURE

SUB 1 SIGNATURE

SUB 2 SIGNATURE

007324



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION 6
1445 ROSS AVENUE, SUITE 1200
DALLAS, TX 75202-2733

December 11, 1996

[REDACTED]
[REDACTED]
Slidell, LA 70458

Re: [REDACTED]
[REDACTED]

RECEIVED
97 JAN 21 PM 12:37
S. J. ANDERSON DIV.
DIRECTOR'S OFFICE

During the last year, the U.S. Environmental Protection Agency (EPA) and the Louisiana Department of Environmental Quality (LDEQ) have been investigating possible asbestos contamination within communities on the west bank of the Mississippi River, south of New Orleans, Louisiana. As a protective measure, representatives of these agencies will undertake a cleanup of these Westbank areas. This property has been identified as needing cleanup of asbestos-containing materials. Enclosed are fact sheets that provide additional information on the cleanup and on asbestos.

Enclosed is a form granting access to your property in order that further assessments may be done. Please sign the form, including both your name and address, and you will greatly facilitate this process. Please tell us if an address correction is needed or if you wish to receive future mailings at a different address. Send the signed form to the address below.

If you have any questions, please call our local information line at (504) 363-4917, or the EPA office in Dallas at 1-800-533-3508 (toll-free). Please refer to tracking numbers 930.

Sincerely,

Stacey Bennett, EPA Remedial Project Manager

for John J. Martin
EPA On-Scene Coordinator
U.S. EPA Region 6 (6SF-R2)
1445 Ross Ave.
Dallas, TX 75202

Enclosures

05-0930-600

007325

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/2/98
SITE #: 930

ADDRESS: [REDACTED]

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED

APPR. CRAWL SPACE HEIGHT:

NA

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

<p>NO ACM Donovan Allison</p>	

TEAM MEMBERS:

DA/ML

05-0930-540

007326

12/11/96 Mon after 2 pm visit
she works a lot

Tracking Number 931

NO visible ACM

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee:
Address: [REDACTED]	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant:	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): <u>locked gate</u> ; gate; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____

Comments: No home 12/11 10:50 TLM
15:15

She has 2 jobs, hard to reach; Wants us to look at yard for asbestos

Date/Time of Interview: 12/16/96 1442

Access Granted (circle): yes no

Team Members:

MLBS

07-0931-510

007327

this already has a tracking

Tracking Number 931

NO visible
ACM

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee:
Address: [REDACTED]	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>same</u> <u>NO visible ACM</u>	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): <u>locked gate</u> ; gate; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____

Comments:

Date/Time of Interview: 12/11/96 14212

Access Granted (circle): yes; no

Team Members: ML/PS

07-0931-510

007328

931

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]
Property's Address: [REDACTED]
State/Zip Mass 010072 Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

12-10-1996
DATE

[REDACTED]
SIGNATURE

07-0931-520

007329

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE:

9/2/98

ADDRESS:

[REDACTED]

SITE #:

931

ACM LOCATED BENEATH:

☐ HOUSE
☐ SHED

APPR. CRAWL SPACE HEIGHT:


NA

DESCRIPTION OF ACM:

☐ CHUNKS
☐ POWDER
☐ SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:



A hand-drawn sketch of a concrete slab, represented by a thick black diagonal line. The sketch is located on the left side of a large rectangular area with horizontal lines. To the right of the sketch, the words "concrete slab" are handwritten in cursive.

TEAM MEMBERS:

DA/ML

07-0931-540

007330

FIELD DATA SHEET 1

~~NO VISIBLE ACM~~ACM FOUND IN SERVITUDE
Revised 5/15/97 *GRB*


Site Information:

Occupant: <u>[REDACTED]</u>	Interviewee:
Address: <u>[REDACTED] 70072</u>	
Phone No.: <u>[REDACTED]</u>	
Owner Name, Address, and Phone No. if Different Than Occupant:	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): <u>locked gate</u> ; <u>gate</u> ; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____

Comments: No visible ACM; KS/TC visited this house once before and found no vis. ACM.
5/15/97 → ACM found in servitude during excavation of site 1087 next door.
No one home 5/15/97 site 1007 removal went into site 932 - Tim 10:37 hrs. *GRB*

Date/Time of Interview: 12/11 11:15

Access Granted (circle): yes no

Team Members: TL/ML

07-0932-510

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]
Property's Address: [REDACTED] *Marino*
State/Zip: *MA 01902* Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 *et seq.* Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

12/10/96
DATE


[REDACTED]
SIGNATURE

07-0932-520

SITE SKETCH

ADDRESS:

UPDATED: 9/9/97



NOTES:

N (NT8)
4

SMALL AMOUNT OF ACM DISCOVERED

RESTORATION: A: GRASS 6'x2'

B:
C:

ARRIVAL: 1045

DEPARTURE: 1120

TEAM: MM/DB

RESTORATION APPROVED BY:

DATE: 9, 9, 97

007333:

• (City owns servitude) DATE: 9/30/87

70 27 9/30

K

07-0932-530

#	COVER	THICKNESS
1	GRASS/SHELLS	1'-4"
2	GRASS/SHELLS	+6
3	SHELLS/SAND	+6

WESTBANK ACM REMOVAL PROJECT
SAMPLE ANALYSIS CONFIRMATION
USEPA START TEAM

FYI:

SITE# 932

ADDRESS: [REDACTED]
Marrero, La


THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON no analytical as of 11-6-97

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ☒

B. FURTHER ACTION NECESSARY: ☐



AUTHORIZED EPA/START REPRESENTATIVE

004534

EMSL Analytical, Inc.

6330 East 73th Street, Suite 152
Indianapolis, Indiana 46250
Phone (317) 570-5892 Fax (317) 570-5894

EMSL

Attn.: **[REDACTED]**
Ecology & Environment
[REDACTED]

Baton Rouge, LA 70816

Monday, November 10, 1997

Ref Number: IN971578

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 800/R-83/116 Method*

Project: WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
WB8832G01	[REDACTED] MA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		70% Quartz 30% Other
WB8463G01	[REDACTED] HA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile < 1% Crocidolite		70% Quartz 30% Other
WB8463G02	[REDACTED] HA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile < 1% Crocidolite		70% Quartz 30% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "N of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 186-1 Method

Jane Wasilewski
Analyst

007335

Approved
Signatory

07-0932-570


Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus, negative results are not guaranteed. Floor tiles and wipe samples should be tested with either SEM or TEM. The above test report relates only to the PLM analysis. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim compliance with any agency of the United States Government. All "WVLA" reports with WVLA logo must contain at least one signature of the analyst. EMSL is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL at Indianapolis (317) 570-5892 and (317) 570-5894.



INTERNATIONAL
TECHNOLOGY
CORPORATION



By PM Date 11-7-97 Subject RESTORATION SITE # 932 Sheet No. _____ of _____
Chkd. By _____ Date _____ Proj. No. _____



07-0932-590

007336

SITE # 932

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
ock Installation (sq.yds.)							
d Installation (sq.yds.)					(b) (4)		
Concrete Installation (sq. yds.)					(b) (4)		
Concrete Installation (sq. yds.)					(b) (4)		
nd Installation (sq.yds.)					(b) (4)		
ower Lift Sand					(b) (4)		
ock, Brown (cu.yds.)					(b) (4)		
ock, Gray (cu.yds.)					(b) (4)		
and (cu.yds.)					(b) (4)		
oncrete (cu.yds.)					(b) (4)		
lastic Edging (ft.)							
alkway Rock Inst. (sq.yds.)							
opsoil (cu.yds.)							
XTRA							

Site Sketch on Back of Page

COMMENTS: _____

07-0932-590

T REPRESENTATIVE SIGNATURE

SUB 1 SIGNATURE

SUB 2 SIGNATURE

007337

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/22/98

ADDRESS: [REDACTED]

SITE #: 0932

MA

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

 <p>no ACM present</p>	<u>Removal of dog sign</u>

TEAM MEMBERS:

JS & EW

07-0932-540

007338

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee: [REDACTED]
Address: [REDACTED] <u>Marrero, LA</u>	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>SAME</u>	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other <u>None</u> resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; <u>don't know</u> If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____

Comments: NOT HOME 12/11 PM concrete drivewayDate/Time of Interview: 12/17 10:27 Access Granted (circle): yes; noTeam Members: KJ / KR

07-0933-510

007339

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: _____
Property's Address: _____
State/Zip: 70072 Phone Number(s): _____

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

12-18-96
DATE

SIGNATURE

07-0933-520


007340

933

ADDRESS:

Maffei

UPDATED: / /



N (NTS)
←

Some SACM present in Runners
about 6 sq. ft. total
SUSPECTED ACM UNDER 3"-4" OF ASPHALT
THAT IS IN GOOD CONDITION (DRIVEWAY)

ARRIVAL: 1345
DEPARTURE: 1425

TEAM: BB DM RL

RESTORATION APPROVED BY:

DATE: 7-21-97
007341

#	COVER	THICKNESS
①	Soil/Grass	No ACM
②	2"-3" Soil/Grass	cured ACM
③	Thin layer of	Shingle/Tar over ACM

07-0933-530

DATE: 8 / 1 / 97

⊗ FORWARD TO IT 8/1/97
9w

WESTBANK ACM REMOVAL PROJECT

SAMPLE ANALYSIS CONFIRMATION

USEPA START TEAM

FYI:


SITE# 933

ADDRESS: [REDACTED]
Marrero

THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON _____

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #:	1	2	3	4	5	6	7	8
A. PROCEED WITH RESTORATION:	✓	✓						
B. FURTHER ACTION NECESSARY:	___	___						



07-0933-560

AUTHORIZED EPA/START REPRESENTATIVE [REDACTED]
007342

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
 Indianapolis, Indiana 46250
 Phone (317) 570-5892 Fax (317) 570-5894

Attn.: Alma Rillera
 Ecology & Environmental
 11550 New Castle Avenue
 Baton Rouge, LA 70816

EMSL

Tuesday, September 09, 1997

Ref Number: IN971031

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: 020601 RAGI WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
WBS1162G01	MA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile Crocidolite		40% Quartz 60% Other
WBS933G01	MA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile Crocidolite		80% Quartz 20% Other
WBS933G02	MA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
WBS922G01		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
WBS922G02		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
WBS922G03	MA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile Crocidolite		80% Quartz 20% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

Jane Wasilewski
 Analyst

Approved
 Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative be guaranteed. Floor tiles and waxes should be tested with either SEM or TEM. The above test report relates only to the item may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product NVLAP for any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one si Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200188-0).

07-0933-570

007343

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
Indianapolis, Indiana 46250
Phone (317) 570-5892 Fax (317) 570-5894



Attn.: [REDACTED]
Ecology & Environmental
[REDACTED]
Baton Rouge, LA 70816

Tuesday, September 09, 1997

Ref Number: IN971031

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: 020601 RAGI WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
WBS1182G01	[REDACTED] ST. MA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile Crocidolite		40% Quartz 60% Other
WBS933G01	[REDACTED] MA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile Crocidolite		80% Quartz 20% Other
WBS933G02	[REDACTED] MA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
WBS922G01	[REDACTED] MA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
WBS922G02	[REDACTED] MA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
WBS922G03	[REDACTED] MA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile Crocidolite		80% Quartz 20% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

[REDACTED]
Analyst

[REDACTED]
Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative results should be confirmed by SEM or TEM. The above test report relates only to the fiber analysis. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the fiber analysis. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product liability for any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one of the following: Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200168-0).

07-0933-570

007344




INTERNATIONAL
TECHNOLOGY
CORPORATION



By DM Date 9-6-97 Subject RESTORATION SITE # 933 Sheet No. of

Chkd. By Date Proj. No.



07-0933-590

007345

SITE # 933

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)					(b) (4)		
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)							
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

07-0933-590

IT REPRESENTATIVE SIGNATURE _____
SUB 1 SIGNATURE _____
SUB 2 SIGNATURE _____

007346

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/9/98
SITE #: 933

ADDRESS: [REDACTED] NA

ACM LOCATED BENEATH:

☐ HOUSE
☐ SHED

APPR. CRAWL SPACE HEIGHT:


NA

DESCRIPTION OF ACM:

☐ CHUNKS
☐ POWDER
☐ SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

TEAM MEMBERS: DA/KJ

07-0933-540

007347

~~000000~~

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee: [REDACTED]
Address: [REDACTED], Marrero	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: owner @ [REDACTED], Marrero (across street)	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other <u>NO</u> resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; <u>don't know</u> If yes, note on site sketch. How deep? _____

Site Sketch:

Estimated Volume of ACM: 8' x 10' = 80 ft²Comments: Concrete in front Holiday access grantedDate/Time of Interview: 12/11/96

1321

Access Granted (circle): yes; noTeam Members: TN | KI

07-0934-510

007348

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]

Property's Address: [REDACTED]

State/Zip: MD, 20077 Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

12/11/96
DATE

[REDACTED]
SIGNATURE

07-0934-520

007349

WESTBANK ACM REMOVAL PROJECT
SAMPLE ANALYSIS CONFIRMATION
USEPA START TEAM

FYI:

SITE# 934

ADDRESS: [REDACTED]

Marrero, La. 70072

THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON 12-17-96.

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ☒

B. FURTHER ACTION NECESSARY: ☐

geo-
liner
needed
(See below)

① geo-liner needed at stairs - Geo-liner needed on entire grid!
~6" back fill concrete

SITE #934

STAIRS concrete

WB593401HA

07-0934-560

AUTHORIZED EPA/START REPRESENTATIVE [REDACTED]

007350

Waltham, NJ	Placerville, NJ	Carle Place, NY	Manhasset, NY	Seattle, WA	Ann Arbor, MI	San Mateo, CA	Dayton, OH	Greensboro, NC	Houston, TX
603-651-0001	908-961-0558	516-937-7551	212-239-8852	206-233-6087	213-493-4510	415-476-5401	604-333-4882	910-297-1657	713-496-3435

EMSL

Ecology & Environment, Inc.
11550 Newcastle Ave. #250
Baton Rouge, LA 70816


Tuesday, December 17, 1996

Ref Number: TX963264

POLARIZED LIGHT MICROSCOPY (PLM)

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS % NONFIBROUS
WBS30203MA1	302	Tan Non-Fibrous Homogeneous	Teased	2% Chrysotile < 1% Crocidolite			98% Other
WBS30204MA1	302	Tan Non-Fibrous Homogeneous	Teased	< 1% Chrysotile < 1% Crocidolite			100% Other
WBS93401MA1	934	Tan Non-Fibrous Homogeneous	Teased	2% Chrysotile < 1% Crocidolite			98% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.



Carlos D. Salinas
Analyst

Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative results are not guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product or nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature. EMSL is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

07-0934-570

007351




By PM Date 12-16-96 Subject RESTORATION SITE # 934

Sheet No. of

Chkd. By Date

Proj. No.



①	15.00	x 7	=	108.00	SQ
②	3	x 7	=	21.00	SQ
③	5	x 1.50	=	7.50	SQ
TOTAL				=	136.50 SQ FT
				=	15.22 SQ YD

ALL
CONCRETE
AREAS A/B/C

07-0934-590

007352

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 7/28/98

SITE #: 934

ADDRESS: [REDACTED]

Marrero LA

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	_____

TEAM MEMBERS:

AL/DA

07-0934-540

007353

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee:
Address: [REDACTED] Marrero	
Phone No.:	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED] come by after 2:00	

Site Description:

1) Description of property (circle): single home; duplex; business; school; daycare; <u>church;</u> vacant house; vacant lot; other
2) Problems accessing yards (circle): locked gate; gate; dogs; other <u>No</u> resolution:
3) Underground utilities installed by owner? (circle): <u>no</u> water; gas; electric; cable TV; septic tank; other Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; <u>don't know</u> If yes, note on site sketch. How deep?

Site Sketch:



Estimated Volume of ACM: _____

Comments: 12/12 0940 TC/ml

LIMESTONE

check for duplicate [REDACTED]

Date/Time of Interview:

Access Granted (circle): yes; no

Team Members:

TN/KJ

07-0935-510

007354

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]
Property's Address: [REDACTED]
State/Zip: La Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

12-12-96
DATE

[REDACTED]
SIGNATURE

07-0935-520


Call [REDACTED]
Backfill: soil/grass or
limestone

007355

TRACKING # 935

SITE SKETCH

ADDRESS: [REDACTED]

UPDATED: 1/1

NOTES:

N (NTS)



TRUCK (16 wheeler) near Acn

② CALL BACK THIS AFTERNOON

RESTORATION: A: Limestone
B: Soil/sod
C:

ARRIVAL: 10:30

DEPARTURE: 11:20

TEAM: TT/DA

RESTORATION APPROVED BY: [REDACTED]

DATE: 7/11/97

07-0935-530

DATE: 8/8/97

8/8/97 ZOIT

007250

WESTBANK ACM REMOVAL PROJECT SAMPLE ANALYSIS CONFIRMATION USEPA START TEAM

FYI:

SITE#

935

ADDRESS:

[REDACTED]

Martinez, Ca.

THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON No analysis as of 9-10-97



BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION:

✓ ✓

B. FURTHER ACTION NECESSARY:



07-0935-560

AUTHORIZED EPA/START REPRESENTATIVE

007357

Attn.: Christopher Sansone
Ecology & Environment, Inc.
11550 Newcastle Ave. #250
Baton Rouge, LA 70816

Saturday, September 13, 1997

Ref Number: TX973824

EMSL

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: WESTBANK ASBESTOS REMOVAL PROJECT / KS6102 020601RAXX

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	NONFIBROUS
WBS982G01		Brown Fibrous Homogeneous	Teased	< 1%	Chrysotile	100%	Other
WBS1019G01		Brown Fibrous Homogeneous	Teased	< 1%	Chrysotile	100%	Other
WBS982G02		Brown/White Fibrous Homogeneous	Teased	3%	Chrysotile < 1% Crocidolite	97%	Other
WBS654G01		Brown Fibrous Homogeneous	Teased	None Detected		100%	Other
WBS654G02		Brown Fibrous Homogeneous	Teased	None Detected		100%	Other
WBS935G01		Brown Fibrous Homogeneous	Teased	None Detected		100%	Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

Analyst

Approved
Signatory

Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus nega be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the it may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim prod NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Houston (NVLAP Air and Bulk #102106).

07-0935-570

007358

EMSL

Attn.: Christopher Sansone
 Ecology & Environment, Inc.
 11550 Newcastle Ave. #250
 Baton Rouge, LA 70816

Saturday, September 13, 1997

Ref Number: TX973824

POLARIZED LIGHT MICROSCOPY (PLM)


Performed by EPA 600/R-93/116 Method*

Project: WESTBANK ASBESTOS REMOVAL PROJECT / KS6102 020601RAXX

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	NONFIBROUS
WBS935G02	[REDACTED]	Brown Fibrous Homogeneous	Teased	< 1% Chrysotile < 1% Crocidolite		100% Other	
WBS1039G01	5 [REDACTED]	Brown Fibrous Homogeneous	Teased	None Detected		100% Other	
WBS1039G02	[REDACTED]	Brown Fibrous Homogeneous	Teased	None Detected		100% Other	
WBS1275G01	[REDACTED]	Brown Fibrous Homogeneous	Teased	None Detected		100% Other	
WBS1039G03	[REDACTED]	Brown Fibrous Homogeneous	Teased	< 1% Chrysotile		100% Other	

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method



Analyst



Approved
Signatory

Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus neg be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim prc NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least on Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Houston (NVLAP Air and Bulk #102106).

07-0935-570

007359




INTERNATIONAL
TECHNOLOGY
CORPORATION



By PM Date 9-11-97 Subject RESTORATION SITE # 935 Sheet No. _____ of _____

Chkd. By _____ Date _____ Proj. No. _____



07-0935-590

007360

WESTBANK ASBESTOS ABATEMENT NEW ORLEANS, LOUISIANA

RESTORATION FORM

SITE # 935

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)					(b) (4)		
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)					(b) (4)		
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

07-0935-590

IT REPRESENTATIVE SIGNATURE _____

SUB 1 SIGNATURE _____

SUB 2 SIGNATURE _____

007361

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 7/28/98

SITE #: 0935

ADDRESS: [REDACTED]

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	_____

TEAM MEMBERS:

AL/DA

07-0935-540

007382

936

Tracking Number 807-0000 12/12

11-21 sketch made, 14:20 JM/AR

FIELD DATA SHEET 1

11-23 ~~no answer~~, no answer, JM3-14-97 NA
3-23-97 left access w/ renter at [redacted] give to owner12/29/96 NA
12/19/96 NA

4-17-97 NA

8-8-97 called no answer

8-16-97 call no answer

Site Information:

Occupant: [redacted]	Interviewee: [redacted]
Address: [redacted] <u>Gretia</u>	
Phone No.: [redacted]	
Owner Name, Address, and Phone No. if Different Than Occupant:	
[redacted] JM, 11-23	
[redacted] DB 11/7/92	
<u>Harvey Ferraglow, LA</u>	


9/5/97 call
no answer

Site Description:

- 1) Description of property (circle): single home; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
- 2) Problems accessing yards (circle): locked gate; gate; dogs; other _____ resolution: _____
- 3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____
Note location on site sketch.
- 4) Is any underground ACM present? (circle): yes; no; don't know
If yes, note on site sketch. How deep? _____

Site Sketch:

[hatched box] = ACM

Estimated Volume of ACM: 25 ft³Comments: backfill

Date/Time of Interview:

Access Granted (circle) yes no

Team Members:

05-0936-510

007363

936

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]
Property's Address: [REDACTED] *2100 N.A.*
State/Zip: 70053 Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

9-23-97

DATE

[REDACTED]
SIGNATURE

05-0936-520


007364

TRACKING # 936

SITE SKETCH

ADDRESS: [REDACTED]

UPDATED: 1 / 1



NOTES:

N (NTS)
→ N

RESTORATION: A: sod-soil
B:
C:

ARRIVAL: 1015
DEPARTURE: 1105

TEAM: SJ, JS

RESTORATION APPROVED BY: [REDACTED]

DATE: 11 / 10 / 97

05-0936-530

DATE: 11 / 10 / 97

TO ET 11/13/97

007365

WESTBANK ACM REMOVAL PROJECT
SAMPLE ANALYSIS CONFIRMATION
USEPA START TEAM

FYI:

SITE# 936

ADDRESS: [REDACTED]
Gretna, LA


THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON no analytical ASDs 1-24-98 min

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ☒

B. FURTHER ACTION NECESSARY: ☐



AUTHORIZED EPA/START REPRESENTATIVE [REDACTED]

007366

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
Indianapolis, Indiana 46250
Phone (317) 570-5892 Fax (317) 570-5894

EMSL

Attn.: Chris Sansome
Ecology & Environment
11550 New Castle Avenue
Suite 250
Baton Rouge, LA 70816

Wednesday, January 28, 1998

Ref Number: IN98247

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: 020601RAG1

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS % NONFIBROUS
WBS1639-G01	MA	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			40% Quartz 60% Other
WBS1639-G02	MA	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			40% Quartz 60% Other
WBS936-G01	GR	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile			25% Quartz 75% Other
WBS1658-G01	MA	Brown Non-Fibrous Homogeneous	Crushed	None Detected			10% Quartz 90% Other
WBS1357-G01	MA	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile			40% Quartz 60% Other
WBS1606-G01	MA	Brown Non-Fibrous Homogeneous	Crushed	2% Chrysotile < 1% Crocidolite			40% Quartz 58% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "% of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method


Analyst


Approved
Signatory


05-0936-570

Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus neg. be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the i may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim pro NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200185-0)

007367



By PM Date 1-26-98 Subject RESTORATION SITE # 936 Sheet No. of
Chkd. By Date Proj. No.



05-0936-590

007368

WESTBANK ASBESTOS ABATEMENT NEW ORLEANS, LOUISIANA

RESTORATION FORM

SITE # 936

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)							
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)							
4" Concrete Installation (sq. yds.)							
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand							
Rock, Brown (cu.yds.)							
Rock, Gray (cu.yds.)							
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)							
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

05-0936-590

IT REPRESENTATIVE SIGNATURE

SUB 1 SIGNATURE

SUB 2 SIGNATURE

007369

Resident Contact Log

Owner

Residence Number:**Property Address:**

Owner Name:

Current Location/Phone/Fax:[illegible]

M=Meeting; P=Phone Call; W=Fax or Written

Init=Your Initials

R=Received; I=Initiated Communication

Comments: Briefly discuss purpose/reference other forms or documents that may have been completed.

Status: Note any milestones (received access, keys, etc.) or follow-up actions to take place.

05-0936-600

007370



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION 6
1445 ROSS AVENUE, SUITE 1200
DALLAS, TX 75202-2733

September 12, 1997

Dear [REDACTED]

As you may be aware, the United States Environmental Protection Agency is conducting a Superfund removal action in the Westbank area of Louisiana. Your property at [REDACTED], Gretna, has been identified as containing asbestos containing material. We have been unable to contact you regarding the removal of this hazardous material from your property.

Our goal is to mitigate the threat to human health and the environment posed by the asbestos located on your property. However, our project is nearing completion. In order to thoroughly investigate your property we need a signed access agreement from you. Please sign the enclosed agreement and return it at your earliest convenience. Should you have any questions or concerns, feel free to contact an EPA site representative at either (504)367-6788 or (504)363-4917.

I have enclosed the latest fact sheet regarding the removal project for your information. Thank you for your assistance and cooperation.

Sincerely,

[REDACTED]
Federal On-Scene Coordinator, U.S. EPA

enclosures: fact sheet, access agreement
reference: Site #936
[REDACTED]

05-0936-600

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 8/6/98

SITE #: 0936

ADDRESS: [REDACTED]
GRETN

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED

APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

<div>NO VIS. ACM</div>	_____

05-0936-540

TEAM MEMBERS: PM

007372

Tracking Number 937

Ref 124

No visible ACM

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee: [REDACTED]
Address: [REDACTED] Westwego	
Phone No.: —	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED] Westwego ([REDACTED])	

Site Description:

1) Description of property (circle): single home; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____

Comments: No visible ACM

Date/Time of Interview: 12/12 16:25

Access Granted (circle): yes; no NA

Team Members: TC/ml

09-0937-510

007373

TRACKING #

946


SITE SKETCH

ADDRESS:

~~XXXXXXXXXX~~

M. H. H. H.

UPDATED: 1/1



NOTES:

N (NTS)

#	COVER	THICKNESS
①	Soil/Grass	NO ACM
②	Soil	
③	1"-2" soil/Grass covered	ACM

RESTORATION: A: LIMESTONE

B:

C:

ARRIVAL: 1055

DEPARTURE: 1114

RESTORATION APPROVED BY: fw 7/16/97

07-0946-530

TEAM:

BB DA JD

DATE:

7/15/97
007400

DATE: 7/24/97

TO IT 7/24/97 JRA

AUTHORIZED EPA/START REPRESENTATIVE

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
 Indianapolis, Indiana 46250
 Phone (317) 570-5892 Fax (317) 570-5894

EMSL

Attn.: Chris Sansone
 Ecology & Environment
 11550 New Castle Avenue
 Baton Rouge, LA 70816

Friday, October 10, 1997

Ref Number: IN971328

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: 020601 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	<u>ASBESTOS</u>		<u>NONASBESTOS</u>	
				%	TYPE	%	FIBROUS % NONFIBROUS
WBS946G01	[REDACTED] IMA	Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile Crocidolite		80% Quartz 20% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "% of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

Margaret S. Phillips
 [REDACTED]

Analyst

Entered
 10/10/97
 GRD

[Signature]

Approved
 Signatory


Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the item may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one of Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200185-0).

07-0946-570



By PM Date 10-9-97 Subject RESTORATION SITE # 946 Sheet No. _____ of _____

Chkd. By _____ Date _____ Proj. No. _____



07-0946-590

WESTBANK ASBESTOS ABATEMENT NEW ORLEANS, LOUISIANA

RESTORATION FORM

SITE # 946

	DATE	DATE	DATE	DATE	EST. QTY	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)					(b) (4)		
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)							
Concrete (cu.yds.)							
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

07-0946-590

IT REPRESENTATIVE SIGNATURE _____

SUB 1 SIGNATURE _____

007404

SUB 2 SIGNATURE _____

001500

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9-24-98

ADDRESS: [REDACTED]

SITE #: 0946

Maerero

ACM LOCATED BENEATH:

<input checked="checked" type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED

APPR. CRAWL SPACE HEIGHT:

10' 1"


DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

0%

SKETCH OR COMMENTS:

NO ACM AT Barroom

TEAM MEMBERS: J.Y. & A.T.

07-0946-540

007405

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee: [REDACTED]
Address: [REDACTED], <u>Gratna La</u>	
Phone No.: <u>see below</u>	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED] - Tuesday 5 PM - 5:30 PM (home) <u>Metairie La 70002</u> (work) [REDACTED] - different address	

Site Description: work address Gratna Parish Massimo Agenz

- 1) Description of property (circle): single home; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
- 2) Problems accessing yards (circle): locked gate; gate; dogs; other none
resolution: _____
- 3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____
Note location on site sketch.
- 4) Is any underground ACM present? (circle): yes; no; don't know
If yes, note on site sketch. How deep? see note

Site Sketch:



Estimated Volume of ACM: _____

Comments: ACM in servitude, material dug up by City of Gratna contractors working on storm sewers. Work stopped upon discoveryDate/Time of Interview: 12/16/12Access Granted (circle) yes no

Team Members: [REDACTED]

05-0947-510

007406

7 947

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]
Property's Address: [REDACTED] *Green St*
State/Zip: *La 9053* Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

12/16/96
DATE

[REDACTED]
SIGNATURE

Note - [REDACTED]
[REDACTED]

05-0947-520

WESTBANK ACM REMOVAL PROJECT
SAMPLE ANALYSIS CONFIRMATION
USEPA START TEAM

FYI:

SITE# 947

ADDRESS: [REDACTED]

Gretna, La. 70053

THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON N/A.


BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: N/A — — — — —

B. FURTHER ACTION NECESSARY: geo-liner needed (see below) — — — — —

Note: This servitude was removed only the width of the driveway per EPA J. Martin.



(1): 6' concrete put in by city of Gretna; results are for confirmation only.

AUTHORIZED EPA/START REPRESENTATIVE [REDACTED]

05-0947-560

007408

Westmont, NJ 909-322-0800 Princeton, NJ 908-961-0530 Carlo Place, NY 516-487-7251 Manhattan, NY 212-250-0252 Seattle, WA 206-233-5907 Ann Arbor, MI 313-963-4010 San Mateo, CA 415-670-5401 Smyrna, GA 404-333-4000 Greensboro, NC 910-297-1487 Houston, TX 713-266-3635



Ecology & Environment, Inc.
11550 Newcastle Ave. #250
Baton Rouge, LA 70816

Friday, December 20, 1996


Ref Number: TX963314

POLARIZED LIGHT MICROSCOPY (PLM)

Project: 020601 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
WBS947G01		Tan Non-Fibrous Homogeneous	Teased	2%	Chrysotile < 1% Crocidolite		98% Other
WBS476G01		Tan Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.


Charles R. Smith
Analyst

Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus neg. guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the item only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

05-0947-570

007409

**WESTBANK ASBESTOS ABATEMENT
NEW ORLEANS, LOUISIANA**

RESTORATION FORM

SITE # 947

	RATE				TOTAL QTY.
Driveway Reconst. (sq.yds.)	(b)	(4)			
Walkway Reconst. (sq.yds.)	(b)	(4)			
Sod Installation (sq.yds.)	(b)	(4)			
Topsoil Backfill (cu.yds.)	(b)	(4)			
Sand Backfill (cu.yds.)	(b)	(4)			
Backfill Installation (sq.yds.)	(b)	(4)			
Backfill Lower Lift #1 (sq.yds.)	(b)	(4)			
Backfill Lower Lift #2 (sq.yds.)	(b)	(4)			
Backfill Lower Lift #3 (sq.yds.)	(b)	(4)			
Backfill Lower Lift #4 (sq.yds.)	(b)	(4)			
Plastic Edging (lft.)	(b)	(4)			
Limestone (cu.yds.)	(b)	(4)			
Concrete 6" (sq.yds.)	(b)	(4)			
Concrete 4" (sq.yds.)	(b)	(4)			

Site Sketch on Back of Page

COMMENTS: Restoration Done By City of GREYNA

IT REPRESENTATIVE SIGNATURE _____

NOLA REPRESENTATIVE SIGNATURE _____

05-0947-590

007410

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 8/6/98
SITE #: 947

ADDRESS: [REDACTED]
GRETN, LA

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED

APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

TEAM MEMBERS:

[Signature]

05-0947-540

007411

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 8-26-98

ADDRESS: [REDACTED]

SITE #: 047

Marrero

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED

APPR. CRAWL SPACE HEIGHT:


18"

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	<u>NO VIS SACM</u>

TEAM MEMBERS:

PLL/AB

05-0947-540

007412

#947:
servitude:
filed by city
of Gretna
(B)

FIELD DATA SHEET 1


Site Information:

Occupant: <u>[REDACTED]</u>	Interviewee: _____
Address: <u>[REDACTED] Brea CA</u>	
Phone No.: _____	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>[REDACTED]</u> <u>Brea CA 9253</u> <u>[REDACTED]</u>	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other <u>none</u> resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; <u>no</u> ; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



1/8/97 -- [REDACTED] stopped to obtain signed access agreement. ACM is no longer in driveway. It has been broken up and scattered along the sidewalk. New concrete slab is in place now. We notified [REDACTED] of this via radio upon discovery.

Estimated Volume of ACM: _____

Comments: ACM in service. material dug up by City of Brea contractors working on storm sewers. Worked stopped upon discovery 12/19/96 - [REDACTED] RJ/K.

Date/Time of Interview: 12/16/96 Greg Day Access Granted (circle): yes; no

Team Members: _____

05-0948-510

No removal necessary 1020-97

007414

Owner

948

~~_____~~, bretna

Owner Name:

Current Location/Phone/Fax:

007415

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 8-6-98

ADDRESS: [REDACTED]

SITE #: 948

GREYNA, LA.

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	<u>NO VISIBLE ACM</u>

TEAM MEMBERS:

[Signature]

05-0948-540

007416

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee:
Address: [REDACTED] <u>Maricao, LA 70072</u>	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant:	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; <u>gate</u> ; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; <u>don't know</u> If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____

Comments: ACM UNDER SHED - EXTENDS ~ 1 FOOT OUT FROM BASE + WALLS - SHED FLOOR - POURED CONCRETE. Owner wants soil replaced ground shed.Date/Time of Interview: 2/12/97 0904Access Granted (circle): yes; noTeam Members: CMA/KR

07-0949-510

007417

#1949

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: _____
Property's Address: _____ MAPPERD
State/Zip: _____ Phone Number(s): _____

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

2/12/97
DATE

[REDACTED]
SIGNATURE

07-0949-520

007418



SITE 949

SITE SKETCH

[REDACTED] Morrero

4/8/97
1500/1520

[REDACTED] Morrero LA



Note
shed was built on
concrete slab placed
on top of ACM slab

① SALM 2-3" thick

Restoration:

① soil - approved by [REDACTED] on 4/10/97 via phone

07-0949-530

2007/4/97

WESTBANK ACM REMOVAL PROJECT
SAMPLE ANALYSIS CONFIRMATION
USEPA START TEAM

FYI:

SITE# 949

ADDRESS: [REDACTED]
Marrero

THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON _____.


BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

- A. PROCEED WITH RESTORATION: ☒ _____
- B. FURTHER ACTION NECESSARY: ☐ _____

• visible ACM highlighted below: (Z1) and (Z2)
• geolined 05-06-97

Grid	Sample ID	Depth	Backfill/Area
①	WBS949601	12"	sod, soil/yard



0071
AUTHORIZED EPA/START REPRESENTATIVE [REDACTED]

Westmont, NJ 908-265-4800	Freeholdway, NJ 908-261-0066	Carle Place, NY 516-987-7251	Manhasseton, NY 212-230-0853	Seattle, WA 206-233-9007	Ann Arbor, MI 313-963-4810	San Mateo, CA 415-578-5481	Baytown, TX 281-333-0886	Greensboro, NC 919-237-1487	Burton, TX 713-486-3635
------------------------------	---------------------------------	---------------------------------	---------------------------------	-----------------------------	-------------------------------	-------------------------------	-----------------------------	--------------------------------	----------------------------

EMSL

Ecology & Environment, Inc.
11550 Newcastle Ave. #250
Baton Rouge, LA 70816

Thursday, May 08, 1997

Ref Number: TX971658

POLARIZED LIGHT MICROSCOPY (PLM)

Project: 020601RAG1 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		%	NONASBESTOS	
				%	TYPE		FIBROUS	% NONFIBROUS
WBS94G01	MA	Tan Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile			100% Other
WBS94G02	MA	Tan Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile			100% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.



Analyst

Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus, negall guaranteed. Floor tiles and wipees should be tested with either SEM or TEM. The above test report relates only to the items only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product on nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

07-0949-570




INTERNATIONAL
TECHNOLOGY
CORPORATION



By AM Date 5-7-97 Subject Restoration site # 949 Sheet No. of

Chkd. By Date Proj. No.



07-0949-590

07422

WESTBANK ASBESTOS ABATEMENT NEW ORLEANS, LOUISIANA

RESTORATION FORM

SITE # 949

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)							
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)					(b) (4)		
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____


07-0949-590

IT REPRESENTATIVE SIGNATURE

SUB 1 SIGNATURE

SUB 2 SIGNATURE

007423



NOTES;

N (NTS)

RESTORATION: A: LIMESTONE

B:

C:

ARRIVAL: 1055

DEPARTURE: 1114

TEAM:

BB DA JD

RESTORATION APPROVED BY:

DATE:

007400

61010

DATE: 7/24/97

TO IT 7/24/97 JKA

#	COVER	THICKNESS
①	Soil/Grass	NO ACM
②	Soil	
③	1"-2" soil/Grass covered	ACM

WESTBANK ACM REMOVAL PROJECT
SAMPLE ANALYSIS CONFIRMATION
USEPA START TEAM

FYI:

SITE# 946

ADDRESS: [REDACTED]
MARPERO, Ca.


THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON _____.

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ☒

B. FURTHER ACTION NECESSARY: ☐



(b) (6)(b) (6)(b) (6)

007401

AUTHORIZED EPA/START REPRESENTATIVE

[Signature]

07-0946-560

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
Indianapolis, Indiana 46250
Phone (317) 570-5892 Fax (317) 570-5894

EMSL

Attn.: Chris Sansone
Ecology & Environment
11550 New Castle Avenue
Baton Rouge, LA 70816

Friday, October 10, 1997

Ref Number: IN971328

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/118 Method*

Project: 020601 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS
WBS946G01		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile Crocidolite		80% Quartz 20% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "% of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

Margaret J. Phillips
Margaret Phillips
Analyst

Entered
10/10/97
GRS

Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the item may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one of Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200198-0)

07-0946-570




INTERNATIONAL
TECHNOLOGY
CORPORATION



By PM Date 10-9-97 Subject RESTORATION SITE # 946 Sheet No. _____ of _____

Chkd. By _____ Date _____ Proj. No. _____



07-0946-590

101700

**WESTBANK ASBESTOS ABATEMENT
NEW ORLEANS, LOUISIANA**

RESTORATION FORM

SITE # 946

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)					(b) (4)		
Sod Installation (sq.yds.)							
6" Concrete Installation (sq. yds.)							
4" Concrete Installation (sq. yds.)							
Sand Installation (sq.yds.)							
Lower Lift Sand							
Rock, Brown (cu.yds.)							
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)							
Concrete (cu.yds.)							
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

07-0946-590

IT REPRESENTATIVE SIGNATURE

SUB 1 SIGNATURE

007404

SUB 2 SIGNATURE

007404

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9-24-98

ADDRESS: [REDACTED]

SITE #: 0946

Westbank Expy.

ACM LOCATED BENEATH:

<input checked="" type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED

APPR. CRAWL SPACE HEIGHT:

10' 1"


DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

0%

SKETCH OR COMMENTS:

NO ACM AT BARROOM

TEAM MEMBERS: J.Y. & A.T.

07-0946-540

007405

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee: [REDACTED]
Address: [REDACTED]	
Phone No.: <u>see below</u>	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>father has address</u> <u>daughter has power of attorney</u> <u>Tuesday 5 PM - 5:30 PM</u> <u>(home)</u> [REDACTED] <u>different address</u>	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other <u>none</u> resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? <u>see note</u>

Site Sketch:



Estimated Volume of ACM: _____	
Comments: <u>ACM in servitude, material dug up by City of Grapna contractors working on storm sewers. Work stopped upon discovery</u>	
Date/Time of Interview: <u>12/16/16</u>	Access Granted (circle) <u>yes</u> no
Team Members: <u>Greg Day, Kim Rhodes</u>	<u>05-0947-510</u>

007406

7/947

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]
Property's Address: [REDACTED]
State/Zip: LA 90053 Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

12/16/96
DATE

[REDACTED]
SIGNATURE

*Note - daughter [REDACTED]
has power of attorney*

05-0947-520

007407

WESTBANK ACM REMOVAL PROJECT
SAMPLE ANALYSIS CONFIRMATION
USEPA START TEAM

FYI:

SITE# 947

ADDRESS: [REDACTED]

Gretna, La. 70053

THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON N/A.


BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: N/A _____

B. FURTHER ACTION NECESSARY: geo-liner needed (see below) _____

Note: This servitude was removed only the width of the driveway per EPA J. Martin.



(1): 6' concrete put in by city of Gretna; results are for confirmation only.

AUTHORIZED EPA/START REPRESENTATIVE

Barbara A. Storey

05-0947-560

007408

Westmont, NJ Princeton, NJ Carlo Place, NY Manhattan, NY Seattle, WA Ann Arbor, MI San Mateo, CA Baytown, TX Greensboro, NC Houston, TX
 800-523-4828 800-961-0538 516-667-7251 212-220-0052 206-233-0907 313-963-0910 415-670-6401 409-323-0200 910-297-1687 713-686-3635



Ecology & Environment, Inc.
 11550 Newcastle Ave. #250
 Baton Rouge, LA 70816

Friday, December 20, 1996


Ref Number: TX963314

POLARIZED LIGHT MICROSCOPY (PLM)

Project: 020601 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS % NONFIBROUS
WBS947G01		Tan Non-Fibrous Homogeneous	Teased	2%	Chrysotile < 1% Crocidolite		98% Other
WBS476G01		Tan Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "N of Layers" refers to number of separable subsamples.


 Carlos D. Salinas
 Analyst

Approved
 Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus neg. guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the item only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

05-0947-570

007409

**WESTBANK ASBESTOS ABATEMENT
NEW ORLEANS, LOUISIANA**

RESTORATION FORM

SITE # 947

	RATE				TOTAL QTY.
Driveway Reconst. (sq.yds.)	(b)	(4)			
Walkway Reconst. (sq.yds.)	(b)	(4)			
Sod Installation (sq.yds.)	(b)	(4)			
Topsoil Backfill (cu.yds.)	(b)	(4)			
Sand Backfill (cu.yds.)	(b)	(4)			
Backfill Installation (sq.yds.)	(b)	(4)			
Backfill Lower Lift #1 (sq.yds.)	(b)	(4)			
Backfill Lower Lift #2 (sq.yds.)	(b)	(4)			
Backfill Lower Lift #3 (sq.yds.)	(b)	(4)			
Backfill Lower Lift #4 (sq.yds.)	(b)	(4)			
Plastic Edging (lft.)	(b)	(4)			
Limestone (cu.yds.)	(b)	(4)			
Concrete 6" (sq.yds.)	(b)	(4)			
Concrete 4" (sq.yds.)	(b)	(4)			

Site Sketch on Back of Page

COMMENTS: Restoration Done By City of GRENA

IT REPRESENTATIVE SIGNATURE _____

NOLA REPRESENTATIVE SIGNATURE _____

05-0947-590

007410

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 8/6/98
SITE #: 947

ADDRESS: [REDACTED]
GRETN, LA

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED

APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

TEAM MEMBERS:

[Signature]

05-0947-540

007411

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 8-26-98

ADDRESS: [REDACTED]

SITE #: 847

Marrero

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED

APPR. CRAWL SPACE HEIGHT:


18"

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	<u>NO VIS SATM</u>

TEAM MEMBERS:

RL/ASB

05-0947-540

007412

947:
Servitude:
filed by City
of Gretna
(B)

FIELD DATA SHEET 1


Site Information:

Occupant: Kevin D. [redacted]	Interviewee:
Address: [redacted] Chetna La	
Phone No.:	
Owner Name, Address, and Phone No. if Different Than Occupant: [redacted] Chetna LA 7053 [redacted]	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other <u>none</u> resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; <u>no</u> ; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____

Comments: ACM in sidewalk. material dug up by City of Chetna contractors working on storm sewers. Worker stopped upon discovery 12/19/96 - nobody home KT/K

Date/Time of Interview: 12/16/96 Greg Day

Access Granted (circle): yes; no

Team Members:

05-0948-510

No removal necessary 10-20-97

007414

Owner

948

110
[REDACTED], Giretna

Owner Name:

Current Location/Phone/Fax:

Status: Note any milestones (received access, keys, etc.) or follow-up actions to take place.

007415

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 8-6-98

ADDRESS: [REDACTED]

SITE #: 948

GREYNA, LA.

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	<u>NO VISABLE ACM</u>

TEAM MEMBERS:

[Signature]

05-0948-540

607416

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee:
Address: [REDACTED] <u>Marrero, LA 70072</u>	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant:	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; <u>gate</u> ; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; <u>don't know</u> If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____

Comments: ACM UNDER SHED - EXTENDS ~ 1 FOOT OUT FROM BASE + WALLS -
SHED FLOOR - POURED CONCRETE. Owner wants soil replaced
around shed

Date/Time of Interview: 2/12/97 0904Access Granted (circle): (yes) noTeam Members: CMA/KR

07-0949-510

007417

#1949

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: _____
Property's Address: _____ **MARRERO** _____
State/Zip: _____ Phone Number(s): _____

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.



This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

2/12/97
DATE

[Signature]
SIGNATURE

07-0949-520

007418

4/8/97
1500/1520[REDACTED]
Morrero LA
[REDACTED]

(b) (6)

Note
shed was built on
concrete slab placed
on top of AZM slab

① SALM 2-3" thick

Restoration:

① sod/soil - approved by [REDACTED]

at 1427 hrs on 4/10/97 via phone

07-0949-530

7/10/97

WESTBANK ACM REMOVAL PROJECT
SAMPLE ANALYSIS CONFIRMATION
USEPA START TEAM

FYI:

SITE# 949

ADDRESS: [REDACTED]
Marrero

THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON _____.

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:


GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ☒

B. FURTHER ACTION NECESSARY: ☐

• visible ACM highlighted below: (Z1) and (Z2)
• geolined 05-06-97

Grid	Sample ID	Depth	Backfill/Area
①	WBS949601	12"	sd, soil/yard



AUTHORIZED EPA/START REPRESENTATIVE

07120

Manuel Roane

Westmont, NJ 908-255-4800 Pleasantway, NJ 908-261-0500 Carlo Plaza, NY 619-907-7251 Manhattan, NY 212-235-0853 Seattle, WA 206-235-9007 Ann Arbor, MI 313-965-0810 San Mateo, CA 415-578-5451 Smyrna, GA 404-323-0806 Greensboro, NC 919-277-1457 Houston, TX 713-486-3635

EMSL

Ecology & Environment, Inc.
11550 Newcastle Ave. #250
Baton Rouge, LA 70816

Thursday, May 08, 1997

Ref Number: TX971658

POLARIZED LIGHT MICROSCOPY (PLM)

Project: 020601RAG1 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	NONFIBROUS
WBS940G01	MA	Tan Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other
WBS940G02	MA	Tan Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.


Carlos D. Salinas
Analyst

Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus we will not guarantee Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product on nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.


07-0949-570



INTERNATIONAL
TECHNOLOGY
CORPORATION



By DM Date 5-7-97 Subject Restoration site # 949 Sheet No. of
Chkd. By Date Proj. No.



07-0949-590

007.122

WESTBANK ASBESTOS ABATEMENT NEW ORLEANS, LOUISIANA

RESTORATION FORM

SITE # 949

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)							
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)					(b) (4)		
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

07-0949-590

IT REPRESENTATIVE SIGNATURE _____

SUB 1 SIGNATURE _____

SUB 2 SIGNATURE _____

007423

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE:

8/19/08
949

ADDRESS:

[REDACTED]
Maricord

SITE #:

ACM LOCATED BENEATH:

HOUSE
SHED

APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

CHUNKS
POWDER
SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

<i>No ACM</i>	

TEAM MEMBERS:

MTL / ASB

07-0949-540

007424

1-7-97 site visited without this FDS,
but with duplicate

Tracking Number 950

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee: <u>Orinth Davis</u>
Address: [REDACTED]	<u>Marrero LA 70072</u>
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>Same</u>	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other <u>fencing</u> resolution: _____
3) Underground utilities installed by owner? (circle): no; <u>water</u> ; <u>gas</u> ; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): <u>yes</u> ; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: <u>70 ft³</u>	
Comments: <u>ACM ~ 6"-8" below ground surface. Extension of ACM from site 318 soil prod</u>	
Date/Time of Interview: <u>12/17/96</u>	Access Granted (circle): <u>yes</u> no
Team Members: <u>GD / AR</u>	

Owner called LDEQ and wants property ~~not~~ investigated (12/16/96) KR

007425

07-0950-510

950

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]

Property's Address: [REDACTED] *Marino Rd.*

State/Zip: *70072*

Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

12-19-1996

DATE

[REDACTED]
SIGNATURE

07-0950-520

007426

TRACKING #


950

SITE SKETCH

ADDRESS: [REDACTED]

MARKER

UPDATED: 06/28/97



NOTES:

N (ITS)

1

#	COVER	THICKNESS
①	GRASS 5"	ACM 1"
②	GRASS 6"	NO ACM
③	CONCRETE	NO ACM

RESTORATION: A: SOD/SAND (~15x4)

B:

C:

ARRIVAL: 1510

DEPARTURE: 1546

RESTORATION APPROVED BY: [REDACTED]

DATE: 6/21/97

TEAM: MIV/ID/SB

DATE: 6/21/97

YOT 6/21

007427

07-0950-530

WESTBANK ACM REMOVAL PROJECT

SAMPLE ANALYSIS CONFIRMATION

USEPA START TEAM

FYI:

SITE# 950

ADDRESS: [REDACTED]
Marietta, LA

THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON 7/16/97 (AR)


BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

	GRID #:	1	2	3	4	5	6	7	8
A. PROCEED WITH RESTORATION:		<input checked="" type="checkbox"/>							
B. FURTHER ACTION NECESSARY:									

Visible ACM after excavation highlighted below by: (I) and (II)

Geotimed 07.10.97

N.T.S.
 07.11.97
 AR.



07-0950-560

AUTHORIZED EPA/START REPRESENTATIVE

Thurman 7/16/97
 007428

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
Indianapolis, Indiana 46250
Phone (317) 570-5892 Fax (317) 570-5894

Attn.: Larry Roedl
Ecology & Environmental
11550 New Castle Avenue
Baton Rouge, LA 70816

Monday, July 14, 1997

Ref Number: IN97461

EMSL**POLARIZED LIGHT MICROSCOPY (PLM)**

Performed by EPA 600/R-93/116 Method*

Project: 020601 RAG1 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS NONFIBROUS
WBS950G01		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile Crocidolite		80% Quartz 20% Other
WBS393G01		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile Crocidolite		80% Quartz 20% Other
WBS258G01		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile		80% Quartz 20% Other
WBS258G02		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile Crocidolite		80% Quartz 20% Other
WBS716G01		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile Crocidolite		80% Quartz 20% Other
WBS716G02		Brown Non-Fibrous Homogeneous	Crushed	< 1%	Chrysotile Crocidolite		80% Quartz 20% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "% of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

Margaret S. Phillips
Margaret Phillips
Analyst

[Signature]
Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negs be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the PLM. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim compliance with any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200188-0).


07-0950-570

00 7429



INTERNATIONAL
TECHNOLOGY
CORPORATION

By PM Date 7-11-97 Subject RESTORATION SITE # 950 Sheet No. _____ of _____
Chkd. By _____ Date _____ Proj. No. _____



07-0950-590

007430

**WESTBANK ASBESTOS ABATEMENT
NEW ORLEANS, LOUISIANA**

RESTORATION FORM

SITE # 950

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)							
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)							
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

07-0950-590

IT REPRESENTATIVE SIGNATURE _____

SUB 1 SIGNATURE _____

SUB 2 SIGNATURE _____

007431

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 8-26-98

ADDRESS: [REDACTED]

SITE #: 950

Marrero

ACM LOCATED BENEATH:

☐ HOUSE
☐ SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

☐ CHUNKS
☐ POWDER
☐ SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	<u>no vis ACM</u>

TEAM MEMBERS:

PL/ASB

07-0950-540

007432

Tracking Number 951

FIELD DATA SHEET 1

Revised 7/9/97
NO ACM


Site Information:

Occupant: <u>City of Westwego</u>	Interviewee:
Address: [REDACTED] ([REDACTED])	
Phone No.: <u>347-5745</u>	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED]	

Site Description:

1) Description of property (circle): single home; duplex; business; school; daycare; church; vacant house; <u>vacant lot</u> ; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other <u>none</u> resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____

Comments:

Date/Time of Interview: 12/19/96 1125Access Granted (circle): yes noTeam Members: mg / BS

09-0951-510

007434

951

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]

Property's Address: [REDACTED]

State/Zip: W. Virginia

Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

Dec. 19, 1996

DATE

[REDACTED]
SIGNATURE

09-0951-520

007435


Westwego

TRACKING # 951


SITE SKETCH

ADDRESS: [REDACTED]

UPDATED: 1 1



NOTES:



No ACM

RESTORATION: A:
B:
C:

ARRIVAL: 700
DEPARTURE: 730

TEAM: TT/BAS

RESTORATION APPROVED BY: N/A

DATE: 7/16/97
007436

DATE: 1 1

#	COVER	THICKNESS
1	limestone 6'	

09-0951-530

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 8/12/98
SITE #: 951

ADDRESS: [REDACTED]
WESTBANK

ACM LOCATED BENEATH:

	HOUSE
	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

	CHUNKS
	POWDER
	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	_____

TEAM MEMBERS: JW/KJ

09-0951-540

007437

REVISED VERSION

Tracking Number 952

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee: [REDACTED]
Address: [REDACTED] Gretna, LA 70053	
Phone No.: [REDACTED] Business	
Owner Name, Address, and Phone No. if Different Than Occupant:	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): <u>locked gate</u> ; gate; <u>dogs</u> ; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; <u>don't know</u> If yes, note on site sketch. How deep? _____

Site Sketch:



Note: owner will be buying brick there, please ask her what she would like for fill at time of removal

Estimated Volume of ACM: <u>200 ft³</u>	
Comments: Talked to [REDACTED] uncle (1/8/97) she is not home today, but can be reached next door (827) at Day Care after 3pm. This is where she works.	
Date/Time of Interview: <u>1/8/97 1020</u>	Access Granted (circle): <u>yes</u> ; no
Team Members: <u>LT/RW</u>	05-0952-510

007438

REVISED

Tracking Number 952

FIELD DATA SHEET 1


Site Information:

Occupant:	Interviewee:
Address: <u>[REDACTED] GRETNA LA</u>	
Phone No.: <u>[REDACTED]</u>	
Owner Name, Address, and Phone No. if Different Than Occupant:	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; <u>no</u> ; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____

Comments: ACM ~ 1x12' in servitude, ACM thick.

Date/Time of Interview: _____

Access Granted (circle): yes; no

Team Members: GD/KJ

05-0952-510

007439

#952

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]
Property's Address: [REDACTED] GRETNA
State/Zip: LA Phone Number(s): [REDACTED]
Work: [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.


I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.


1-8-97
DATE

[REDACTED]
SIGNATURE

05-0952-520



NOTES:



NOTE: 200 FT² OF CONCRETE WILL BE PLACED IN FRONT OF STAIRS #1 TOWARD BACK FENCE

RESTORATION: A: sand

B: 200 FT² CONCRETE

C: sod & soil

ARRIVAL: 0940

DEPARTURE: 1015

RESTORATION APPROVED BY: [Redacted]

DATE: 6/3/97

TEAM: ALL/DY/MP

Jm
6/4/97

DATE: 007441 1997

#	COVER	THICKNESS
①	3" grass + soil	+2" ACM
②	2" grass + soil	+2" ACM
③	+6" grass + soil	—

05-0952-530

007442

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
Indianapolis, Indiana 46250
Phone (317) 570-5892 Fax (317) 570-5894

Attn.: Larry Roedl
Ecology & Environmental
11550 New Castle Avenue
Baton Rouge, LA 70816

Thursday, July 10, 1997

Ref Number: IN97441

EMSL**POLARIZED LIGHT MICROSCOPY (PLM)**


Performed by EPA 600/R-93/116 Method*

Project: 020601 RAG1 WESTBANK ASBESTOS


SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
WBS982G01	WVORSTER, GR	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			80% Quartz 20% Other
WBS982G02	WVORSTER, GR	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile			60% Quartz 40% Other
WBS212G01		Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			80% Quartz 20% Other
WBS212G02		Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			60% Quartz 40% Other
WBS561G01		Brown Non-Fibrous Homogeneous	Crushed	2% Chrysotile			60% Quartz 38% Other
WBS561G02		Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile			80% Quartz 20% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "W of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method



Jane Wasilewski
Analyst



Approved
Signatory

05-0952-570

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negall be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the lta may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim produ NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one a Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200188-0).


007443



INTERNATIONAL
TECHNOLOGY
CORPORATION



By PM Date 7-8-97 Subject RESTORATION SITE # 952 Sheet No. _____ of _____
Chkd. By _____ Date _____ Proj. No. _____



05-0952-590

007444

WESTBANK ASBESTOS ABATEMENT

NEW ORLEANS, LOUISIANA

RESTORATION FORM

SITE # 952

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)							
3od Installation (sq.yds.)					(b) (4)		
3" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)					(b) (4)		
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS:

05-0952-590

IT REPRESENTATIVE SIGNATURE

SUB 1 SIGNATURE

SUB 2 SIGNATURE

007445

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE:

8/31/98

ADDRESS:

[REDACTED] GA

SITE #:

952

ACM LOCATED BENEATH:

☐ HOUSE
☐ SHED

APPR. CRAWL SPACE HEIGHT:


12'

DESCRIPTION OF ACM:

☐ CHUNKS
☐ POWDER
☐ SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	_____

TEAM MEMBERS:

SA/ML

05-0952-540

007446

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee: [REDACTED]
Address: [REDACTED] <u>Gratna LA 70053</u>	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>SAME</u>	

Site Description:

1) Description of property (circle): <u>single home</u> , duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other <u>NONE</u> resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): <u>yes</u> ; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:

Estimated Volume of ACM: 240 ft²Comments: Crushed linerock with border for backfill

Date/Time of Interview:

Access Granted (circle): yes noTeam Members: GD / Rst

05-0953-510

#953

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: _____
Property's Address: _____, GREYNA
State/Zip: LA Phone Number(s): _____

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.


This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

1-8-97
DATE

[Signature]
SIGNATURE

05-0953-520

007448



(b) (6)

NOTES:



#	COVER	THICKNESS
(1)	GRASS 6+	No ACM
(2)	SHELLS 1"	ACM 2+
(3)	SHELLS 6+	No ACM
(4)	GRASS/SHELLS 6+	No ACM

RESTORATION: A: CONCRETE (15 x 21) DRIVEWAY
 B: 70% ACM
 C:

05-0953-530

ARRIVAL: 1513
 DEPARTURE: 1600

RESTORATION APPROVED BY: [REDACTED]

DATE: 6/24/97

TEAM: [REDACTED]

DATE: 06/19/97

To 27 6/25

007450

EMSL Analytical, Inc.

6330 East 75th Street, Suite 152
Indianapolis, Indiana 46250
Phone (317) 570-5892 Fax (317) 570-5894

EMSL

Attn.: Barbara Storey
Ecology & Environmental
11550 New Castle Avenue
Baton Rouge, LA 70816

Wednesday, July 23, 1997

Ref Number: IN97549

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: 020601 RAGI WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	<u>ASBESTOS</u>		<u>NONASBESTOS</u>	
				%	TYPE	%	FIBROUS NONFIBROUS
WBS953G01	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			40% Quartz 60% Other
WBS516G01	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			80% Quartz 20% Other
WBS516G02	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			80% Quartz 20% Other
WBS516G03	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile < 1% Crocidolite			80% Quartz 20% Other
WBS516G04	[REDACTED]	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile			80% Quartz 20% Other
WBS818G01	WESTWOOD, MA	Brown Non-Fibrous Homogeneous	Crushed	< 1% Chrysotile			80% Quartz 20% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

Margaret Phillips
Margaret Phillips
Analyst

*Entered
@ 7/24/97
G.P.*

[Signature]
Approved
Signatory

Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negat be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the file may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim prod. NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered sample. Analysis performed by EMSL of Indianapolis (NVLAP Air and Bulk #200188-0).

05-0953-570

007451




INTERNATIONAL
TECHNOLOGY
CORPORATION



By DM Date 7-22-97 Subject Restoration site # 953 Sheet No. _____ of _____

Chkd. By _____ Date _____ Proj. No. _____



05-0953-590

007452

SITE # 953

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)							
Sod Installation (sq.yds.)							
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)					(b) (4)		
Plastic Edging (ft.)							
Walkway Rock Inst. (sq.yds.)							
Topsoll (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS:

05-0953-590

IT REPRESENTATIVE SIGNATURE

SUB 1 SIGNATURE

SUB 2 SIGNATURE

007453

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 8/28/98
SITE #: 953

ADDRESS: [REDACTED]
Gretna

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED

APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

<i>No ACM</i>	_____

TEAM MEMBERS:

MTL/PLL

05-0953-540

007454

FIELD DATA SHEET 1


Site Information:

Occupant: <u>[REDACTED]</u>	Interviewee: <u>[REDACTED]</u>
Address: <u>[REDACTED], MARRERO, LA 70072</u>	
Phone No.: <u>[REDACTED]</u>	
Owner Name, Address, and Phone No. if Different Than Occupant: <u>Same</u>	

Site Description:

1) Description of property (circle): <u>single home;</u> duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; <u>gate;</u> dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; <u>don't know</u> If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: 160 ft²

Comments: Backfill: concrete walkway to shed
soil + sod elsewhere

Date/Time of Interview: 1/15/97 1520

Access Granted (circle): yes; no

Team Members: LT/RW

07-0954-510

~~#1762~~ 11/7/97
#954

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]
Property's Address: [REDACTED] MARRERO
State/Zip: LA 70072 Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade; CONCRETE WALKWAY
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

1-17-97
DATE


[REDACTED]
SIGNATURE

07-0954-520

007456

4/8/97

Marrero LA



Notes:

① SACM walk 2" thick

② SACM walk 2" thick

Restoration

① Concrete - approved by [REDACTED] at 1351 h-i on
4/10/97 via phone - TMW

07-0954-530

007457

WESTBANK ACM REMOVAL PROJECT
SAMPLE ANALYSIS CONFIRMATION
USEPA START TEAM

FYI:

SITE# 954

ADDRESS: [REDACTED]
Marrero, LA

THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON No analytical received as of 05.10.97


BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

GRID #: 1 2 3 4 5 6 7 8

A. PROCEED WITH RESTORATION: ☒

B. FURTHER ACTION NECESSARY: ☐

• Visible ACM after excavation highlighted below by: (1)
• Geolined 05.10.97



07-0954-560

AUTHORIZED EPA/START REPRESENTATIVE 07458 [Signature]



Ecology & Environment, Inc.
11550 Newcastle Ave. #250
Baton Rouge, LA 70816

Thursday, May 15, 1997

Ref Number: TX971748

POLARIZED LIGHT MICROSCOPY (PLM)

Project: 020601RAG1 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS % NONFIBROUS
WBS954G01	[REDACTED]	Brown Non-Fibrous Homogeneous	Teased	None Detected			100% Other
WBS323G01	[REDACTED]	Brown Non-Fibrous Homogeneous	Teased	2%	Chrysotile		98% Other
WBS323G02	[REDACTED]	Brown Fibrous Homogeneous	Teased	10%	Chrysotile		90% Other
				< 1%	Crocidolite		
WBS323G03	[REDACTED]	Brown Non-Fibrous Homogeneous	Teased	5%	Chrysotile		95% Other
				< 1%	Crocidolite		
WBS323G04	[REDACTED]	Brown Fibrous Homogeneous	Teased	8%	Chrysotile		92% Other
				< 1%	Crocidolite		
WBS323G05	[REDACTED]	Brown Fibrous Homogeneous	Teased	15%	Chrysotile		85% Other
				< 1%	Crocidolite		

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "% of Layers" refers to number of separable subsamples.

Carlos D. Salinas
Analyst

Approved
Signatory

07-0954-570

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items it only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product and nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.


007459



INTERNATIONAL
TECHNOLOGY
CORPORATION



By PM Date 5-13-97 Subject RESTORATION SITE # 954 Sheet No. of
Chkd. By Date Proj. No.



07-0954-590

007460

**WESTBANK ASBESTOS ABATEMENT
NEW ORLEANS, LOUISIANA**

RESTORATION FORM

SITE # 954

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)							
Sod Installation (sq.yds.)							
6" Concrete Installation (sq. yds.)							
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)					(b) (4)		
Plastic Edging (ft.)					(b) (4)		
Walkway Rock Inst. (sq.yds.)							
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

07-0954-590

IT REPRESENTATIVE SIGNATURE _____

SUB 1 SIGNATURE _____

SUB 2 SIGNATURE _____

007461

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE:

9/23/98

ADDRESS:

[REDACTED]

SITE #:

954

marero

ACM LOCATED BENEATH:

HOUSE
SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

CHUNKS
POWDER
SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	<u>soil</u>

TEAM MEMBERS:

RL/JS

07-0954-540

007462

Tracking Number

955

No visible ACM

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee: [REDACTED]
Address: [REDACTED] DR, MARRERO, LA 70072	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED]	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; <u>gate</u> ; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; <u>no</u> ; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



(b) (6)(b) (6)

(b) (6)

(b) (6)(b) (6)

Estimated Volume of ACM: _____

Comments: No visible ACMDate/Time of Interview: 2/15/97 0800Access Granted (circle): yes; no N/ATeam Members: 2/15/97 0800

07-0955-510

007463

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 9/15/98
SITE #: 955

ADDRESS: [REDACTED]
Marrero

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED


APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

	_____

TEAM MEMBERS: KJ / TS

07-0955-540

007464

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee:
Address: [REDACTED] <u>Marrero</u>	<u>70072</u>
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED]	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; <u>gate</u> ; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): <u>yes</u> ; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: _____

Comments: * ACM under ~ 1/2" grass in middle of driveway (between driveway tracks). Owner agrees limestone backfill is OK.

Date/Time of Interview: 2/12/97 0840Access Granted (circle): yes noTeam Members: Rhodes / Nammiti07-0956-510

007465

956

CONSENT FOR ACCESS TO PROPERTY
WESTBANK ASBESTOS SITE

Property Owner's Name: [REDACTED]
Property's Address: [REDACTED] MARRERO 1209 1/2
State/Zip: LA 70072 Phone Number(s): [REDACTED]

I hereby consent to officers, employees, and parties authorized by the United States Environmental Protection Agency (EPA) entering and having continued access to my property for the following purposes:

1. The taking of such soil, water and air samples as may be determined to be necessary;
2. Other actions related to the investigation of surface or subsurface contamination;
3. The performance of a response action including, but not limited to, the following actions:
 - a. Use of mechanical equipment (e.g. small bulldozers, backhoes, or trackhoes and trucks) on the property;
 - b. Removal of asbestos-contaminated material from the property;
 - c. Replacement of removed asbestos-containing material with a like-material (i.e., clean fill, crushed limestone) and regrading of the replaced material to the property's original grade;
 - d. The replacement with locally-available vegetation of any sod, bushes, or trees whose removal was a necessary part of the removal action, and;
 - e. The taking of other actions necessary to mitigate releases or threats of releases of hazardous substances, pollutants or contaminants from the property.

I realize that these actions are undertaken pursuant to EPA's response responsibilities under the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA), 42 U.S.C. § 9601 et seq. Under those authorities, EPA can only remediate and restore contaminated property, and it legally cannot improve a property beyond removing hazardous substances located on such a property.

This written permission is given by me voluntarily with knowledge of my right to refuse and without threats or promises of any kind. By signing this access agreement I am not waiving any rights in law or in equity I may have against any person or party in connection with the response action EPA will perform.

2-12-97
DATE

[REDACTED]
SIGNATURE

07-0956-520

007466


TRACKING # 956

SITE SKETCH

ADDRESS: [REDACTED]

Marren

UPDATED: 1/1



(b) (6)

NOTES:

N (115°)



8' x 50' drive way (A)
 2' x 15' area in service (B)

RESTORATION: A: Lm in drive
 B: soil & soil

3/5/97 ARRIVAL: 1030
 DEPARTURE: 1725

TEAM: CC/SS/PH

RESTORATION APPROVED BY: [REDACTED]

DATE: 5/7/97

007467

#	COVER	THICKNESS
①	2" grass & soil	2" ALM
②	4" grass & soil	2" ALM
③	3" grass & soil	2" ALM
④	+ 6" grass & soil	-
⑤	+ 6" grass & soil	-
⑥	+ 6" grass & soil	-

07-0956-530

WESTBANK ACM REMOVAL PROJECT SAMPLE ANALYSIS CONFIRMATION USEPA START TEAM

FYI:

SITE# 956

ADDRESS: [REDACTED] Ave A
Marrero, LA


THE SAMPLE ANALYSIS RESULTS FOR THE ABOVE REFERENCED SITE WERE RECEIVED AND WERE EVALUATED BY THE USEPA START TEAM ON 5-16-97 ln.

BASED ON AN EVALUATION OF THE ANALYTICAL DATA, WE RECOMMEND THE FOLLOWING ACTION:

	GRID #:		1	2	3	5	6	7	8
A. PROCEED WITH RESTORATION:	✓	✓	✓						
B. FURTHER ACTION NECESSARY:									

- Visible ACM highlighted below: (A) and (B)
- Geolined 05-14-97

Grid	Sample ID	depth	Backfill/Area
①	WBS956G01	12"	limestone sew.
②	WBS956G02	6"	sod/sod trans.
③	WBS956G03	6"	limestone drive



AUTHORIZED EPA/START REPRESENTATIVE 007468 Laurence [Signature]

Westwood, NJ 800-333-6000	Providence, RI 800-851-0520	Carle Place, NY 616-937-7231	Manhasset, NY 212-230-0832	Seattle, WA 206-223-9037	Ann Arbor, MI 313-963-0010	San Mateo, CA 415-476-8481	Burlingame, CA 415-333-0000	Crookston, NC 815-237-1407	Beaumont, TX 713-486-3035
------------------------------	--------------------------------	---------------------------------	-------------------------------	-----------------------------	-------------------------------	-------------------------------	--------------------------------	-------------------------------	------------------------------



Ecology & Environment, Inc.
11550 Newcastle Ave. #250
Baton Rouge, LA 70816

Friday, May 16, 1997


Ref Number: TX971780

POLARIZED LIGHT MICROSCOPY (PLM)

Project: 020601RAG1 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS % NONFIBROUS
WBS956G01	[REDACTED]	Brown Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other
WBS956G02	[REDACTED] MA	Brown Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other
WBS956G03	[REDACTED] MA	Brown Non-Fibrous Homogeneous	Teased		None Detected		100% Other
WBS959G04	[REDACTED] JAMES BLVD, MA	Brown Non-Fibrous Homogeneous	Teased	2% < 1%	Chrysotile Crocidolite		98% Other
WBS267G02	[REDACTED] BLVD, MA	Brown Non-Fibrous Homogeneous	Teased	< 1%	Chrysotile		100% Other
WBS360G01	[REDACTED]	Brown Non-Fibrous Homogeneous	Teased	2%	Chrysotile		98% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "% of Layers" refers to number of separable subsamples.


Carlos D. Salinas
Analyst

Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. This negative guarantee. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items as only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product and nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature. It is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

07-0956-570

007469




INTERNATIONAL
TECHNOLOGY
CORPORATION



By PM Date 5-16-97 Subject RESTORATION SITE # 956 Sheet No. of

Chkd. By Date Proj. No.



07-0956-590

007470

WESTBANK ASBESTOS ABATEMENT NEW ORLEANS, LOUISIANA

RESTORATION FORM

SITE # 956

	DATE	DATE	DATE	DATE	EST. QTY.	ACTUAL QTY.	ACT. COMP.
Rock Installation (sq.yds.)					(b) (4)		
Sod Installation (sq.yds.)					(b) (4)		
6" Concrete Installation (sq. yds.)					(b) (4)		
4" Concrete Installation (sq. yds.)					(b) (4)		
Sand Installation (sq.yds.)					(b) (4)		
Lower Lift Sand					(b) (4)		
Rock, Brown (cu.yds.)					(b) (4)		
Rock, Gray (cu.yds.)					(b) (4)		
Sand (cu.yds.)					(b) (4)		
Concrete (cu.yds.)					(b) (4)		
Plastic Edging (ft.)					(b) (4)		
Walkway Rock Inst. (sq.yds.)					(b) (4)		
Topsoil (cu.yds.)							
EXTRA							

Site Sketch on Back of Page

COMMENTS: _____

07-0956-590

IT REPRESENTATIVE SIGNATURE _____

SUB 1 SIGNATURE _____

SUB 2 SIGNATURE _____

007471

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE: 3/18/98
SITE #: 956

ADDRESS: [REDACTED] Ave. A
Marrero

ACM LOCATED BENEATH:

<input type="checkbox"/>	HOUSE
<input type="checkbox"/>	SHED

APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

<input type="checkbox"/>	CHUNKS
<input type="checkbox"/>	POWDER
<input type="checkbox"/>	SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

<i>No ACM</i>	_____

TEAM MEMBERS:

MTL/ASB

07-0956-540

007472

1-21-97 0935

[REDACTED]
[REDACTED], Marrero
[REDACTED]

drive way on right of white house
has shotgun house +
white frame house

- can go thru fence
- "concerned, not looking for freebies"

has grass + gravel over ACM
can go to backyard if needed
- leave note on door

007473

07-0956-600

FIELD DATA SHEET 1

Site Information:

Occupant: [REDACTED]	Interviewee: [REDACTED] (son)
Address: [REDACTED], Westwego	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED]	

Site Description:

1) Description of property (circle): <u>single home</u> ; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): <u>locked gate</u> ; <u>gate</u> ; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): <u>no</u> ; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:

no visible ACM *

Estimated Volume of ACM: _____

Comments: * Notes: owner says ACM buried under shell in driveway
transit found in shell material.
no visible ACM found.Date/Time of Interview: 2/1/97 1035Access Granted (circle): yes; no N/ATeam Members: Rhodes/Whitcomb

09-0957-510

WESTBANK ASBESTOS REMOVAL PROJECT NEW ORLEANS, LA

DATE:

9/16/98

SITE #:

957

ADDRESS

[REDACTED] Ale G
Wweep

ACM LOCATED BENEATH:

HOUSE
SHED

APPR. CRAWL SPACE HEIGHT:

DESCRIPTION OF ACM:

CHUNKS
POWDER
SLAB

PERCENT OF AREA (ACM)

SKETCH OR COMMENTS:

NO ACM	

TEAM MEMBERS:

KJ/TS

09-0957-540

007475